



Commercial Vehicle Inspection Report

Decal Number: GJ84736
Decal Expiry Date: 2026-Jul-31
Inspection Number: 21417737

Inspection Result:
PASS

FACILITY: T & L TRUCK & TRAILER / S0781
INSPECTOR: BOSZAK, CURTIS SCOTT / 102847
WORK ORDER #: 2025-0511

INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual

INSP. START: 2025-Jul-08 07:30 AM PDT
INSP. COMPLETE: 2025-Jul-08 09:05 AM PDT

VEHICLE JUR: British Columbia
PLATE #: 53883K

REGI: 03203947
UNIT/FLEET#:
VIN: 2P9ST3DX78A015710

OWNER/LESSEE NAME: HIGH NOON INVESTMENT CORP, HIGH NOON INVESTMENT CORP
ADDRESS: 13538 73 AVE, 13538 73 AVE
Surrey, British Columbia
V3W2R6, Canada

LICENCED GVW(kg): 999999
VEHICLE YEAR: 2008
MAKE: MAGNUM
MODEL:

BODY STYLE: Flat Deck Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Repaired (same day) #3 axle shocks
Section 3 - Brake System	Passed 6 wheel brakes, shoes, hardware & drums
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) marker lamps, compliance tape
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	35	37	8.2	8	8	8.6	
2	Clamp	30	Automatic	35	36	11.2	11.3	13.9	13.7	
3	Clamp	30	Automatic	37	37	8.9	10.2	6.2	6.6	
Comment:				Comment:						

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	20	20	Lining (Shoe)	21	21	Drum	419.10	419.10
2	20	20	Lining (Shoe)	21	21	Drum	419.10	419.10
3	20	20	Lining (Shoe)	21	21	Drum	419.10	419.10
Comment:			Comment: NEW			Comment: NEW		

Inspection Comments:
Has this Vehicle been road tested? No
Inspector: BOSZAK, CURTIS SCOTT

Road Test Date:
Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Jul-08 09:28 AM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.