



Commercial Vehicle Inspection Report

Decal Number: GN31019
Decal Expiry Date: 2027-May-31
Inspection Number: 21772942

Inspection Result:

PASS

FACILITY: KEVIN'S HEAVY DUTY / S7132
INSPECTOR: LAFORTUNE, KEVIN JOHN / 112846
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Annual

INSP. START: 2026-May-18 10:00 AM PDT
INSP. COMPLETE: 2026-May-21 05:00 PM PDT

VEHICLE JUR: British Columbia
PLATE #: RG7743
LICENCED GVW(kg): 17200
VEHICLE YEAR: 2012
MAKE: FREIGHTLIN
MODEL:

REGI: 10302869
UNIT/FLEET#:
BODY STYLE: Truck Tractor
ODOMETER: 457711 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 1FUBC5DV6CDBJ8288
OWNER/LESSEE NAME: LITTLEFIELD FARM, LTD
ADDRESS: 1320 FAIRFIELD RD
Cobble Hill, British Columbia
V8H0H7, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Repaired (same day) REPLACED HC METERING MODULE
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Repaired (same day) REPLACE AIR COMPRESSOR DISCHARGE LINE
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) REPLACE LH REAR MUDFLAP AND 1/4 FENDER
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)					Tire Tread Depth (mm)					
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	20	Automatic	34.9	34.9	13.5			14.3	✓
2	Clamp	30L	Automatic	38.1	38.1	14.3	21.4	13.5	15.1	
Comment:					Comment:					

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)				
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right	
1	65	65	Lining (Shoe)	16	16	Drum			
2	40	40	Lining (Shoe)	19	19	Drum			
Comment:			Comment:		Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.				

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: LAFORTUNE, KEVIN JOHN

Road Test Date: 2026-05-21
Signature: [Signature] Road Tester:

This Inspection Report was submitted to CVSE on 2026-May-21 05:32 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

5/21/2026 5:32:29 PM PDT