

03891111

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

Vehicle Standards and Inspection
Box 45024, Regent Plaza, Suite 100
Winnipeg, MB, R2C 9C7
1-800-665-0820Manitoba
A869021

Date Inspection Started DAY 10 MO. 08 YR. 24	Station Number C1014317	Station Name Kindersley Transport Ltd.	City Winnipeg
Date Inspection Completed DAY 14 MO. 08 YR. 24	Mechanic Number M1401717	Mechanic Signature <i>[Signature]</i>	Station Phone Number 204-697-0189
Inspection Expiry Date DAY 31 MO. 08 YR. 25	Vehicle Owner Kindersley Transport		
Address P.O. Box 7270, St. John's, Saskatchewan SK		City St. John's	Province SK
Postal Code S7K4J2		Phone	
Licence Number 2916LIZM		Prov. SK	NBC # C010105
Vehicle Identification Number 31AK314LDR7MSM199516		Make F/L	Model Issued
Year 2022		Unit # 401240	

☒ Pass/Safe Vehicle
☒ Fail/Unsafe Vehicle
☐ Fail/Hazardous

☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

 Truck ☒ KGS ☒ Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark 'X' under 'R' when item Rejected 'XX' under 'R' when item Hazardous 'X' under 'P' when item Corrected or No Defects found in Section																																																																							
X		Section 1 - Power Train: Defects (if any)																																																																							
X		Section 2 Suspension: Defects (if any)																																																																							
X	X	Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type X14, B LF Brake block not spring broken X13, A fluid leaks corroded.																																																																							
		Brake Inspection Type: A B C D E Circle appropriate letter for Internal Brake Component Inspection <table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>3/4</td> <td>3/4</td> <td>16.543</td> <td>16.544</td> <td>1 1/2</td> <td>1 1/2</td> </tr> <tr> <td>2</td> <td>3/4</td> <td>3/4</td> <td>16.540</td> <td>16.540</td> <td>1 1/2</td> <td>1 1/2</td> </tr> <tr> <td>3</td> <td>3/4</td> <td>3/4</td> <td>16.542</td> <td>16.543</td> <td>1 1/2</td> <td>1 1/2</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table> Final Measurement	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	3/4	3/4	16.543	16.544	1 1/2	1 1/2	2	3/4	3/4	16.540	16.540	1 1/2	1 1/2	3	3/4	3/4	16.542	16.543	1 1/2	1 1/2	4							5																													
Axle	Lining			Drum/Rotor		Stroke																																																																			
	L	R	L	R	L	R																																																																			
1	3/4	3/4	16.543	16.544	1 1/2	1 1/2																																																																			
2	3/4	3/4	16.540	16.540	1 1/2	1 1/2																																																																			
3	3/4	3/4	16.542	16.543	1 1/2	1 1/2																																																																			
4																																																																									
5																																																																									
X		Section 4 - Steering: Defects (if any)																																																																							
X	X	Section 5 - Instruments & Auxiliary Equipment: Defects (if any) X5B wiper blades worn.																																																																							
X		Section 6 - Lamps: Defects (if any)																																																																							
X		Section 7 - Electrical System: Defects (if any)																																																																							
X		Section 8 - Body: Defects (if any)																																																																							
X		Section 9 - Tire & Wheel: Defects (if any)																																																																							
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th></th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>6</td> <td>6</td> <td>14</td> <td>18</td> <td>100</td> <td>100</td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>7</td> <td>6</td> <td>3</td> <td>7</td> <td>26</td> <td>26</td> <td>26</td> <td>26</td> </tr> <tr> <td>3</td> <td>8</td> <td>5</td> <td>3</td> <td>9</td> <td>26</td> <td>26</td> <td>26</td> <td>26</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected			L	R	L	R	L	R	L	R	1	6	6	14	18	100	100			2	7	6	3	7	26	26	26	26	3	8	5	3	9	26	26	26	26	4									5								
Axle	Tread Depth				Air Pressure																																																																				
	Initial		Corrected		Initial		Corrected																																																																		
	L	R	L	R	L	R	L	R																																																																	
1	6	6	14	18	100	100																																																																			
2	7	6	3	7	26	26	26	26																																																																	
3	8	5	3	9	26	26	26	26																																																																	
4																																																																									
5																																																																									
X		Section 10 - Coupling Devices: Defects (if any)																																																																							

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by:

Signature

Date:

FV50022-01-(R-09/15)

COPY IN CAB - PLEASE ENSURE CERTIFICATE IS SIGNED - NOT FOR DESTRUCTION

Ce document peut être obtenu en français sur demande