

Commercial Vehicle
Inspection ReportDecal Number: GH37617
Decal Expiry Date: 2026-Feb-28
Inspection Number: 212398325185
Inspection Result:
PASS

FACILITY: TRUE NORTH FLEET MAINTENANCE / S20394
INSPECTOR: Barrett, Daniel David / 203233
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual

INSP. START: 2025-Feb-17 10:04 AM PST
INSP. COMPLETE: 2025-Feb-17 12:04 PM PST

VEHICLE JUR: Alberta
PLATE #:
LICENCED GVW(kg): 0
VEHICLE YEAR: 2014
MAKE: VANGUARD
MODEL: DRY VAN

REGI:
UNIT/FLEET#: 053-9307
BODY STYLE: Trailer
ODOMETER:
HUB ODOMETER: 194134 KM
BRAKE TYPE: Air
FUEL TYPE: Not Applicable

VIN: 5V8VC5325EM402200
OWNER/LESSEE NAME: TRANSFORCE ADMINISTRATION INC, TRANSFORCE
ADDRESS: 2340405 WRANGLER RD SE, 2340405 WRANGLER RD SE
ROCKYVIEW, Alberta
T1X0K2, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Repaired (same day) REPLACE LEAKING LEVELING VALVE
Section 3 - Brake System	Repaired (same day) REPLACE #1AXLE DRUM AND SHOES BOTH SIDES
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) REPAIR CRACKS IN ROLL UP DOOR FRAME
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	38	38	12	11	8	4	
2	Clamp	30	Automatic	38	38	13	12	11	15	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right	Brake Lining/Pad (mm)	Left	Right	Rotor Thickness or Drum Inside Diameter (mm)	Left	Right
1	80	80	Lining/Pad	12	12	Rotor/Drum		
2			Lining (Shoe)	19	18	Drum		
			Lining (Shoe)			Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: Barrett, Daniel David

Road Test Date:
Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Feb-17 12:05 PM PST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VP at the Commercial Vehicle Safety Enforcement.

CVSE0014

1/17/2025 12:15:04 PM PST