

Experian AutoCheck Report

Report run: 02/13/2026 13:02:25 EST

2016 Honda Fit EX Hatchback 4D (1.5L I4 DI Gasoline)

VIN:	JHMGK5H70GX038576
Class:	Car - Subcompact
Country of Assembly:	Japan
Vehicle Age:	10 year(s)
Last Reported Odometer:	99,208 (01/26/2026)

Owners - 3



Vehicle Usage
Fleet, Lease



AutoCheck Score

Similar vehicles usually range between **69 and 85**

Vehicle History at a Glance



State Title Brand



Auction Brand / Issues

Odometer Problem, Structural Damage



Accident / Damage

Structural Damage



CLEAN



AUCTION ISSUE REPORTED



SEVERE



Open Recall Check



Insurance Loss / Transfer



Odometer Check

Last reported odometer:
99,208 (01/26/2026)



2 OPEN RECALL(S)



NO ISSUE



ODOMETER ISSUE REPORTED



Certified Pre-Owned



Service / Repair

1 Service Record(s) Reported



Additional History

Lien Reported, Inspection Performed



NO CPO INFO AVAILABLE



NO ISSUE



EVENTS REPORTED




This vehicle is eligible for Buyback Protection

Due to the vehicle's history showing no reported major state title brands. [Terms & Conditions](#)

[Learn More](#)



Accident & Damage



Damage Date	Damage Type	Severity
08/29/2018	Collision	Unknown
09/26/2019	Structural Damage	Severe
01/29/2026	Structural Damage	Severe

Accident or damage event(s) have been reported for this vehicle to Experian AutoCheck. An inspection may provide added confidence in the vehicle's condition before purchase.

🔍 Inspection History Check



Information Reported

Below are inspection(s) that were reported for this vehicle. Please note that not all inspections are reported to Experian AutoCheck.

Inspection Date - 10/01/2019

Location - ORLANDO, FL

Odometer Reading - 5,995

Data Source - TrueFrame Certified Inspection

Details - Trueframe Inspection Performed

[View the complete report](#)

⟳ Open Recall Check



Information Reported: AutoCheck found 2 open recall(s).

It is recommended that this vehicle be taken to the nearest dealer to have the recalled components replaced or fixed. Service bulletins if available are not part of open recalls and can be found in the vehicle history details.

Recall Date - 12/09/2020

Recall Type - Unspecified

NHTSA / OEM Recall No. - N/A / V90

Campaign Description - 2015-17 FIT START/STOP SWITCH WARRANTY EXTENSION

Status: Remedy Unknown

Recall Date - 02/18/2022

Recall Type - Unspecified

NHTSA / OEM Recall No. - N/A / XC6

Campaign Description - 2015-16 FIT FUEL INJECTOR WARRANTY EXTENSION

Status: Remedy Available

[More information](#) including remedy or risk factors. Locate your nearest authorized [Honda Dealer](#) to schedule repair.



Odometer Check



Problem Reported

One or more odometer problems have been reported to AutoCheck by the state Division of Motor Vehicles (DMV) or auction sources OR there is a potential odometer discrepancy when AutoCheck examined the sequence of reported odometer readings.



State Title Odometer Check

No issues reported



Auction Odometer Check

The following odometer brand(s) has been announced by an auction:

Odometer Issue



Odometer Calculation Check

No issues reported

Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order.

Vehicle: 2016 Honda Fit EX (JHMGK5H70GX038576) Report Run Date: 02/13/2026 13:02:25 EST

2016

Owner 1

Location: NY

Owned From: 08/2016

Usage: Fleet, Lease

Event Date	Location	Odometer	Data Source	Details
08/16/2016	BROOKLYN, NY		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
09/07/2016	NY	16	Motor Vehicle Dept.	Title(Leased Vehicle)
08/16/2018	BROOKLYN, NY		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
08/29/2018	KINGS COUNTY, NY		State Agency	Collision with Another Vehicle(Case #:37459432)
09/07/2018	BROOKLYN, NY		Damage Report	Accident or Damage Reported Vehicle Damage Reported Left Side Damage or Repair Reported Right Side Damage or Repair Reported Front Damage or Repair Reported Damage or Repair to Bumper Reported Damage or Repair to Radiator Reported Damage or Repair to Fender Reported
06/11/2019	BROOKLYN, NY	5,368	Bay Ridge Honda 718.836.4600	Multiple Point Vehicle Inspection Electrical System Serviced
09/12/2019	EASTERN REGION	5,987	Auto Auction	Reported at Auto Auction
09/16/2019	EASTERN REGION	5,987	Auto Auction	Auction Announced as Fleet/Lease(COLOR REPORTED AS BLUE)
09/26/2019	EASTERN REGION		Auto Auction	Auction Announced as Structural Damage
10/01/2019	ORLANDO, FL	5,995	TrueFrame Certified Inspection	Trueframe Inspection Performed View the complete report

2019

Owner 2

Location: FL

Owned From: 11/2019

Usage: Personal

Event Date	Location	Odometer	Data Source	Details
11/24/2019	WEST PALM BEACH, FL		Dealer Record	Vehicle in Dealer Inventory
11/24/2019	ORLANDO, FL	6,026	Motor Vehicle Dept.	Title(Title #:0136873413) (Lien Reported)
11/24/2019	ORLANDO, FL		Motor Vehicle Dept.	Registration Event/Renewal
12/11/2019	ORLANDO, FL		Motor Vehicle Dept.	Title(Title #:0136873413) (Lien Reported)

Event Date	Location	Odometer	Data Source	Details
06/17/2020	ORLANDO, FL		Motor Vehicle Dept.	Registration Event/Renewal
12/09/2020			Manufacturer	Manufacturer Recall Mfr. Recall V90 2015-17 FIT START/STOP SWITCH WARRANTY EXTENSION LOCATE YOUR NEAREST AUTHORIZED HONDA DEALER TO SCHEDULE REPAIR. Status: Remedy Unknown
02/18/2022			Manufacturer	Manufacturer Recall Mfr. Recall XC6 2015-16 FIT FUEL INJECTOR WARRANTY EXTENSION LOCATE YOUR NEAREST AUTHORIZED HONDA DEALER TO SCHEDULE REPAIR. Status: Remedy Available

2022

Owner 3

Location: FL

Owned From: 05/2022

Usage: Personal

Event Date	Location	Odometer	Data Source	Details
05/20/2022	OCOEE, FL		Motor Vehicle Dept.	Registration Event/Renewal
07/02/2024	OCOEE, FL		Motor Vehicle Dept.	Registration Event/Renewal
01/26/2026	FL	99,208	Auto Auction	Reported at Auto Auction
01/29/2026	FL		Auto Auction	Auction Announced as Structural Damage Auction Announced as Broken Odometer
01/30/2026	FL		Auto Auction	Auction Announced as Structural Damage

AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to [AutoCheck Terms and Conditions](#). If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

Buyback Protection Terms and Conditions

This vehicle (JHMGK5H70GX038576) qualifies for [AutoCheck Buyback Protection](#). If you obtained the report from a dealer, the dealer has been provided with the terms and can share them with you. These Buyback Protection Terms and Conditions are also available to you at any time at www.autocheck.com/bbptersms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.