04104278

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

Vehicle Safety
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba
C119957

	DAY	MO.	YR.
Date Inspection Started	28	04	26
Date Inspection Completed	21	10	26
Inspection Expiry Date	31	10	27

Station Number: A0119 — Station Name: ELIAS TRUCK SERVICE WPG — City

Mechanic Number: M77169 — Mechanic Signature — Station Phone Number: 2047752271

Vehicle Owner: BUHLER VERSATILE INC.

Address — City — Province — Postal Code — Phone

- [X] Pass/Safe Vehicle
- [X] Fail/Unsafe Vehicle
- [ ] Fail/Hazardous

Licence Number: CEP1A93 — Prov.: MB — NSC #: MB00084272 — Odometer Reading: 395612 — Odom. Type: [X] km [ ] mi

Vehicle Identification Number: 2NPBJTJX6FM276326 — Make: PB — Model: — Year: 2015 — Unit #:

[ ] Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

X Truck — GVWR: 24716A KGS — ___Truck Tractor ___Trailer ___Semi-Trailer ___Bus ___School Bus ___Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	
X		**Section 1 - Power Train:** Defects (if any)
X		**Section 2 Suspension:** Defects (if any)
X	X	
		Section 3 - Brake Systems: 3H (3A) — Brake Inspection Type: A B (C) D E — Circle appropriate Letter for Internal Brake Component Inspection
		Defects (if any) — Circle Brake Type
		3A.2.G) FAN HUB LEAKING AIR
		3A.14.B) #3 AXLE R/S BRAKE POT BROKEN
X		SPRING

	Lining In		Drum/Rotor		Stroke In	
Axle	L	R	L	R	L	R
1	5/8	5/16			1 1/4	1 1/4
2	2/16	3/4			1 1/4	1 1/4
3	11/16	9/16			1 1/4	1 1/4
4						
5						
	Final Measurement					

		Section 4 - Steering: Defects (if any)
X	X	
		Section 5 - Instruments & Auxiliary Equipment: Defects (if any) 5.3.B) L/S & R/S WIPER BLADES STREAK
		5.3.D) WASHERS NOT WORKING 5.8.A) BLOWER MOTOR SPEED KNOB BROKEN
X	X	**Section 6 - Lamps:** Defects (if any) 6.1.C) LICENSE LIGHT OUT. 6.1.I) L/S REAR CLEARANCE LIGHT
		INTERMITTENT. 6.1.C) L/S TAIL LIGHT OUT.
X		**Section 7 - Electrical System:** Defects (if any)
X	X	**Section 8 - Body:** Defects (if any) 8.21.A) R/S FRONT MUDFLAP / FENDER MOUNT BRACKET
		BROKEN
X		**Section 9 - Tire & Wheel:** Defects (if any)

	Tread Depth mm								Air Pressure PSI							
	Initial				Corrected				Initial				Corrected			
Axle	L		R		L		R		L		R		L		R	
1		11	12							100	100					
2	13	13	8	8					100	100	100	100				
3	5	5	5	5					100	100	100	100				
4																
5																

		Section 10 - Coupling Devices: Defects (if any)

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: Wheels pulled on invoice #72165 (MAY 25/2026)