

0944

[illegible]

ALL ESTIMATES ARE FOR LABOUR ONLY...MATERIALS ADDITIONAL.
THIS COMPANY DOES NOT ASSUME ANY RESPONSIBILITY WHATEVER FOR
VEHICLES OR EQUIPMENT LEFT FOR REPAIRS, STORAGE OR OTHER
PURPOSES, OR FOR ARTICLES LEFT IN SAME VEHICLES DRIVEN BY OUR
EMPLOYEES AT OWNER'S RISK.

TOTAL MATERIAL

PRESTIGE

OUT

P.O. NO.

MAKE <i>Kenworth</i>		YEAR <i>2015</i>		MODEL <i>T800</i>		SERIAL NUMBER <i>976216</i>	
MOTOR NUMBER			TRANS. NUMBER			LICENSE	
CASH	CHARGE	D.P.	WARRANTY	DEPOSIT	SERVICE SALES		
☐	☐	☐	☐	\$			

☐ **CHECK ALL WHEEL TORQUES AFTER 50 KM'S**

WORK DESCRIPTION

- 7 Check out Transmission Found broken pieces with drainings!
- 7 Remove Transmission
- 7 Clean up bell housing
- 7 Install new cross shafts and cross shaft bushings
- 7 Install Regrinded Flywheel
- 7 New clutch brake and New Clutch
- 7 Install New Transmission

SERVICEMAN	HOURS	MEN	RATE
	9.6	1	120

INVOICE DUE IN 30 DAYS!

INSPECTION CHARGE
(\$175.00 per Unit)

TOTAL		
LABOUR	1152	00

SHOP SUPPLIES	34	5
------------------	----	---

TOTAL PARTS	6774	7
-------------	------	---

TRAVEL

SUB TOTAL	7.961	3
-----------	-------	---

GST	398	0%
-----	-----	----

TOTAL	8,359.3
-------	---------

PAY THIS AMOUNT-

I HEREBY ACKNOWLEDGE MY INDEBTEDNESS IN THE AMOUNT OF \$_____ BEING THE TOTAL AMOUNT OWING, OR BALANCE OWING AS SHOWN HEREON.

DATE _____

SIGNATURE