

MECHANIC	JOHN
DEPARTMENT	TRANS
REPAIR REQUEST NO: (IF APPLICABLE)	

[illegible][illegible]

PARTS AND MATERIALS

QTY	PART NUMBER	DESCRIPTION
1	11-8014	THOMAS LUBRIC (PND)
1		oil filter
1		FUEL Filter
1		Air Filter
1/2 hr		Engine oil
1	21-331-1	(New) top wire hose

RECORD OF REPAIRS

REPAIR REQUEST NO:	(IF APPLICABLE)
--------------------	-----------------

MECHANIC	10504
DEPARTMENT	Transport

REPAIRS / FAULTS
Intentional Light Switch Broken Side marker light / Responder / And meter / Broken

[illegible]

RECORD OF REPAIRS

START DATE:	14-2-23
END DATE:	15-2-23

KMS/HOURS	146061
REGO	83761-S
FLEET NO.	
VEHICLE	A-trailer

REPAIR REQUEST NO: (IF APPLICABLE)	
---------------------------------------	--

DEPARTMENT	Trans Port
------------	------------

MECHANIC	Will / 11/11
----------	--------------

REPAIRS / FAULTS	turntable foot brushes worn	turntable wear plate on turntable worn
Roller Service		
Roller Service		
May 1992		

QTY	PART NUMBER	DESCRIPTION
1	RK-331-1	Low Wire Plate
2	3D05B2	Wear Pad Foot Pocket
1	RK-06356	Turn table Pin Kit
1		Spacers
1		Oil Filter
1		Ever Puller
1		Pin Puller
1		Engine Oil

DAF

SHEPPARTON TRUCK CENTRE PTY. LTD.
 A.C.N. 147 859 210 A.B.N. 92 147 859 210
 CNR. DOYLES & NEW DOOKIE ROADS
 PO BOX 6116 SHEPPARTON VIC 3632
 PHONE: (03) 5821 3977 FAX: (03) 5821 9547
BANK DETAILS: NAB 083-764 189430118

Service TAX Invoice		CUSTOMER COPY		Date: 15/12/22	Document Number: 524289
----------------------------	--	----------------------	--	-----------------------	--------------------------------

Customer Details		JEFTOMSON TRANSPORT P/L		Reg No. 83761S		Stock No. Y55811		Advisor MAREE LUCAS MAREE LU		Terms 30	
Account: JEFTOMSON TRANSPORT P		Current Kims 0		Body No. 076699		Wty Start Date		Wty Expiry Date		Compliance Date	
Contact Today 0358 299 446		Engine Number 6F8T25008B076699		Build Date		Selling Dealer		Delivery Date		Order No. tba	
Driver Name JEFTOMSON TRAN		PP# CLOY/A02606		PP# DCODE/1223110		Fleet No.		Body Type		Card No. 53072	
Home No. 04 1079 4716		Vehicle Description MAXITRANS		Model DFT		Colour		Sale Kims		Ext Wty Type	
Work No. 03 5829 9200		Booked 14/12/22 08:00AM		Required 14/12/22 04:00PM		Ext Wty Exp Date		Ext Wty Exp KM		Email Address accounts@jeftomson.com	

Payment Details

Subacct Ref No. 53072 Date 15/12/22
 Detail CHR

Next Service Details

MONITOR BRAKE WEAR 20% REMAINING
 FOOT BUSHES ON TURNABLE TO BE REPLACED
 Your NEXT SERVICE is due at 0 kims or on 12/01/2023, whichever comes first.
 Please call our Service Dept on (03) 5821 3977 when you wish to make a booking.
 You were served by MAREE LUCAS MAREE LUCAS

Amount Due 446.05

Our services comes with guarantee that cannot be excluded under the Australian Consumer Law. For major failures with service, you are entitled:
 - to cancel your service contract with us, and
 - to a refund for the unused portion, or to compensation for its reduced value.
 You are also entitled to choose a refund or replacement for major failures with goods. If a failure with the goods or services does not amount to major failure, you are entitled to have the failure rectified in a reasonable time. If this is not done you are entitled to a refund for the goods and to cancel the contract for the service and obtain a refund of any unused portion. You are also entitled to be compensated for any other reasonably foreseeable loss or damage from the foreseeable loss or damage from a failure in the goods or service.

SHEPPARTON TRUCK CENTRE PTY. LTD.
A.C.N. 147 859 210 A.B.N. 92 147 859 210
CNR. DOYLES & NEW DOOKIE ROADS
PO BOX 6116 SHEPPARTON VIC 3632
PHONE: (03) 5821 3977 FAX: (03) 5821 9547
BANK DETAILS: NAB 083-764 189430118

852247H
31670EH

Service TAX Invoice		CUSTOMER COPY		Date: 28/10/22		Document Number: 523741	
Customer Details		JEFFERSON TRANSPORT P/L		Reg No. 83761S		Stock No. Y55811	
22-30 WHEELER STREET		SHEPPARTON VIC 3630		Current Kims		Body No. 076699	
Account: JEFFERSON TRANSPORT P		Vehicle Identification Number		6F8T250008B076699		Build Date	
Contact No. Today		0358 299 446		Engine Number		JEFFERSON TRANS	
Driver Name		Driver Phone		PP#		CLOY/A02606	
Card No.		Home No.		Vehicle Description		MAXITRANS	
53072		04 1079 4716		Model		DFT	
Mobile No.		Work No.		Colour		Sale Kims	
0358 299 446		03 5829 9200		Required		27/10/22 04:30PM	
Email Address		accounts@jefferson.com		Booked		27/10/22 08:30AM	
Contact Today		0358 299 446		Selling Dealer		Delivery Date	
Order No.		TBA		Fleet No.		Order No.	
Body Type		TBA		Why Start Date		Why Expiry Date	
Compliance Date		TBA		Terms		30	
Advisor		MAREE LUCAS MAREE L		Compliance Date		TBA	

Carried out trailer service as per attached schedule

Labour TRAILER SERVICE
Sundry Lmx Grease
Qty Code 1.00 KW66
Operation ISVC
Amount 140.00
10.73
150.73

2 R REPAIR LIGHT AND REFLECTORS

P: LHS INDICATOR NOT OPERATING AND REFLECTOR TO BE REPLACED
C: WIRING FOR LIGHT U/S REFLECTOR BROKEN
R: REMOVED AND REPLACED REFLECTOR, CHECKED OPERATION OF INDICATOR FOUND WHEN UNIT WAS ROLLED FORWARDS IT WOULD WORK BUT WHEN ROLLED BACK IT WOULD NOT WORK, CHECKED PLUGS AT BOTH ENDS OF WIRING COIL THAT RAN UNDERNEATH AND FOUND PLUG AT FRONT WAS U/S, CUT OFF PLUG AND WIRED IN NEW, TEST OPERATION OK.
Labour REPAIR LIGHT AND REFLECTORS
Parts (F1) Reflector-White
(F1) 7 Pin Flat Plug Blister
Qty Num/Ref 1 K*2921 1 K*82141BL
Unit Price 4.14 6.93
Total Item 2 151.07

3 R REPAIR SCAM TUBES

P: SCAM TUBES TO BE WELDED
C: MOVEMENT
R: CLEANED TUBES FOR LHS MIDDLE AND REAR, WELDED AS REQUIRED.
Labour REPAIR SCAM TUBES
Operation
Amount 140.00
140.00
151.07

4 R ADJUST WHEEL BEARINGS

NOT REQUIRED
Labour ADJUST WHEEL BEARINGS
Parts (F1) Gskt-Multi Hole
Qty Num/Ref 1 K*104-4042
Unit Price 2.27
Total Item 4 2.27
Amount 0.00
2.27

Continued Over

Our services comes with guarantee that cannot be excluded under the Australian Consumer Law. For major failures with service, you are entitled; to cancel your service contract with us, and to a refund for the unused portion, or to compensation for its reduced value.
You are also entitled to choose a refund or replacement for major failures with goods. If a failure with the goods or services does not amount to major failure, you are entitled to have the failure rectified in a reasonable time. If this is not done you are entitled to a refund for the goods and to cancel the contract for the service and obtain a refund of any unused portion. You are also entitled to be compensated for any other reasonably foreseeable loss or damage from the goods or service.
Failure in the goods or service.

SHEPPARTON TRUCK CENTRE PTY. LTD.
A.C.N. 147 859 210 A.B.N. 92 147 859 210
CNR. DOYLES & NEW DOOKIE ROADS
PO BOX 6116 SHEPPARTON VIC 3632
PHONE: (03) 5821 3977 FAX: (03) 5821 9547
BANK DETAILS: NAB 083-764 189430118

Service TAX Invoice		CUSTOMER COPY		Date: 28/10/22		Document Number: 523741	
Customer Details JEFTHOMSON TRANSPORT P/L 22-30 WHEELER STREET SHEPPARTON VIC 3630 Account: JEFTHOMSON TRANSPORT P							
Contact No. Today		Contact Today		Engine Number		Build Date	
0358 299 446		JEFTHOMSON TRANS		6F8T250008B076699		Compliance Date	
Driver Name		Driver Phone		PP#		Delivery Date	
53072		04 1079 4716		CLOY/A02606		Order No. TBA	
Mobile No.		Work No.		Vehicle Description		Body Type	
0358 299 446		03 5829 9200		MAXITRANS		Ext Why Type	
Email Address		Model		Colour		Sale Kims	
accounts@jefthomson.com		DFT				Ext Why Exp Date	
Booked		Required		27/10/22 04:30PM		Ext Why Exp KM	
27/10/22 08:30AM							

R ADJUST TURNTABLE

P: TURNABLE JAWS TO BE ADJUSTED
C: MOVEMENT IN JAW
R: ADJUSTED JAWS AS REQUIRED.

Labour

ADJUST TURNTABLE

6 R REPLACE LOWER SHOCKER RUBBERS

P: ALL LOWER SHOCKER RUBBERS TO BE REPLACED
C: WORN ALLOWING SHOCKERS TO BE LOOSE
R: REMOVED ALL LOWER BOLTS, REPLACED ALL SHOCKER RUBBERS, REFITTED SHOCKERS.

Labour

REPLACE LOWER SHOCKER RUBBERS

Parts

(F1) Kit-Shocker Bush

Sublet

(R2) CONSUMABLES/ENVIRO LEVY

Qty Num/Ref 2 K*98941-006-8P

Operation

Unit Price 74.97

Total Item 6

Amount 149.94

Amount 15.29

Total Sublet

Total Costs
Total Invoice (excluding GST) 777.30
Total Goods & Services Tax 77.73
Total Round Off 0.02
Total Invoice (including GST) 855.05

Payment Details

Subacct 53072 Ref No. 523741 Date 28/10/22 Detail CHR

Next Service Details

Your NEXT SERVICE is due at 0 Kims or on 26/04/2023, whichever comes first.
Please call our Service Dept on (03) 5821 3977 when you wish to make a booking.
You were served by ADRIAN WOJCIK

Our services comes with guarantees that cannot be excluded under the Australian Consumer Law. For major failures with service, you are entitled:
to cancel your service contract with us, and
to a refund for the unused portion, or to compensation for its reduced value.

You are also entitled to choose a refund or replacement for major failures with goods. If a failure with the goods or services does not amount to major failure, you are entitled to have the failure rectified in a reasonable time. If this is not done you are entitled to a refund for the goods and to cancel the contract for the service and obtain a refund of any unused portion. You are also entitled to be compensated for any other reasonably foreseeable loss or damage from the foreseeable loss or damage from a failure in the goods or service.

RECORD OF REPAIRS

START DATE:	01-9-22
END DATE:	01-9-22

KMS/HOURS	141416.2
REGO	85701
FLEET NO.	
VEHICLE	✓ 124112

REPAIR REQUEST NO:	(IF APPLICABLE)
--------------------	-----------------

MECHANIC	<i>[Signature]</i>
DEPARTMENT	<i>[Signature]</i>

REPAIRS / FAULTS	Service	10/12/12 # 35024	10/11/12 # 31972
		Front Motor	

[illegible]

RECORD OF REPAIRS

REPAIR REQUEST NO:	(IF APPLICABLE)
--------------------	-----------------

MECHANIC	<i>John</i>
DEPARTMENT	<i>Thompson</i>

[illegible]

RECORD OF REPAIRS

27-4-22	START DATE:
29-4-22	END DATE:

KMS/HOURS	138528
REGO	83701.5
FLEET NO.	
VEHICLE	A-74412

REPAIR REQUEST NO: (IF APPLICABLE)	
---------------------------------------	--

MECHANIC	10/10/2024
DEPARTMENT	TRANS

REPAIRS / FAULTS	DATE	BY	TIME
Service And Repair			

QTY	PART NUMBER	DESCRIPTION
2		MWD Guard
2		MWD PWR
1		20/30 Brake Boost
1		Chassis
1	307-0713	HUB SPR
1	3009	HUB CAP (RIGHT)
1		HUB OIL
1		Cleaner Wagon System

RECORD OF REPAIRS

23-3-22	START DATE:
28-3-22	END DATE:

KMS/HOURS	1370606
REGO	837615
FLEET NO.	
VEHICLE	5 TWIN-14

REPAIR REQUEST NO:	(IF APPLICABLE)
--------------------	-----------------

MECHANIC	✓
DEPARTMENT	✓

REPAIRS / FAULTS	DATE	TIME	BY
Fill Bore - Bracket repair			
Oil Leak Lt middle HUB			

[illegible]

RECORD OF REPAIRS

REPAIRS / FAULTS	
Left side indicator, mount LTR hinge on toolbox, rear light bar, bridge motor, sensor	

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.[illegible]

RECORD OF REPAIRS

REPAIR REQUEST NO:	(IF APPLICABLE)	3253
--------------------	-----------------	------

MECHANIC	
DEPARTMENT	Transp

[illegible]

RECORD OF REPAIRS

START DATE:	27/10/21
END DATE:	27/10/21

KMS/HOURS	1,315,239 km
REGO	83761.5
FLEET NO.	N/A
VEHICLE	A-TRAILER VAN

REPAIR REQUEST NO: (IF APPLICABLE)	N/A
---------------------------------------	-----

MECHANIC	MATT
DEPARTMENT	TECHSUPPORT

[illegible][illegible]

START DATE:	18-10-21
END DATE:	20-10-21
KMS/HOURS	1311 027
REGO	63761-5
FLEET NO.	
VEHICLE	A-100

REPAIR REQUEST NO:	(IF APPLICABLE)
DEPARTMENT	Transport
MECHANIC	Lesly

REPAIRS / FAULTS

trailer plug re/ter cut broken guard, brakes,
king pin, handle bushes, water pump bell

[illegible]

RECORD OF REPAIRS

REPAIR REQUEST NO:	(IF APPLICABLE)
--------------------	-----------------

MECHANIC	Joseph
DEPARTMENT	Manufacturing

[illegible]

Issue Date: 01/04/20 (R38)

RECORD OF REPAIRS

START DATE:	7-8-2021
END DATE:	7-8-2021

KMS/HOURS	1,288,401km
REGO	83761.5
FLEET NO.	N/A
VEHICLE	A-TRAILER VAN

MECHANIC	MATT + COBY
DEPARTMENT	TRANSPORT
REPAIR REQUEST NO: (IF APPLICABLE)	N/A

[illegible][illegible]

RECORD OF REPAIRS

REPAIR REQUEST NO:	(IF APPLICABLE)
--------------------	-----------------

MECHANIC	Cody
DEPARTMENT	Transport

[illegible]

REPAIR REQUEST NO: (IF APPLICABLE)	
---------------------------------------	--

MECHANIC	Cody
DEPARTMENT	Transport

[illegible]

RECORD OF REPAIRS

REPAIR REQUEST NO:	(IF APPLICABLE)
--------------------	-----------------

MECHANIC	Loddy
DEPARTMENT	Transport

[illegible]

Issue Date: 01/04/20 (R38)

REPAIR REQUEST NO:	
(IF APPLICABLE)	
DEPARTMENT	mechanics
MECHANIC	hatter

REPAIRS / FAULTS

SOUBALIN 1015 @ Pollen

[illegible]

Issue Date: 01/04/20 (R38)

REPAIR REQUEST NO:	
(IF APPLICABLE)	
DEPARTMENT	Transport
MECHANIC	Cody

REPAIRS / FAULTS

Height control valve belt loose, middle right shock loose
safety crack in cross member, rear left and right wheel
bearing front right angled

[illegible]

RECORD OF REPAIRS

VEHICLE	A-00AN
FLEET NO.	
REGO	83761-5
KMS/HOURS	29,250 ENCLIDE HOURS.

START DATE:	15/2/21
END DATE:	15/2/21

REPAIR REQUEST NO:	
(IF APPLICABLE)	

DEPARTMENT	TRANSPO/RT
MECHANIC	MAN.

[illegible][illegible]

RECORD OF REPAIRS

START DATE:	15/1/21
END DATE:	15/1/21

KMS/HOURS	29,098 EMD
REGO	83761-5
FLEET NO.	
VEHICLE	A-07A0

29,098 END HOURS

REPAIR REQUEST NO:	
(IF APPLICABLE)	
DEPARTMENT	TRANSPORT
MECHANIC	DAN

[illegible][illegible]

RECORD OF REPAIRS

REPAIR REQUEST NO:	
(IF APPLICABLE)	
CHINESE HOURS	
DEPARTMENT	TRANSPO
MECHANIC	DAN.

[illegible][illegible]

RECORD OF REPAIRS

END DATE:	5/10/20
START DATE:	14/0/20

KMS/HOURS	11049
REGO	5-13768
FLEET NO.	
VEHICLE	

REPAIR REQUEST NO:	(IF APPLICABLE)
--------------------	-----------------

MECHANIC	Code
DEPARTMENT	Transport

REPAIRS / FAULTS

flour reel end cap
both door seals getting worn
frontable rubber stoppad plate cracked
shade absorbers - replace next service
Door latch replaced

[illegible]

RECORD OF REPAIRS

16/10/20	START DATE:
16/10/20	END DATE:

KMS/HOURS	
REGO	83761-5
FLEET NO.	
VEHICLE	A-00AD

REPAIR REQUEST NO: (IF APPLICABLE)	
---------------------------------------	--

DEPARTMENT	TRANSPO
------------	---------

	MECHANIC
--	----------

[illegible][illegible]

RECORD OF REPAIRS

START DATE:	17/08/20
END DATE:	18/08/20
KMS/HOURS	1177039
REGO	83761-S
FLEET NO.	
VEHICLE	A7M1ER

MECHANIC	JOHNSON
DEPARTMENT	TRANSPORT
REPAIR REQUEST NO: (IF APPLICABLE)	

REPAIRS/FAULTS

EXCESSIVE PLAY AT THIS & OIL LEAK ON RH REAR

EXCESSIVE PLAY AT LH REAR THIS

LOOK OUT HOSE COUPERS male & female

GRIP WELD ON LH THRU NUT BRACKET

[illegible]

\\FILESVR01\CompanyData\Quality\Quality Manual\Transport\HACCP Transport\Records\R38 Record of Repairs 2020-04-01.docx

[illegible]