



Commercial Vehicle Inspection Report

Decal Number: GN93076
Decal Expiry Date: 2027-Aug-31
Inspection Number: 21895753

Inspection Result:
PASS

FACILITY:	PACIFIC CROSSROAD INDUSTRIAL REPAIRS / S17080	INSP. TYPE:	Complete	INSP. START:	2026-Aug-26 08:00 AM PDT
INSPECTOR:	BERNSTEIN, RALPH HERBERT / 106846	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2026-Aug-26 09:29 AM PDT
WORK ORDER #:	7784	INSP. REASON:	Annual		

VEHICLE JUR:	British Columbia	REGI:	13518792	VIN:	1FDAF57F3XEF11432
PLATE #:	YA7688	UNIT/FLEET#:	211	OWNER/LESSEE NAME:	Dolan's Ready Mix Ltd., .
LICENCED GVW(kg):	8250	BODY STYLE:	Utility Truck	ADDRESS:	4779 Roger Street
VEHICLE YEAR:	1999	ODOMETER:	278014 KM		Port Alberni, British Columbia
MAKE:	FORD	HUB ODOMETER:			V9Y3Z3, Canada
MODEL:		BRAKE TYPE:	Hydraulic		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3H - Hydraulic Brakes	Passed
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) Repair right mid clearance light
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed with Caution Right front tire needs to be replaced (owner aware)
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Not Applicable
Section 11 - Other Vehicle Components	Passed

Tire Tread Depth (mm)						Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Outer L	Inner L	Inner R	Outer R	Steering	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	8			1	✓	Pad	7	5	Rotor	37.60	38.08
2	19	10	16	16		Pad	13	10	Rotor	38.70	38.14
Comment: Right front tire needs to be replaced. Owner aware and truck is going to tire shop after leaving facility,						Comment:			Comment:		

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: R. Bernstein Road Tester:
Inspector: BERNSTEIN, RALPH HERBERT Signature:

This Inspection Report was submitted to CVSE on 2026-Aug-26 09:30 AM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVPA at the Commercial Vehicle Safety Enforcement

CVSE0014

8/28/2026 9:30:13 AM PDT