



## 2019 Kenworth W9 Series

### Test Information

<b>Engine</b>	Cummins ISX / X15 (15.0)
<b>Engine Serial</b>	CMMNS*6X3u17D1500000000*80446178*0000000000
<b>VIN</b>	<a href="#">1XKWD40X0KJ998963</a>
<b>Driveline</b>	Class 8 6x4
<b>Body</b>	Truck-Tractor MDHD: CBE (Cab Behind Engi
<b>Test Time</b>	March 20, 2025, 8:44 a.m.
<b>File Length</b>	75.283 s

### Usage

Label	Value	Units
Engine Odometer	452,882	mi
Engine Total Hours of Operation	18,382.9	h
Aftertreatment 1 Diesel Particulate Filter Soot Load Percent	84	%

### Engine On/Off

Engine running

### Check Engine Light

No check engine lights on

### Emissions Deleted/Tampered

No

### Faults

<u>DM</u>	<u>Controller Name</u>	<u>SPN Name</u>	<u>FMI Name</u>	<u>Count</u>
Previous	Engine #1	Anti-Lock Braking (ABS) Active	Abnormal Update Rate	2
Previous	Engine #1	Manufacturer Assignable SPN	Voltage Below Normal	1
Emissions Previous	Engine #1	ECU Power Output Supply Voltage #1	Erratic, Intermittent, or Incorrect	4
Emissions Previous	Engine #1	Manufacturer Assignable SPN	Voltage Below Normal	1