



# Commercial Vehicle Inspection Report

Decal Number: GF47067  
Decal Expiry Date: 2025-Aug-31  
Inspection Number: 21250864

Inspection Result:  
**PASS**

**FACILITY:** JOHNSON RADIATOR SERVICES / S5626  
**INSPECTOR:** GILOWSKI, TRAVIS GORDON / 200472  
**WORK ORDER #:** 205476  
**INSP. TYPE:** Complete  
**INSP. CLASS:** Class 3 - Trailer and Semi-Trailer  
**INSP. REASON:** Semi-annual  
**INSP. START:** 2025-Feb-18 05:00 AM -07  
**INSP. COMPLETE:** 2025-Feb-27 03:25 AM -07

**VEHICLE JUR:** British Columbia  
**PLATE #:** 75640K  
**LICENCED GVW(kg):** 999999  
**VEHICLE YEAR:** 2018  
**MAKE:** LANGFAB  
**MODEL:**  
**REGI:** 12563693  
**UNIT/FLEET#:** PVI-116B  
**BODY STYLE:** Pup Trailer  
**ODOMETER:**  
**HUB ODOMETER:**  
**BRAKE TYPE:** Air  
**FUEL TYPE:**  
**VIN:** 2L9PPA6C0JS014038  
**OWNER/LESSEE NAME:** PEACE VALLEY INDUSTRIES, PVI  
**ADDRESS:** PO BOX 1510  
Chetwynd, British Columbia  
V0C1J0, Canada

<b>Vehicle Identification (VIN)</b>	Passed
<b>Section 1 - Power Train</b>	Not Applicable
<b>Section 2 - Suspension</b>	Passed
<b>Section 3 - Brake System</b>	Passed
<b>Section 3A - Air Brakes</b>	<b>Repaired (same day)</b> REPLACED AXLE 2 BRAKE POT PLUGS
<b>Section 3H - Hydraulic Brakes</b>	Not Applicable
<b>Section 4 - Steering</b>	Not Applicable
<b>Section 5 - Instruments and Auxiliary Equipment</b>	Passed
<b>Section 6 - Lamps</b>	<b>Repaired (same day)</b> REPAIRED LICENSE LIGHT
<b>Section 7 - Electrical System</b>	Passed
<b>Section 8 - Frame and Body</b>	Passed
<b>Section 9A - Tires</b>	<b>Repaired (same day)</b> REPLACED AXLE 1 RIGHT OUTER TIRE, AXLE 2 RIGHT TIRES
<b>Section 9B - Wheels</b>	Passed
<b>Section 10 - Coupling Devices</b>	Passed
<b>Section 11 - Other Vehicle Components</b>	Passed

### Air Brake Chamber Type, Size and Push Rod Stroke (mm)

### Tire Tread Depth (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	40	40	11	12	13	19	
2	Clamp	30	Automatic	40	40	16	16	19	19	
3	Clamp	30	Automatic	40	40	16	16	11	17	

Comment:

Comment:

### Air Brake Camshaft Rotation (degrees)

### Brake Lining/Pad (mm)

### Rotor Thickness or Drum Inside Diameter (mm)

Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	70	95	Lining (Shoe)	16	12	Drum		
2	40	70	Lining (Shoe)	17	16	Drum		
3	70	75	Lining (Shoe)	14	14	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

### Inspection Comments:

Has this Vehicle been road tested? No  
Inspector: GILOWSKI, TRAVIS GORDON

Road Test Date:  
Signature: *Travis Gordon*

Road Tester: *Travis Gordon*

This Inspection Report was submitted to CVSE on 2025-Feb-27 04:38 AM -07

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

### NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

2/27/2025 4:38:31 AM -07