



# Commercial Vehicle Inspection Report

Decal Number: GF47053  
Decal Expiry Date: 2025-Aug-31  
Inspection Number: 21227521

Inspection Result:  
**PASS**

K04-17

FACILITY: JOHNSON RADIATOR SERVICES / S5626  
INSPECTOR: GILOWSKI, TRAVIS GORDON / 200472  
WORK ORDER #: 206040  
INSP. TYPE: Complete  
INSP. CLASS: Class 3 - Trailer and Semi-Trailer  
INSP. REASON: Semi-annual  
INSP. START: 2025-Jan-29 04:00 PM -07  
INSP. COMPLETE: 2025-Feb-04 07:50 AM -07

VEHICLE JUR: British Columbia  
PLATE #: 28308K  
LICENCED GVW(kg): 0  
VEHICLE YEAR: 2020  
MAKE: LANGFAB  
MODEL:  
REGI: 13143945  
UNIT/FLEET#: PVI-122B  
BODY STYLE: Dump Trailer  
ODOMETER:  
HUB ODOMETER:  
BRAKE TYPE: Air  
FUEL TYPE:  
VIN: 2L9PPA6C3LS014103  
OWNER/LESSEE NAME: PEACE VALLEY INDUSTRIES, PVI  
ADDRESS: PO BOX 1510  
Chetwynd, British Columbia  
V0C1J0, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Repaired (same day) REPLACED AXLE 2 LEFT AIR BAG
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) REPLACED AXLE 3 LEFT SERVICE LINE, AXLE 1 SUPPLY LINE
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) REPLACED LICENSE LIGHT
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

## Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	40	40	15	14	14	15	
2	Clamp	30	Automatic	40	40	14	16	14	14	
3	Clamp	30	Automatic	40	40	14	13	19	19	

Comment:

Comment:

## Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	55	80
2	90	50
3	50	90

Comment:

## Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	15	16
Lining (Shoe)	12	15
Lining (Shoe)	17	14

Comment:

## Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

## Inspection Comments:

Has this Vehicle been road tested? No  
Inspector: GILOWSKI, TRAVIS GORDON

Road Test Date:  
Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Feb-04 07:57 AM -07

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

## NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement.

CV/SE0014

2-4 2025 7:57:25 AM -07