

Commercial Vehicle Inspection Report

Decal Number: Decal Expiry Date: Inspection Number:

GD88952 2025-Apr-30 21126084

Inspection Result:

INSPECTOR: WORK ORDER #:

JOHNSON RADIATOR SERVICES / FACILITY:

S5626

GILOWSKI, TRAVIS GORDON /

200472

INSP. TYPE:

INSP. CLASS: INSP. REASON:

BODY STYLE:

ODOMETER:

BRAKE TYPE:

FUEL TYPE:

HUB ODOMETER:

Class 3 - Trailer and Semi-Trailer

INSP. START: INSP. COMPLETE: 2024-Oct-29 03:00 PM -07 2024-Oct-30 02:00 PM -07

200182

VEHICLE JUR: PLATE #:

VEHICLE YEAR:

MAKE:

MODEL:

British Columbia 08894K

LICENCED GVW(kg): 0 2020 LANGFAB REGI: UNIT/FLEET#:

13155897 PVI-123B Dump Trailer

Air

Complete

Semi-annual

VIN:

OWNER/LESSEE NAME: ADDRESS:

2L9PPA6C7LS014105 PEACE VALLEY INDUSTRIES, PVI

Thickness or Drum Diameter not measured.

PO BOX 1510

Chetwynd, British Columbia

V0C1J0, Canada

Vehicle Identification (VIN)

Section 1 - Power Train Section 2 - Suspension Section 3 - Brake System

Section 3A - Air Brakes Section 3H - Hydraulic Brakes

Section 4 - Steering

Section 5 - Instruments and Auxiliary Equipment Section 6 - Lamps

Section 7 - Electrical System Section 8 - Frame and Body Section 9A - Tires Section 9B - Wheels

Section 10 - Coupling Devices Section 11 - Other Vehicle Components Passed Not Applicable Passed

> Passed REPLACED AXLE 1 RIGHT BRAKE POT Repaired (same day)

Not Applicable

Not Applicable

Passed

Passed Passed Passed Passed Passed Passed

Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Tire Tread Depth (mm)

The brains of the state of the						me mene webe				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	40	40	11	15	12	12	
2	Clamp	30	Automatic	40	40	20	19	20	20	
3	Clamp	30	Automatic	40	40	20	20	20	20	
Comment:						Comment:				

Air Brake Camsha	ft Rotation (degr	ees)	Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right	
1	50	30	Lining (Shoe)	16	17	Drum			
2	60	90	Lining (Shoe)	15	13	Drum			
3	45	60	Lining (Shoe)	17	17	Drum			
Comment: Comment:						Comment: Air Brake Camshaft Rotation performed. Rotor			

Inspection Comments:

Inspector:

Has this Vehicle been road tested?

GILOWSKI, TRAVIS GORDON

Road Test Date: Signature:

This Inspection Report was submitted to CVSE on 2024-Oct-30 02:09 PM -07

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Metor Vehicle Act and Division 25 of the Libitor Vehicle Act Regulations, it is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle hispection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager. NSCVIP at the Commercial Vehicle Safety Enforcement. CVSE0014

10/30/2024 2:09:11 PM:-07