

Service Job	Invoice No	Date	Customer Id	Customer Name	Cost Cent	Prob	Type of Call	Equip ID	Hrs	Kms	Job Description	Work Done	Labor Cost	Material Cost	Subcontractor Cost	Other Cost	Total Cost
91745	110140	06/03/2026	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	R	Electrical	1ME1172	55002.0000	0	REPLACE SENSOR UNIT		0	592.02	0	0	592.02
89694	110142	05/01/2026	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	R	Sundries	1ME1172	55002.0000	0	COMPLETE MAY PMI'S & WEEKLY WASH OUTS		102	0	0	0	102
87869	106636	03/31/2026	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	R	Brake	1ME1172	0.0000	0	INSPECT BRAKE ASSEMBLIES - KOMATSU		0	0	667.95	0	667.95
87225	106619	03/19/2026	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	R	Hydraulic	1ME1172	55179.0000	0	REPLACE WORN HYD HOSE TO FIRE SUPPRESSION SYSTEM		144	0	93.69	0	237.69
84091	105069	01/20/2026	1HM112H BG	IC - NORSKE SKOG PROJECT	184G	R	Brake	1ME1172	55002.0000	0	RHS FRONT BRAKE FAULT	TRAVELLED TO BOYER REMOVED RH FRONT FINAL DRIVE DISASSEMBLED & INSPECTED RETURNED TO WORKSHOP & ORDERED PARTS ONCE PARTS ARRIVED, RETURNED TO BOYER FIT FINAL DRIVE BACK ONTO LOADER AS REQUIRED	1816.5	12093.84	0	430	14240.34
84018	104754	01/19/2026	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	R	Brake	1ME1172	54809.0000	0	RIGHT HAND FRONT BRAKE FAULT	DISASSEMBLED FRONT BRAKE ASSEMBLY AND FINAL DRIVE DISASSEMBLE BRAKE AND REPALCED ALL SEAL REASSEMBLED ALL AND TEST OPERATION ALL OK	5886	0	831.2	0	6717.2
83051	100438	12/19/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	182G	R	Sundries	1ME1172	54809.0000	0	REPAIR LOG GRAB	TRAVEL TO BOYER TO WELD REPAIR BROKEN TYNE ON LOG GRAB AS REQUESTED	1457	0	0	380	1837
82927	104429	12/17/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	S	Service EarthmovingB	1ME1172	55113.0000	0	COMPLETE 500 HR SERVICE		1306	3003.46	0	0	4309.46
81945	99451	12/02/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	R	Sundries	1ME1172	54809.0000	0	COMPLETE DECEMBER WEEKLY PMI;S & CORE / ENGINE WASHOUTS		384	0	0	0	384
81605	97785	11/26/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	121G	S	Compliance Annual	1ME1172	0.0000	0	COMPLIANCE INSPECTION - 6 MONTHLY - CHUBB		0	0	517.08	0	517.08
80422	98293	11/05/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	R	Sundries	1ME1172	54809.0000	0	NOVEMBER PMI,S & CORE WASH OUTS		288	0	55	0	343
80178	97438	10/31/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	R	Hydraulic	1ME1172	54809.0000	0	REPLACE LEAKING HYDRAULIC HOSE		288	359.1	758.47	0	1405.57
79290	94976	10/10/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	S	Service EarthmovingA	1ME1172	54809.0000	0	COMPLETE 250 HR SERVICE & SAMPLE ENGINE OIL		192	0	0	0	192

78778	96517	10/01/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	R	Sundries	1ME1172	54719.000 0 0	OCTOBER WEEKLY WASH & PMI;S	432	37.2	0	0	469.2
77287	94588	09/03/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	R	Sundries	1ME1172	54719.000 0 0	COMPLETE SEPTEMBER PMI'S & WEEKLY CORE WASH OUTS	0	22.36	110	0	132.36
77070	93528	09/01/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	182G	R	Hydraulic	1ME1172	54755.000 0 0	REPAIR LEAKING GLAND NUT SEALS ON CENTER DUMP RAM	3048	3394.32	0	150	6442.32
76880	94803	08/27/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	182G	R	Milling	1ME1172	0.0000 0 0	Machine 3 sets of polyurethane stops	576	635	0	60	1211
75821	94972	08/07/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	R	Engine	1ME1172	54680.000 0 0	DIAGNOSE FAULT CODES /HIGH BLOWBY PRESSURE& HIGH EXHAUST TEMP FAULTS	0	0	660	0	660
75472	92803	08/01/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	R	Sundries	1ME1172	54647.000 0 0	COMPLETE AUGUST WEEKLY PMI'S & CORE/ENGINE BAY WASH OUTS	864	49.6	0	0	913.6
73771	90719	07/02/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	R	Sundries	1ME1172	54590.000 0 0	COMPLETE JULY WEEKLY PMI'S & WASH CORE - ENGINE BAY AREAS	768	62	770	0	1600
73089	89374	06/19/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	INT-R	Engine	1ME1172	54570.000 0 0	REPLACE INTERCOOLER HOSES & BRAKE RELAY	336	1272.44	0	0	1608.44
72763	87819	06/13/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	R	Sundries	1ME1172	54570.000 0 0	REPAIR REVERS CAMERA &LOG GRAB TYNE WORK LIGHT U/S	192	0	0	0	192
72655	89376	06/12/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	S	Service Earthmovi ngC	1ME1172	54533.000 0 0	COMPLETE 1000 HR SERVICE	672	2933.89	0	0	3605.89
72242	89402	06/03/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	R	Sundries	1ME1172	54426.000 0 0	JUNE PMI ON LOG LOADER & COMPLETE PMI CHECK SHEET	1061	124	850	0	2035
71320	86533	05/19/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	R	Electrical	1ME1172	54426.000 0 0	REPAIR WORK LIGHT IN LOG GRAB	48	0	0	0	48
70903	85659	05/09/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	R	Sundries	1ME1172	54409.000 0 0	REPAIR CRACKED FRONT WINDOW & REMOVE &RE-FIT WINDOW GAURD	288	589.09	0	0	877.09
70640	87087	05/05/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	184G	R	Sundries	1ME1172	54400.000 0 0	Log grab crack repaires REPAIR CRACKS AROUND BUSHES IN LOG GRAB	1700	0	0	205	1905

70152	85558	04/23/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	R	Sundries	1ME1172	54088.000 0 0	REMOVE CLEAN AND RETENTION BOLTS IN ACCESS PLATFORM		96	0	0	0	96
70150	85557	04/23/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	R	Electrical	1ME1172	0.0000 54408	REPLACE FAILED HYDRAULIC CONTROL LEVERS		384	2059.49	0	0	2443.49
70107	84975	04/22/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	R	Electrical	1ME1172	54088.000 0 0	REPAIR ELETRICAL FAULTS WITH IGNITIO SWITCH AND REVERSE CAMERA		480	907.64	1000	0	2387.64
70048	84973	04/17/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	F	Electrical	1ME1172	54088.000 0 0	FIT UP NEW UHF ASSEMBLY		0	541.64	400	0	941.64
69608	84956	04/09/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	R	Electrical	1ME1172	54088.000 0 0	REPLACE FAILED CAMERA ON LOG GRAB		0	0	500	0	500
69544	84988	04/09/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	R	Sundries	1ME1172	54088.000 0 0	APRIL PMI LOG GRAB		0	24.8	200	0	224.8
68191	84984	03/17/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	R	Electrical	1ME1172	54088.000 0 0	DIAGNOSE FAULT CODES /WIRING REPAIRS	CODE CA274 FOUND FAILED PIN IN PLUG ON SCV2 REPLACED FUEL PUMP PCV2 VAVLE	276.66	2132.7	1350	0	3759.36
67990	82098	03/12/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	S	Service Earthmovi ngB	1ME1172	54088.000 0 0	COMPLETE 500 HR SERVICE	CARRY OUT SERVICE AND VEHICLE INSPECTION. CHECK ALL LIGHTS, CHECK FLUID LEVELS. CHECK SUSPENSION, BRAKES AND TYRES	373.12	3027.54	800	0	4200.66
67891	81918	03/11/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	R	Sundries	1ME1172	0.0000 0	EGR COOLER REPLACEMENT & COOLING SYSTEM FLUSH - KOMATSU		0	4335.83	9954.63	0	14290.46
67651	84983	03/05/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	R	Sundries	1ME1172	54088.000 0 0	MARCH WASH OUT RADIATOR CORES /ENGINE AREA		180.2	0	700	0	880.2
67412	84563	03/03/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	R	Sundries	1ME1172	54088.000 0 0	MARCH PMI		517.25	41.8	0	0	559.05
66993	84952	02/21/2025	1AUSTNH BG	BOYER PAPER MILL LTD	112G	R	Ground Engaging	1ME1172	54088.000 0 0	WELD ON NEW ARROW HEADS TO TYNE TIPS	WELD ON NEW ARROW HEADS TO TYNE TIPS	130	0	1656	0	1786
66228	79529	02/07/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	182G	FAB	Sundries	1ME1172	54088.000 0 0	CUT 8" ARROW HEAD X2 290MM		90.1	0	0	200	290.1
65986	80186	02/04/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	R	Radiator	1ME1172	54088.000 0 0	CLEAN RADIATOR CORES		599.43	18.63	250	0	868.06

65892	79617	02/03/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	R	Electrical	1ME1172	54088.000	0	0	REPAIR REVERSE CAMERA /CHECK TYRE PRESSURES	INSPECT REPORTED FAULTS WITH CAMERA REVERSE FACING COULD NOT FAULT, FULLY INSPECTED WIRING VISUALLY ALL OK AT TIME FRONT FACING CAMERA HAD POOR IMAGE QUALITY, ADJUSTED BRIGHTNESS AND WAS MICH BETTER, GOT DETAILS OFF 1ME1173 FRONT CAMERA AND SENT TO ANDREW	0	0	250	0	250
64143	77819	01/17/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	R	Sundries	1ME1172	54088.000	0	0	REPAIR GREASE LINE FITTING		419.76	0	0	0	419.76
63614	77385	01/08/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	INT-S	Service Earthmovi ngA	1ME1172	54088.000	0	0	COMPLETE 250 HR SERVICE	CARRY OUT SERVICE AND VEHICLE INSPECTION. CHECK ALL LIGHTS, CHECK FLUID LEVELS. CHECK SUSPENSION, BRAKES AND TYRES - REPAIR RHS FRONT WORK LIGHT CONNECTION - INSPECT TYRE CONDITION NOTES - FIRE SUPRESSION SYSTEM REMOVE MOUNTED GAUGE READS UNDERCHARGE, GAUGE ON BOTTLE READS WITHIN SPEC - THREADS ON IGNITION BARREL OR IGNITION NUT IS STRIPPED AND WILL NOT DO UP TIGHTEM. NEW BARREL REQUIRED	373.12	630	400	0	1403.12
63491	77169	01/06/2025	1HM112H BG	IC - NORSKE SKOG PROJECT	121G	S	Complian ce Annual	1ME1172	0.0000	0	0	COMPLIANCE INSPECTION FIRE SUPPRESSION SYSTEM - ANNUAL - CHUBB	INSPECTION COMPLETED BY CHUBB 26/11/2024	0	0	647.08	0	647.08
63387	78065	12/31/2024	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	R	Sundries	1ME1172	54000.000	0	0	JANUARY PMI		270.3	0	0	0	270.3
62302	76972	12/02/2024	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	INT-R	Sundries	1ME1172	54000.000	0	0	DECEMBER PMI		597.84	12.42	0	0	610.26
61926	77414	11/25/2024	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	INT-R	Electrical	1ME1172	54000.000	0	0	REPLACE FAULTY CIRCUIT BREAKER	REPLACE FACTORY 20A CIRCUIT BREKER TO 40A	93.28	61.5	400	0	554.78
61897	73938	11/25/2024	1HM112H BG	IC - NORSKE SKOG PROJECT	184G	R	Sundries	1ME1172	0.0000	53945	0	Call out - Lighting fault	CALLOUT TO INSPECT LIGHTING FAULT REPAIRED LIGHTING FAULT BLOWING FUSES TEST AND FOUND THAT ONLY BLOWING WHEN LIFT LEFT ON UNDER STARTING CONDITIONS	668.33	0	0	150	818.33
61730	84673	11/21/2024	1HM591H BG	CAPEX	112G	INT-R	Sundries	1ME1172	54000.000	0	0	CHANGE OUT CRACKED TYNES & REPAIR BUCKET FLOAT BRACKET	REMOVE TYNE AND FIT TYNE FROM 1ME1173 REPAIRED BUCKET FLOAT INSPECT A/C	1021.58	20213	200	0	21434.58
61363	73867	11/15/2024	1HM112H BG	IC - NORSKE SKOG PROJECT	184G	R	Electrical	1ME1172	0.0000	53925	0	4G Tracker		326.48	319	0	170	815.48
61069	74580	11/11/2024	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	INT-R	Sundries	1ME1172	54000.000	0	0	NOVEMBER PMI & GREASE LOG GRAB	CARRY OUT MONTHLY PMI INSPECTIONS - REPAIRED BENT STEP	373.12	0	0	0	373.12

61002	81304	11/08/2024	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	R	Engine	1ME1172	54000.000 0 0	DIAGNOSE COOLANT IN ENGINE OIL ISSUE		0	0	1702.5	0	1702.5
59553	77392	10/09/2024	1HM112H BG	IC - NORSKE SKOG PROJECT	112G	R	Electrical	1ME1172	53827.000 0 0	REPAIR LOG GRAB CAMERA /MONITOR ISSUES	CARRY OUT PMI INSPECTION	0	465.71	600	0	1065.71
											CHECK IF CAMERAS FOUND IN WORKSHOP WILL REPLACE FRONT CAMERA, OPERATOR REPORTED THAT IT IS GLARE OFF WORK LIGHTS NOT AN ISSUE WITH CAMERA ITSELF					
											FITUP SUPPLIED CAMERA AND TEST OPERATION					
											NOTES: RECOMMEND TRYING A COLOURED LIGHT AND ADJUSTING CONTRAST ON MONITOR OF A NIGHT WHEN IT IS AN ISSUE					
59581	72236	10/09/2024	1HM112H BG	IC - NORSKE SKOG PROJECT	184G	S	Service EarthmovingD	1ME1172	53828.000 0 0	D Service 54,000 hours	CARRY OUT SERVICE AND VEHICLE INSPECTION. CHECK ALL LIGHTS, CHECK FLUID LEVELS. CHECK SUSPENSION, BRAKES AND TYRES - TEST AND ADJUST AUTO GREASER	2485.7	4803.11	0	491	7779.81
											NOTES: ROCKER COVER GASKET LEAKING SLEW CYLINDER LEAKING LHS FRONT WINDOW CRACKED E-STOP NOT FITTED HYDRAULIC LINE UNDER CAB HYDRAULIC LINE BEHIND TRANSMISSION CRACKS AROUND GRAB ASSEMBLY					

Applied filters:
Posted_Date is on or after 01/01/1900
Equipment_ID is 1ME1172