

Service Job	Invoice No	Date	Customer Id	Customer Name	Cost Cent	Prob	Type of Call	Equip ID	Hrs	Kms	Job Description	Work Done	Labor Cost	Material Cost	Subcontractor Cost	Other Cost	Total Cost
98136		09/22/2026	1HM103HBG	ID - EARTH	192G	R	Bodywork	1ME730	0.0000	0	Inspect door not opening		378	0	0	0	378
97527	116878	09/10/2026	1HM103HBG	ID - EARTH	184G	R	Service Ear	1ME730	20184.000	0	PMI SERVICE	TRAVELLED TO HBMI CARRIED OUT PRE-DISPOSAL / PMI AS REQUIRED - INSPECTED E03 TRANS CODE FOUND TRAY POTENTIOMETER BROKEN & ROD BENT.	280.5	159.6	0	200	620.1
95208	115039	08/03/2026	1HM103HBG	ID - EARTH	184G	R	Sundries	1ME730	20128.300	0	INSPECT NO DRIVE FAULT	TRAVELLED TO HBMI TOP UP TRANSMISSION OIL OPERATION - ALL OK AT TIME OF TESTING	504	196.1	0	200	880.1
86232	104896	03/02/2026	1HM103HBG	ID - EARTH	184G	R	Sundries	1ME730	20128.300	0	REPLACE ALL MISSING PARTS AND CHECK ALL OIL LEVELS	CHECKED OVER & REFIT MISSING PANELS AS REQUIRED	300	15	0	15	315
79883	102573	10/27/2025	1HM103HBG	ID - EARTH	184G	R	Sundries	1ME730	0.0000	0	CHECK OUT FAULTS (MISSING PARTS)	TRAVELLED TO HBMI REFIT FLOOR & TRAY SENSOR AS REQUIRED CHECKED OVER - ALL OK AT TIME OF TESTING	100	30	0	210	310
74218	92128	07/09/2025	1HM103HBG	ID - EARTH	121G	R	Engine	1ME730	0.0000	0	KOMATSU TO INVESTIGATE ENG. MISS.	INJECTOR REPLACED	0	0	3769.84	0	3769.84
68271	81335	03/18/2025	1HM103HBG	ID - EARTH	182G	R	Trays/Buck	1ME730	20128.300	0	REPAIR TRAY	FABRICATE AND FIT NEW SPILL GUARD TO TOP OF HEADBOARD. WELD REPAIR CRACKING IN AND AROUND REAR PIVOT POINT.	875.56	0	0	100	975.56
67106	79565	02/25/2025	1HM103HBG	ID - EARTH	182G	INT-R	Sundries	1ME730	0.0000	0	DRILL HOLES IN SEAT BASE FRAME TO ALLOW FITTING OF DIFFERENT SEAT		225.25	31.59	0	25	281.84
66990	80007	02/21/2025	1HM103HBG	ID - EARTH	121G	R	Tyres	1ME730	0.0000	0	STRIP & FIT RUNOUT TYRE - RUBAND	STRIP & FIT RUNOUT TYRE - RUBAND	0	110	0	0	110
66582	79292	02/14/2025	1HM103HBG	ID - EARTH	182G	R	Sundries	1ME730	20128.300	0	FAB ACCUMULATOR MOUNTS	FABRICATE AND FIT NEW MOUNTING PLATES TO SUITE ACCUMULATORS.	527.35	216.42	0	50	793.77
61899	82086	11/25/2024	1HM103HBG	ID - EARTH	186G	R	Sundries	1ME730	20128.300	0	Inspect	refer attached for job story	7936.76	2892.2	0	790	11618.96
53028	64937	06/04/2024	1HM103HBG	ID - EARTH	186G	R	Sundries	1ME730	20128.300	0	Carry out apraisal for repairs.	CLEAN AND REMOVE BELLY PLATES BRING INTO SHED AND CARRRY OUT INSPECTION MAKE LIST OF REQUIRED REPAIRS AND SEND NOTES: AWAITING RESPONSE TO PROCESSED WITH REPAIRS OR NOT	1138.71	51.28	0	50	1239.99

52768	64863	05/30/2024	1HM103HBG	ID - EARTH186G	R	Electrical	1ME730	20000.000(0	Check Transmission fault codes	IDENTIFY LEAKS IN TRUCK FIT SEAT AND MOVE INTO WASHBAY REMOVE ALL COVERS AND PANELS STEAM CLEAN TO IDENTIFY LEAKS AND COMPLETE PMI	2004.73	129.03	0	50	2183.76
52576	62452	05/27/2024	1HM103HBG	ID - EARTH184G	R	Sundries	1ME730	20000.000(0	INspect LHF wheel seal	INDENTIFY WHEEL SEAL U/S AND ADVISE TO BE RETURNED TO THE WORKSHOP	138.33	0	0	50	188.33
51251	60411	04/30/2024	1HM103HBG	ID - EARTH184G	R	Sundries	1ME730	20000.000(0	Filter missed off service number 49857		0	163.31	0	0	163.31
49857	64669	04/02/2024	1HM103HBG	ID - EARTH184G	S	Service Ear	1ME730	20000.000(0	D Service - 20,000 hours	CARRIED OUT SERVICE & VEHICLE INSPECTION. CHECKED ALL LIGHTS, CHECKED FLUID LEVELS. CHECKED SUSPENSION, BELTS, BRAKES & TYRES. ROAD TESTED - ALL OK AT TIME OF TESTING FOLLOW UP NOTES: - RHF FINAL DRIVE PLUGS - RHF STRUT LEAKING - RHF FINAL DRIVE LEAKING OUT OF INPUT SEAL - OIL LEAKS UNDER CAB	2098.27	3386.28	0	400	5884.55
46662	55241	02/15/2024	1HM103HBG	ID - EARTH184G	R	Air Con	1ME730	19777.000(0	Repair A/C @ MPWTS	CHECKED A/C FAULT. FITTED GAUGES, FOUND GAS IN SYSTEM. CARDBOARD BLOCKING RADIATOR FAN FROM COOLING CONDENSOR. CLEANED OUT CORES. RAN TRUCK AND TESTED OK. NOTICED TRACKER NOT WORKING, REPLACED BLOWN FUSE AND SECURED WIRING. TRAVLLED MWTS 30KM	264	0	0	75	339
45031	55349	01/11/2024	1HM103HBG	ID - EARTH184G	R	Sundries	1ME730	19777.000(0	Top up coolant - MPWTS	TOPPED UP COOLANT AND CHECKED FOR LEAKS.	264	77.9	0	80	421.9

42721	52312	11/15/2023	1HM103HBG	ID - EARTH182G	R	Trays/Buck	1ME730	19777.000	0	REPAIR TAILGATE SEAL	• CUT AND REMOVE CRUSHED AND BENT SEALER FRAME FROM TAILGATE. • STRAIGHTEN AND REPAIR GOUGES IN LOWER SECTION OF TAILGATE. • FABRICATE AND FIT NEW SEALING FRAME INTO LOWER SECTION AND SIDES OF TAILGATE. • WELD OUT ALL SEAL FRAMES. • CUT AND FIT NEW RUBBER SEAL INTO NEW SEAL FRAME. • WELD REPAIR CRACKING IN AND AROUND END SECTION OF TRAY. • CUT AND REMOVE WORN TRAY MOUNTING CUSHION PADS. • FABRICATE AND FIT NEW CUSHION PAD FRAME TO TRAY BODY. • FIT UP NEW CUSHION PADS. • COMPLETE FINAL INSPECTIONS OF ALL WORKS COMPLETED.	5903.25	272.49	0	80	6255.74
42730	53279	11/15/2023	1HM103HBG	ID - EARTH186G	S	Service Ear	1ME730	19777.000	0	250hr Service,Adjust Tray Pads	CARRIED OUT 250 HR SERVICE AS PER CHECKLIST - TOPPED UP TRANSMISSION OIL - TOPPED UP HYDRAULIC OIL - TOPPED UP DIFF OILS - REMOVED BATTERIES FROM BATTERY BOX, REPAIRED BOX & REFIT BATTERIES. - REMOVED TRAY PADS, HAD WELD SHOP REPLACE MOUNTING PLATES, FIT NEW PADS TO REAR OF TRAY & ADJUSTED. - GREASED FULL UNIT - REPLACED LH MIRROR - FIT NEW CONDUIT TO WIRING HARNESS RAN & TESTED - ALL OK AT TIME OF TESTING	2358.5	1392.49	0	107	3857.99
41456	49446	10/19/2023	1HM103HBG	ID - EARTH182G	R	Sundries	1ME730	19777.000	0	REPAIR LEAKING HYRAULIC TANK	DRAIN AND EMPTY HYD OIL TANK. CLEAN AND REMOVE HEAVY BUILD UP OF NYRSTAR PRODUCT FROM THE INNER GUARD. INSPECT AND FIND LEAKS. GRIND, PREP AND PATCH LEAKING SECTION OF HYD OIL TANK. PREP AND TOUCH UP PAINT REPAIR. REFILL HYD OIL TANK COMPLETE FINAL INSPECTION.	1232.5	0	0	130	1362.5

41296	50486	10/17/2023	1HM103HBG	ID - EARTH 182G	INT-R	Hydraulic	1ME730	0.0000	0	RESEAL STEERING CYLINDER, REPAIR BEARING BORES IN 2 LIFT CYL & REPAIRS TO MOUNTING BRACKETS, LINEBORE REAR TRAY PIVOT BORES, REPLACE BUSHES, PINS & SEALS	DISMANTLE, REPAIR ROD, RESEAL STEERING CYLINDER & REASSEMBLE, REPAIR BEARING BORES ON BOTH ENDS OF 2 LIFT CYL & LINE BORE MOUNTING BRACKETS ON TRAY, LINEBORE REAR TRAY PIVOT BUSH BORES & TRAY PIVOT BORE BRACKETS, REPLACE BUSHES, PINS & DUST SEALS ON TRAY PIVOTS & CYLINDERS.	12469.75	5156.37	0	300	17926.12
41094	52459	10/12/2023	1HM103HBG	ID - EARTH 186G	R	Chassis	1ME730	19777.0000	0	Hydraulic / Pin Repair	CAP AND FIT CYLINDER HYD LINES REMOVE PINS AND LIFT CYLINDERS TAKE CYLINDER TO MACHINE SHOP JACK UP UNIT, REMOVE LEFT FRONT WHEEL CLEAN OUT DIRT REMOVE HYD LINES AND GREASE LINES REMOVE PINS & CYLINDER AND WASH REFIT CYLINDER AND PINS RECONNECT HYD LINES REFIT WHEEL AND TORQUE WHEEL NUTS MOVE UNIT TO MACHINE SHOP REMOVE BROKEN TRAY SENSOR REMOVE ARM FIT ARM TO NEW SENSOR, FIT SENSOR AND CHECK CLEAN UP WORKSHOP AREA	4249.25	634.64	0	150	5033.89
39656	46592	09/14/2023	1HM103HBG	ID - EARTH 187G	R	Hydraulic	1ME730	19777.0000	0	HYD LIFT CYLINDER BEARING FAULT	HRS: 19,777 TRAVEL TO SITE, REMOVE HYD LIFT CYL PLUMBIDGE, BRACKETS & BOLTS READY FOR HYD / CYLINDER REMOVAL & COVER PLUMBIDGE TRAVEL TO SITE, AFTER MANAGEMENT CHANGE OF PLANS REFIT ALL THE ABOVE & RIGHT SIDE LIFT CYL ASSEMBLY	954.75	0	0	47.75	1002.5

39258	46576	09/06/2023	1HM103HBG	ID - EARTH	187G	R	Suspensior	1ME730	19777.000	0	REAR STRUT REPAIR	HRS: 19,777	379	0	0	299	678
												19/09 TRAVEL TO SITE, REMOVE HYD LIFT CYL PLUMBRIDGE, BRACKETS & BOLTS READY FOR HYD / CYLINDER REMOVEL & COVER PLUMBRIDGE					
												20/09 TRAVEL TO SITE, AFTER MANAGEMENT CHANGE OF PLANS REFIT ALL THE ABOVE & RIGHT SIDE LIFT CYL ASSEMBLY					
38302	46804	08/16/2023	1HM103HBG	ID - EARTH	184G	R	Transmissio	1ME730	0.0000	0	Transmission and Brake Tube Repairs - Komatsu	SUBLET ONLY	0	0	7193.37	0	7193.37
37146	43942	07/26/2023	1HM103HBG	ID - EARTH	182G	R	Sundries	1ME730	19521.000	0	MODIFY HEAD LIGHT MOUNTS	MODIFY HEAD LIGHT MOUNTS - CUT OUT MESH TO FIT IN LIGHT, CUT OUT ANGLE FOR MOUNTING IN HEADLIGHTS,	425	0	0	50	475
36675	44770	07/17/2023	1HM103HBG	ID - EARTH	184G	R	Sundries	1ME730	0.0000	0	REPAIRS	CHECKED HEADLIGHTS AND FRONT INDICATORS U/S SUPPLIED AND FITTED NEW LED HEADLIGHTS. WITH SEALED INDICATORS. MODIFIED HEADLIGHT BRACKET TO SUIT NEW LIGHTS. WIRED IN AS REQUIRED. FITTED NEW RADIATOR HEADER TANK, TOPPED UP COOLANT. FITTED NEW MOUNTS FOR UHF RADIO REPAIRED IDLE FAULT, FOUND WIRING FAULT TO IDLE SWITCH. FITTED NEW TRAY POTENTIOMETER, REMOVED FAULTY UNIT, DRILLED OUT BROKEN BOLTS. PARTS TESTED OK	1625	1716.98	0	100	3441.98

34719	39410	06/09/2023	1HM103HBG	ID - EARTH	186G	R	Hydraulic	1ME730	19521.000	0	Trenamission Issue - Komatsu	SUBLET TO KOMATSU, THEIR STORY AS BELOW:	0	0	1361.53	0	1361.53
												TRAVELLED TO SITE & CHECKED FOR TRANS FAULT, FOUND GEAR LEVER & DIAGNOSTIC SWITCH U/S REMOVED DASH & FIT NEW MONITOR SWITCHES. CHECKED FOR FAULT CODES, TESTED OPERATION UNTIL HOT - ALL OK AT TIME OF TESTING NOTED THAT ACCELLERATOR PEDAL HAD BUILD-UP AROUND BASE, CAUSING INCREASED LOW IDLE. CLEANED OUT AROUND PEDAL & TESTED OPERATION - ALL OK AT TIME OF TESTING. IDLE SWITCH ON DASH REQUIRES REPLACEMENT					
32425	39632	05/16/2023	1HM103HBG	ID - EARTH	184G	R	Trays/Buck	1ME730	0.0000	0	FIT NEW TAILGATE SEAL	- CHECKED OVER UNIT & REPLACED TAILGATE SEAL AS REQUIRED - REPAIRED LIGHTS	1148.69	496.28	0	55	1699.97
31219	36165	04/20/2023	1HM103HBG	ID - EARTH	182G	R	Trays/Buck	1ME730	19537.000	0	REPAIR CRACKS IN REAR OF TRAY	REPAIR CRACKS IN REAR OF TRAY GOUGE OUT CRACKS, WELD CRACS, MAKE NEW PINS, WELDHANDLES ON PINS, CLEAN UP WORK AREA	1246.3	124.8	0	150	1521.1
31150	36764	04/19/2023	1HM103HBG	ID - EARTH	184G	S	Service Ear	1ME730	0.0000	0	SUPPLY FILTERS FOR IMPACT BOAT	SUPPLY PARTS ONLY	1.42E-14	267.26	0	0	267.26
31152	38262	04/19/2023	1HM103HBG	ID - EARTH	184G	R	Electrical	1ME730	0.0000	0	ELECTRICAL REPAIRS	TRAVEL TO IMPACT INSPECT FOR ELECTRICAL ISSUES FOUND BOTH HEADLIGHT TO REQUIRE REPLACING AS WERE BLOWN REPLACE BROKEN ROTATING LIGHT BRACKET FOUND WIRING FAULT AND REPAIRED FOR BOAT	747.1	33.92	0	50	831.02
31015	38068	04/17/2023	1HM103HBG	ID - EARTH	184G	S	Service Ear	1ME730	19537.000	0	C Service 19,500 Hours		798.78	1414.45	0	55	2268.23
30766	35665	04/12/2023	1HM103HBG	ID - EARTH	184G	R	Air Con	1ME730	0.0000	19795	A/C repairs	INSPECT REPORTED A/C IN OP FOUND COMPRESSOR, CONDENSOR AND RECIEVER DRIER U/S FIT AND MODIFY AFTERMARKKET UNIT TO SUIT AS GEN WAS EX JAPAN REPLACED ALL OTHER U/S PARTS AS REQUIRED AND REGAS SYSTEM. TEST AND CHECK FOR LEAKS ALL OK. REPLACED BATTERY ISOLATOR AS NEEDED - CONDENSOR SUPPLIED BY NYRSTAR	1039.98	576.96	0	130	1746.94

30304	34594	03/31/2023	1HM103HBG	ID - EARTH1 184G	INT-R	Electrical	1ME730	0.0000	19500	Repair GPS tracker fault	TRAVELLED TO IMPACT FERTILISER TO INSPECT TRACKER NOT WORKING. - FOUND TRACKER RECEIVING 2v POWER SUPPLY ON WHITE WIRE. SUPPLIED & FIT RELAY TO RECTIFY PROBLEM. - REMOUNTED TRACKER BEHIND HEADLIGHT, AS PREVIOUSLY WAS IN BATTERY BOX & RECEIVNG POOR GPS SIGNAL. - REPLACED 4x HEAVILY CORRODED BATTERY TERMINALS. TESTED OPERATION - ALL OK AT TIME OF TESTING	269.31	0	0	45	314.31
28685	33645	03/20/2023	1HM103HBG	ID - EARTH1 105G	R	Service Ear	1ME730	19461.000	0	MARCH PMI	1ME730	165.54	0	0	0	165.54
27999	33067	03/06/2023	1HM103HBG	ID - EARTH1 182G	R	Trays/Buck	1ME730	19461.000	0	REPAIR TAILGATE	JOB CARRIED OUT - CARRY OUT PMI'S DURING MARCH. REPAIR TAILGATE - UNBOLT TAILGATE FROM R/H ARM, UNBOLT ARM, PUT IN PRESS & STRAIGHTEN, GAS CUT HOLE IN TRAY TO CLEAR MAIN PIVOT BOLT. BOLT UP & TEST REMOVE OLD WORN FLOOR PLATE, CUT NEW FLOOR PLATE & WELD IN	1654.8	140.55	0	100	1895.35
27736	32689	02/27/2023	1HM103HBG	ID - EARTH1 105G	R	Sundries	1ME730	19461.000	0	complete pmi / grease line repiar	1ME730	124.16	0	280	0	404.16
27388	37225	02/20/2023	1HM103HBG	ID - EARTH1 105G	R	Air Con	1ME730	19461.000	0	DIAGNOSE A/C FAULT	1ME730	993.25	1709.66	350	0	3052.91
											JOB CARRIED OUT - TEST A/C, WORKING OK. REMOVE REAR COVERS TO TEST HEATER FAN. FAN HAS FAILED. REPLACE FAILED FAN AND TEST OPERATION. REMOVED BOTH DOOR SEALS. USING SCRAPER AND WIRE WHEEL AND DEGREASER CLEANED CABIN AND DOOR SURFACES. FIT NEW DOOR SEALS. ADDED FOAM TAPE TO CABIN SIDE. BRIDGED A/C COMPRESSOR CLUTCH AND CLEANED EVAPORATOR. WIRED A/C IN FOR THE WEEKEND.					

25634	30023	02/06/2023	1HM103HBG	ID - EARTH# 105G	R	Engine	1ME730	17951.000	0	DIAGNOSE E03 CODE	1ME730	331.08	0	0	30	361.08
											JOB CARRIED OUT - DIAGNOSE E03 CODE. CLEANED ELECTRICAL PLUGS AND CLEARED CODES.					
25107	29408	01/23/2023	1HM103HBG	ID - EARTH# 105G	R	Brake	1ME730	17951.000	0	DIAGNOSE BRAKE FAULT	1ME730	124.16	0	0	0	124.16
											JOB CARRIED OUT - CLEANED PRODUCT FROM UNDER PEDALS.					
23475	27691	12/05/2022	1HM103HBG	ID - EARTH# 105G	R	Air Con	1ME730	17951.000	0	DIAGNOSE A/C FAULT	1ME730	0	0	175	0	175
											JOB CARRIED OUT - TEST A/C, FOUND CONDENSOR BLOCKED. REMOVE GRILL AND PRESSURE WASH CONDENSOR. LOW AIR FLOW AT THE VENT CAUSED BLOCKED EVAPORATOR.					
22746	27725	11/18/2022	1HM103HBG	ID - EARTH# 186G	INT-R	Suspension	1ME730	0.0000	0	Replace sway bar bushes	REMOVED SWAY BAR	588.24	1517.48	0	25	2130.72
											REPLACED BUSHES AND REFITTED					
22016	26272	11/03/2022	1HM103HBG	ID - EARTH# 192G	R	Hydraulic	1ME730	0.0000	0	INSPECT OIL LEAK NEAR HYDRAULIC TANK	INSPECTED HYD LEAK ON MOXIE FOUND IT CRACKED IN THE WELL CLEANED UP AREA SENT PHOTO TO CHRIS IN WELDING SHOP FOR REPAIRS	251.31	0	0	12.6	263.91
20061	23684	09/19/2022	1HM103HBG	ID - EARTH# 184G	INT-R	Electrical	1ME730	17951.000	0	REPAIR LIGHTS	REPAIR HEAD LIGHTS, FRONT PARK LIGHTS AND TAIL LIGHTS ON DUMP TRUCK.	649.05	0	0	70	719.05
											TRAVEL MORNINGTON AND RETURN					
19828	23853	09/14/2022	1HM103HBG	ID - EARTH# 184G	INT-S	Service Ear	1ME730	0.0000	0	S1 C SERVICE	CARRY OUT S1 C SERVICE AS PER SERVICE SHEET	756.64	2169.7	0	90	3016.34
											TRAVEL MORNINGTON AND RETURN					
19263	23282	09/02/2022	1HM103HBG	ID - EARTH# 184G	R	Sundries	1ME730	0.0000	0	INSPECT REPORTED FAULTS	CHECKED AND REPAIRED FAULT LIGHT	85.63	0	0	22.5	108.13
18026	21375	08/08/2022	1HM103HBG	ID - EARTH# 184G	R	Electrical	1ME730	0.0000	18755	CHECK BATTERIES AND REPAIR LIGHTS	INSPECT BATTERIES AND CHECK OVER UNIT, REMOVE AND REPLACE TAIL LIGHT ASSEMBLY	269.31	115.29	0	50	434.6
											TRAVEL NYRSTAR AND RETURN TWICE					
17280	21073	07/22/2022	1HM103HBG	ID - EARTH# 105G	R	Sundries	1ME730	18337.000	0	COMPLETE JULY MONTHLY PMIS	1ME730	248.31	255	0	0	503.31
											JOB CARRIED OUT - CARRY OUT PMI'S DURING JULY AND FIT NEW ID PLATES.					
17217	21613	07/20/2022	1HM103HBG	ID - EARTH# 184G	S	Service Ear	1ME730	0.0000	18760	CARRY OUT S1 A SERVICE	CARRY OUT S1 A SERVICE AS PER SERVICE SHEET'	171.26	327.06	0	25	523.32
											TRAVEL NYRSTAR AND RETURN					
17220	24931	07/20/2022	1HM103HBG	ID - EARTH# 184G	R	Trays/Buck	1ME730	0.0000	0	REPAIR TAIL BOARD SEAL	STRAIGHTEN BRACKETS AND REPLACE TAIL BOARD SEALING RUBBER	667.06	320	0	95	1082.06
											TRAVEL MORNINGTON AND RETURN					

17098	20694	07/18/2022	1HM103HBG	ID - EARTH	105G	R	Sundries	1ME730	18337.000	0	COMPLETE JULY MONTH;LY PMI INSPECTION	1ME730	496.62	0	105	100	701.62
15103	21043	06/02/2022	1HM103HBG	ID - EARTH	105G	R	Electrical	1ME730	18337.000	0	REPLACE FAILED HEAD UNIT	JOB CARRIED OUT - CARRY OUT PMI'S DURING JULY. 1ME730	248.31	141	0	50	439.31
14590	16833	05/23/2022	1HM103HBG	ID - EARTH	105G	R	Sundries	1ME730	18337.000	0	COMPLETE PMI INSPECTION	JOB CARRIED OUT - REPLACE FAILED HEAD UNIT. 1ME730	76.01	0	105	0	181.01
12211	14470	03/25/2022	1HM103HBG	ID - EARTH	105G	R	Sundries	1ME730	18337.000	0	COMPLETE WEEKLY PMI INSPECTION	JOB CARRIED OUT - CARRY OUT PMI'S DURING MAY. 1ME730	228.04	0	0	50	278.04
12157	14182	03/24/2022	1HM103HBG	ID - EARTH	184G	R	Electrical	1ME730	0.0000	0	REPLACE FAULTY PARK BRAKE SWITCH	JOB CARRIED OUT - CARRY OUT PMI'S DURING MARCH. SUPPLY NEW PARK BRAKE SWITCH, NYRSTAR WORKSHOP TO FIT	0	187.45	140	0	327.45
9913		02/03/2022	1HM103HBG	ID - EARTH	105G	R	Sundries	1ME730	18185.000	0	1ME730 COMPLETE PMI	1ME730	0	0	0	0	0
9916		02/03/2022	1HM103HBG	ID - EARTH	105G	R	Air Con	1ME730	18185.000	0	1ME730 SERVICE A/C FAULTS	JOB CARRIED OUT - CARRY OUT PMI. 1ME730	0	0	0	0	0
8295	9400	12/17/2021	1HM103HBG	ID - EARTH	184G	S	Service Ear	1ME730	18185.000	0	S1 A SERVICE	JOB CARRIED OUT - TEST OPERATION OF A/C. ALL WORKING CORRECTLY. VENT TEMP OF 10C. CARRY OUT S1 A SERVICE AS PER SERVICE SHEET	427.1	284.86	0	27.25	739.21
7678	10228	12/06/2021	1HM103HBG	ID - EARTH	105G	R	Hydraulic	1ME730	18051.000	0	repair hydraulic oil leaks	TRAVEL NYRSTAR 1,E730	190.03	1205.3	0	0	1395.33
7650	8531	12/03/2021	1HM103HBG	ID - EARTH	105G	R	Engine	1ME730	18051.000	0	REBUILD DAMPENER AND INSTALL REPLACE HYD HOUSES	JOB CARRIED OUT - FIT PINS TO REAR OF CABIN. UNBOLTED CABIN AT FRONT. USING LIFTING CHAINS, SHORTNERS, JIB AND FORK. ATTEMPTED TO LIFT CABIN. JOB CANCELLED DUE TO FORKLIFT REACH INADEQUATE. 1ME730	1079.37	144.76	0	60	1284.13
6867	8370	11/15/2021	1HM103HBG	ID - EARTH	182G	R	Lathe	1ME730	0.0000	0	MACHINE NEW DAMPER COUPLING AS REQUESTED	JOB CARRIED OUT - REASSEMBLED ENGINE DAMPENER. INSTALLED ASSEMBLY, INSTALLED JACK SHAFT. RE-INSTALLED ALL HOSES AND TESTED OPERATION. RE-FITTED CAB, REPLACED FAILED HOSE AND TESTED. MACHINE NEW DAMPER COUPLING AS REQUESTED	1991.49	1597.75	0	50	3639.24

6485	10227	11/04/2021	1HM103HBG	ID - EARTH184G	R	Sundries	1ME730	0.0000	18063	REPLACE DAMPER RUBBERS AND BEARINGS	REMOVE AND REPLACE REAR ENGINE MOUNTINGS, CHECK UNIT FOR VIBRATION, FOUND MOVEMENT IN DAMPER DRIVE SHAFT. REMOVE DAMPER FROM MACHINE AND STRIP DOWN , FOUND SPLINES ON DRIVE SHAFT AND BODY INSIDE DAMPER WORN OUT. HAVE NEW BODY MADE AND REASSEMBLE DAMPER WITH NEW DRIVE SHAFT , BEARING , SEAL AND DRIVE RUBBERS, REFIT DAMPER TO MACHINE AND TEST OPERATION . TESTED OK REASSEMBLE WORK CARRIED OUT BY KOMATSU FITTER 18,063 HRS	1333.82	3198.37	2073.86	50	6656.05
5592	7049	10/12/2021	1HM103HBG	ID - EARTH184G	R	Engine	1ME730	18051.000	0	REPLACE WORN REAR ENGINE MOUNTS	REMOVE AND REPLACE REAR ENGINE MOUNTS. REPLACE TRANSMISSION MOUNTING BOLTS ,	1106.49	850.76	0	50	2007.25
5503	6872	10/11/2021	1HM103HBG	ID - EARTH184G	R	Hydraulic	1ME730	17977.000	0	REPLACE BLOWN HOSE UNDER CAB	INSPECT OIL LEAK, REMOVE HOLD DOWN BOLTS AND LIFT CAB. REMOVE AND REPLACE BLOWN HOSE, TOP UP HYDRAULIC OIL AND RUN MACHINE TO CHECK FOR LEAKS, LOWER CAB AND REFIT HOLD BOWN BOLTS TRAVEL NYRSTAR AND RETURN	854.2	283.52	0	29	1166.72
5121	7821	09/29/2021	1HM103HBG	ID - EARTH184G	R	Electrical	1ME730	17956.000	0	INSPECT THROTTLE PEDAL ISSUE	INSPECT UNIT IDLING FAST, CLEAN RUBBISH FROM AROUND PEDAL AND FOUND THROTTLE SENSOR TO BE FAULTY AND NEEDS REPLACING. REPAIRED REVOLVING LIGHT WIRING TRAVEL NYRSTAR AND RETURN ENGINE IDLING A BIT FAST BECAUSE OF SENSOR,	384.39	0	0	34.5	418.89
4773	5596	09/21/2021	1HM103HBG	ID - EARTH184G	S	Service Ear	1ME730	17956.000	0	S1 D SERVICE	S1 D SERVICE AS PER SERVICE SHEET TRAVEL NYRSTAR AND RETURN	729.99	1895.71	0	50.5	2676.2
4675	4621	09/20/2021	1HM103HBG	ID - EARTH184G	R	Transmissio	1ME730	0.0000	0	REPAIR TRANSMISSION SHIFT FAULT	INSPECT TRANSMISSION SHIFT FAULT, TOPPED UP TRANSMISSION OIL AFTER HOSE REPLACEMENT. CHECKED BRAKE PEDAL AND REMOVED PRODUCT BUILD UP AND UNIT TESTED OK TRAVEL NYRSTAR AND RETURN	213.55	0	0	14.5	228.05
4507	4317	09/15/2021	1HM103HBG	ID - EARTH105G	INT-R	Hydraulic	1ME730	17681.700	0	REPLACE LEAKING/WORN HYD HOSE IN ARTIC AREA	1ME730 JOB CARRIED OUT - DIAGNOSE OIL LEAK IN ARTIC AREA. CALLED PIRTEK IN TO REPAIR.	76.01	839.63	0	0	915.64

4443	4280	09/14/2021	1HM103HBG	ID - EARTH1105G	INT-R	Electrical	1ME730	17681.700(0	ASSES E01 FAULT CODE MIDDLE BRAKE TEMP SENSOR	1ME730	76.01	0	70	20	166.01
										JOB CARRIED OUT - ASSESS E01 FAULT CODE FOR BEAKE TEMP SENDER. NO FAULT AT TIME OF TESTING.					
4105	4326	09/06/2021	1HM103HBG	ID - EARTH1105G	INT-R	Bodywork	1ME730	17681.700(0	REPAIR DAMAGED L/H SIDE MIRROR ASSEMBLY	1ME730	228.04	789.51	0	0	1017.55
										JOB CARRIED OUT - LEFT HAND SIDE MIRROR ASSEMBLY DAMAGED. ORDER AND FIT NEW ASSEMBLY.					
3797	3740	08/30/2021	1HM103HBG	ID - EARTH1105G	INT-R	Electrical	1ME730	17681.700(0	Diagnose electrical fault	1ME730	152.02	678.57	0	0	830.59
										JOB CARRIED OUT - DIAGNOSE ELECTRICAL FAULT.					
3777	3741	08/30/2021	1HM103HBG	ID - EARTH1105G	INT-R	Electrical	1ME730	17681.700(0	REPAIR ERROR CODES / ELECTRICAL FAULTS	1ME730	228.04	0	455	0	683.04
										JOB CARRIED OUT - TEST FAULT CODES BY FLOW CHART. FOUND ONE OF THE BATTTERY ISOLATORS STUCK ON, CAUSING SEVERAL FAULTS. FIT NEW ISOLATOR.					
200831-000	SVC002517	07/22/2021	1H0103	ID - EARTH1105_HBGN	R	Sundries	1ME730	16760	REPAIR LIGHTS & WINDOW LEAKS	1ME730	254.45	0	0	170	424.45
										ODOMETER - 16760 HOURS					
										JOB CARRIED OUT - REPAIR WIRING TO BEACON LIGHT, REPLACED FAILED TERMINALS. RESEAL LEAKING FRONT WINDSCREEN. FRONT WINDOW WASHER SQUIRTER MISSING, FITTED NEW PART. CLEAN OUT WASHER BOTTLE AND REFILL. CARRY OUT WEEKLY PMI.					
2006	5445	07/15/2021	1HM103HBG	ID - EARTH1121G	R	Tyres	1ME730	17681.700(0	SUPPLY AND FIT TYRES	SUPPLY AND FIT TYRES	0	18074.16	0	0	18074.16

210222-00	SVC002601	07/09/2021	1H0103	ID - EARTH182_INT	A	Trays/Buck	1ME730			REPAIR REAR TRAY PROP MOUNTS	INSPECT AND PLAN REPAIR PROCEDURE. FABRICATE TEMPLATE OF TRAY SAFETY PIN MOUNTS. PROFILE CUT AND PROCESS PLATE FOR NEW PIN MOUNTS. MACHINE HOLES IN PROCESSED PLATES. CUT AND REMOVE DAMAGED MOUNTS. STRAIGHTEN AND REPAIR BENT SECTION IN AND AROUND REAR MOUNT. GRIND AND PREP FOR FITTING OF NEW MOUNTS. FIT UP NEW MOUNTS. LIFT TRAY AND TEST FIT PINS INTO NEW MOUNTS. WELD OUT ALL FABRICATED COMPONENTS. SAND AND PREP REPAIR FOR PAINT. GOUGE AND WELD REPAIR VARIOUS CRACKING IN AND AROUND BOTTOM OF TRAY AND REAR FRAME SECTION. COMPLETE FINAL INSPECTION ON REPAIR.	6611.88	970.99	0	0	7582.87
1282	9848	06/29/2021	1HM103HBG	ID - EARTH182G	R	Exhaust	1ME730	0.0000	0	FABRICATE NEW EXHAUST	FABRICATE NEW EXHAUST	2379.85	62.11	0	0	2441.96
1006	2196	06/23/2021	1HM103HBG	ID - EARTH184G	S	Service Ear	1ME730	0.0000	0	1ME730 S1 B SERVICE	S1 B SERVICE AS PER SERVICE SHEET REPAIR UHF AERIAL CABLE REMOVE , CLEAN AND LOCTITE BOLTS ON LEFT FRONT UNIVERSAL BOLTS. TENSION OTHER UNI BOLTS TRAVEL NYRSTAR	543.27	698.77	0	7.25	1249.29
995	3991	06/23/2021	1HM103HBG	ID - EARTH184G	R	Engine	1ME730	17681.500	0	1ME730 REPAIR EXHAUST SYSTEM	1ME730	1993.57	3048.08	0	0	5041.65
210323-00	SVC002621	05/29/2021	1H0103	ID - EARTH105_HBGN	R	Electrical	1ME730			Replace starter motor	JOB CARRIED OUT - COLLECT PARTS FROM LA WORKSHOP. MODIFY EXHAUST SYSTEM TO FIT MUFFLER. 1ME730	109.05	1086.63	140	0	1335.68
210323-00	SVC002616	05/25/2021	1H0103	ID - EARTH105_HBGN	S	Service	1ME730	17341		A TYPE SERVICE	ODOMETER - 17340 HOURS JOB CARRIED OUT - REPLACE STARTER MOTOR. 1ME730	145.4	245.85	0	50	441.25
											ODOMETER - 17341 HOURS JOB CARRIED OUT - CARRIED OUT S1A SERVICE.					

210210-00	SVC00259	04/23/2021	1H0103	ID - EARTH	184_INT	R	Tyres	1ME730	126127 KM	BROKEN WHEEL BOLTS	RAISE VEHICLE AND BLOCK . REMOVED WHEEL FOR THE BROKEN WHEEL RETAINING BOLTS TO BE REMOVED. HAVE BROKEN BOLTS REMOVED BY SOUTHERN THREAD REPAIRS REFITTED WHEEL AND TENSIONED RETAINING BOLTS WHEEL RETAINING BOLTS SHOULD HAVE TENSION RECHECKED .	921.25	465.31	930	30	2346.56
210226-00	SVC00260	04/22/2021	1H0103	ID - EARTH	184_INT	R	Brake	1ME730	17,242 HRS	REPLACE PARK BRAKE PADS	REMOVE AND REPLACE PARK BRAKE PADS AND ADJUST TO SUIT, FOUND BRAKE NOT HOLDING PROPERLY COMPARED WITH BRAKE OPERATION ON SECOND UNIT AND FOUND PARK BRAKE CYLINDER NOT OPERATING CORRECTLY. REMOVED AND REPLACED PARK BRAKE CYLINDER AND TESTED OPERATION TESTED OK REPAIRE A/C CONNECTION TRAVEL NYRSTAR AND RETURN X 2	1511.45	3215.58	0	50	4777.03
210322-00	SVC00261	04/22/2021	1H0103	ID - EARTH	184_INT	R	Electrical	1ME730	17334 HRS	REPLACE FAULTY WINDOW REGULATO	REMOVE DAMAGED WINDOW REGULATOR, MODIFY DOOR FRAME AND FIT NEW REGULATOR TRAVEL NYRSTAR AND RETURN	245.1	1390.91	0	0	1636.01
210414-00	SVC00262	04/22/2021	1H0103	ID - EARTH	184_INT	R	Electrical	1ME730	17242 HRS	FIT NEW AM/FM RADIO	TRAVEL IMPACT AND RETURN REMOVE OLD RADIO AND FIT NEW AM/FM RADIO, REPAIR WIRING IN DASH CAUSING FUSE TO BLOW MAKE UP AND FIT NEW SEAT ADJUSTER	245.1	115	0	10	370.1
210330-00	10179	04/21/2021	1H0103	ID - EARTH	121_INT	R	Sundries	1ME730		REPLACE WINDOW REG		0	0	0	0	0
210319-00	SVC00261	03/30/2021	1H0103	ID - EARTH	184_INT	R	Trays/Buck	1ME730	17,243 HRS	REPAIR TAIL GATE SEAL, CHECK O	REMOVE AND REPLACE DAMAGED TAIL GATE SEAL GREASE MACHINE AND CHECK OVER DISCONNECT FAULTY WINDOW REGULATOR TRAVEL IMPACT AND RETURN	304.7	6.43	0	12.5	323.63
210218-00	SVC00260	03/29/2021	1H0103	ID - EARTH	183_INT	R	Electrical	1ME730		REPLACE DAMAGED ISOLATOR SWITC	REPLACE DAMAGED ISOLATOR SWITCH. FLASHING LIGHT REPAIRS.	145.4	165.61	0	10	321.01
210210-00	SVC00259	03/11/2021	1H0103	ID - EARTH	184_INT	S	Service	1ME730	17,122hrs	S1C - 1000 HR SERVICE	1ME730	694.45	2148.47	0	35	2877.92
											CARRIED OUT THE REQUIRED SERVICE AND SAFETY INSPECTIONS AS PER SERVICE SHEET.					

201030-00:SVC00254	11/20/2020	1H0103	ID - EARTH1 105_HBGN	R	Electrical	1ME730	16964	REPAIR LIGHT WIRING ISSUES	1ME730	145.4	0	0	50	195.4
									ODOMETER - 16964 HOURS					
									JOB CARRIED OUT - DIAGNOSE WIRING ISSUE WITH HEAD LIGHTS. FOUND AND REPAIRED BREAK IN WIRING HARNESS.					
201013-00:SVC00254	11/16/2020	1H0103	ID - EARTH1 105_HBGN	R	Sundries	1ME730	16923	REPAIR FM RADIO & CAB LEAKS	1ME730	836.05	648.22	0	60	1544.27
									ODOMETER - 16923 HOURS					
									JOB CARRIED OUT - CAB LEAKING WATER. TEST WITH FIRE HOSE, FOUND COMING IN DRIVERS SIDE DOOR AND TOP OF WINDSCREEN. DOOR SEAL TORN, REMOVE AND REPLACE SEAL. PUT SILICONE AT TOP OF WINDOW WHERE WATER COMING IN. RADIO NOT WORKING, DISASSEMBLE DASH AND REMOVE RADIO. CHECK WIRING AND ANTENNA PLUG, ALL OK. SOURCE RADIO, NONE AVAILABLE, PUT DASH BACK TOGETHER. REMOVE DASH AND WIRE IN NEW RADIO AND TEST.					
200831-00:SVC00251	11/06/2020	1H0103	ID - EARTH1 184_INT	R	Air Con	1ME730	16,234 HRS	REPAIR AIR CON SYSTEM	TRAVEL TO NYRSTAR	2381.3	910.34	0	18.75	3310.39
									CHECK A/C SYSTEM FOR LEAKS, FOUND TX AND CHARGE VALVES BOTH LEAKING. REMOVE AND REPLACE VALVES, STRIPPED OUT HEATER BOX AND FOUND EVAPORATOR HOUSING CRACKED. REPLACED EVAPORATOR AND REASSEMBLED HEATER BOX, VAC DOWN SYSTEM AND TESTED OK. REGASSED SYSTEM AND TESTED OPERATION. LOWER CAB AND SECURE IN PLACE					
201002-00:SVC00253	10/28/2020	1H0103	ID - EARTH1 184_INT	R	Engine	1ME730	16234 hrs	REPAIR EXHAUST SYSTEM	RAISE CAB AND REMOVE EXHAUST PIPES	817	586.37	0	53	1456.37
									READY FOR REPLACEMENT. FABRICATE NEW EXHAUST SYSTEM READY FOR FITMENT					
201026-00:SVC00254	10/27/2020	1H0103	ID - EARTH1 105_HBGN	R	Electrical	1ME730	16862 HRS	ADJUST TRAY DUMP POTENTIOMETER	1ME730	145.4	0	0	0	145.4
									ODOMETER - 16862 HOURS					
									JOB CARRIED OUT - DIAGNOSE E03 CODE. ADJUST TRAY DUMP POTENTIOMETER.					

201008-00	SVC002542	10/21/2020	1H0103	ID - EARTH1105_HBGN' R	Engine	1ME730	16839HRS	FIT UP EXHAUST AND LOWER CAB	1ME730	617.95	0	0	40	657.95
									ODOMETER - 16839 HOURS					
									JOB CARRIED OUT - COLLECT AND TEST FIT EXHAUST. REMOVE AND WRAP EXHAUST IN HEAT WRAP. RETAP ALL THREADS. FITUP EXHAUST AND TEST OPERATION. LOWER AND REMOUNT CAB.					
201015-00	SVC002543	10/21/2020	1H0103	ID - EARTH1105_HBGN' S	Service	1ME730	16850	S1A - 250HR SERVICE	1ME730	363.5	47.28	0	50	460.78
									ODOMETER - 16850 HOURS					
									JOB CARRIED OUT - CARRY OUT SERVICE. PARK BRAKE SLACK ADJUSTER HALF OFF SHAFT. INSPECT, FOUND CIRCLIP BENT AND STUCK IN ADJUSTER. REMOVE OLD CLIP, REINSTALL ADJUSTER AND INSTALL NEW CLIP. ADJUST AND TEST.					
201016-00	SVC002543	10/21/2020	1H0103	ID - EARTH1105_HBGN' R	Sundries	1ME730		RE-SEAL FRONT WINDOW	1ME730	0	290.91	0	0	290.91
									JOB CARRIED OUT - RESEAL FRONT WINDOW.					
200810-00	SVC002510	08/21/2020	1H0103	ID - EARTH1105_HBGN' R	Air Con	1ME730	16667	ASSES A/C FAULTS	1ME730	36.35	0	0	0	36.35
									ODOMETER - 16667 HOURS					
									JOB CARRIED OUT - ASSESS A/C FAULT, FURTHER INVESTIGATION NEEDED.					
200817-00	SVC002508	08/18/2020	1H0103	ID - EARTH1184_INT R	Air Con	1ME730	16,667 HRS	REPAIR A/C SYSTEM	REPAIR A/C SYSTEM, PRESSURE TEST SYSTEM AND REPAIR LEAKS, REGASSED SYSTEM AND TESTED OK	367.65	0	0	88.75	456.4
									TRAVEL NYRSTAR AND RETURN					
200708-00	SVC002488	07/14/2020	1H0103	ID - EARTH1184_INT R	Suspensior	1ME730	16650 HRS	RESEAL RIGHT REAR STRUTT	RESEAL RIGHT REAR STRUTT	1593.15	3132.76	0	75	4800.91
									REMOVE SIEZED PINS AND REMOVE RIGHT HAND REAR SUSPENSION CYLINDER. DISMANTLE CYLINDER AND CLEAN ALL PARTS,					
									POLISH ROD AND REASSEMBLE CYLINDER WITH NEW SEALS AND BUSHES.					
									CLEAN RUST FROM SUSPENSION MOUNTS AND REFIT CYLINDER WITH NEW PINS					
									REGAS CYLINDER AND CHECK HEIGHT , GREASE PINS					
									TRAVEL NYRSTAR AND RETURN TWICE					

200706-00	SVC00248	07/08/2020	1H0103	ID - EARTH	105_HBGN	R	Tyres	1ME730	CHECK TYRE PRESSURES	1ME730	0	75	0	0	75	
										JOB CARRIED OUT - B'SELECT CHECKED TYRE PRESSURES.						
200525-00	SVC00246	06/30/2020	1H0103	ID - EARTH	184_INT	R	Trays/Buck	1ME730	16650 HRS	REPAIR TRAY SAFETY LOCKS	5 lt engine supplied to G Hazell.	1143.8	54.86	0	68.75	1267.41
200611-00	SVC00247	06/26/2020	1H0103	ID - EARTH	186_INT	R	Differential	1ME730	16650 HRS	REPAIR OIL LEAK FRONT LEFT HUB	REPAIR OIL LEAK FRONT LEFT HUB MOVE MACHINE INTO WORKSHOP, JACK UP AND SUPPORT LEFT FRONT OF MACHINE. REMOVE WHEEL ASSEMBLY AND CLEAN PRODUCT FROM AROUND FINAL DRIVE TO GAIN ACCESS TO BOLTS. REMOVE FINAL DRIVE FROM MACHINE AND DISSASSEMBLE. CLEAN AND INSPECT ALL PARTS.REASSEMBLE FINAL DRIVE WITH NEW DUO SEALS AND O RINGS. FIT FINAL DRIVE TO MACHINE AND TENSION MOUNTING BOLTS TO SPECS, REFIT DRIVE SHAFT AND TENSION BOLTS, REPLACE CORRODED BRAKE FITTINGS AND FIT NEW ONES , REFIT BRAKE HOSES AND COOLING PIPES. BLEED BRAKES FIT WHEEL ASSEMBLY AND FILL FINAL DRIVE WITH OIL . TOP UP TRANSMISSION OIL CLEAN UP WORK AREA AND DISPOSE OF PRODUCT FROM AROUND FINAL DRIVE AND TAIL GATE	3707.7	4829.57	0	50	8587.27
200623-00	SVC00248	06/26/2020	1H0103	ID - EARTH	186_INT	R	Trays/Buck	1ME730	16650 HRS	RESEAL TAIL BOARD	RESEAL TAIL BOARD LIFT TRAY AND FIT SAFETY PINS, REMOVE DAMAGED TAIL BOARD SEALING RUBBER AND BENT MOUNTING PLATES. REMOVE BUILT UP PRODUCT FROM AROUND SEALING AREA AND WELD ON NEW MOUNTING PLATES, FIT NEW RUBBER SEAL.	1017.8	137.72	0	50	1205.52
200619-00	SVC00248	06/24/2020	1H0103	ID - EARTH	184_INT	R	Hydraulic	1ME730	16648 HRS	REPLACE HYD. HOSES	FABRICATE AND FIT 2 NEW HOSES	77.2	94.27	0	0	171.47

200409-00	SVC00245	06/23/2020	1H0103	ID - EARTH	182_INT	R	Sundries	1ME730	16498	FABRICATE HAND RAILS	MEASURE UP AND SET OUT LOCATION OF RAIL MOUNT ON DUMPER. BEND PIPE RAIL SECTIONS PRESS SWAGED WIRE VIB MOUNTS AND WELD TO PIPE RAIL SECTIONS. CUT AND FABRICATE BASE PLATES WITH TAPPED MOUNTING HOLES. WELD OUT RAIL. PREP AND PAINT. FIT UP COMPLETED RAILS ONSITE AT NYSTAR.	229.3	0	0	75	304.3
200525-00	SVC00246	06/09/2020	1H0103	ID - EARTH	105_HBGN	R	Sundries	1ME730		RESEAL FRONT WINDOW	JOB CARRIED OUT - WINDSCREEN SEAL LEAKING AROUND BOTTOM. CLEANED OUT SEAL, SIKAFLEXED WINDOW AND TAPED DOWN TO ALLOW FOR USE.	72.7	0	0	25	97.7
200529-00	SVC00244	06/05/2020	1H0103	ID - EARTH	105_HBGN	R	Hydraulic	1ME730	16642	REPAIR STEER CYLINDER	JOB CARRIED OUT - ASSESS HYD OIL LEAK. FOUND RH SIDE STEER CYLINDER GLAND NUT LOOSE. CLEANED UP AND TIGHTENED GLAND. TOPPED UP OIL AND TESTED OPERATION.	145.4	0	0	76	221.4
200519-00	SVC00246	05/29/2020	1H0103	ID - EARTH	182_INT	R	Lathe	1ME730	16632	MACHINE TRAY SAFETY PINS (3)	MACHINE TRAY SAFETY PINS (3) AS PER SAMPLE	218.1	119.91	0	10.5	348.51
200521-00	SVC00246	05/27/2020	1H0103	ID - EARTH	105_HBGN	R	Sundries	1ME730	16632	REPLACE WIPER BLADES	JOB CARRIED OUT - FIT NEW WIPER BLADES.	72.7	33.24	0	20	125.94
200520-00	SVC00246	05/25/2020	1H0103	ID - EARTH	121_INT	R	Tyres	1ME730	121987	FIT COP X 2	FIT COP X 2 CARRIED OUT BY B SELECT MOONHA WORK ORDER 29605	0	0	632.73	0	632.73
200501-00	SVC00246	05/22/2020	1H0103	ID - EARTH	105_HBGN	R	Sundries	1ME730		MAY - MONTHLY PMI'S	JOB CARRIED OUT - CARRY OUT PMI.	72.7	0	0	0	72.7
200518-00	SVC00246	05/22/2020	1H0103	ID - EARTH	105_HBGN	S	Service	1ME730	16551	S1B - 500HRS SERVICE	JOB CARRIED OUT - CARRY OUT SERVICE AND CHECKOVER.	508.9	445.11	0	70	1024.01
200506-00	SVC00245	05/13/2020	1H0103	ID - EARTH	121_INT	R	Tyres	1ME730	LOCKED	CHECK & ADJUST TYRE PRESSURES	CHECK & ADJUST TYRE PRESSURES CARRIED OUT BY B SELECT MOONAH	0	0	82.5	0	82.5

200406-00	SVC00245	05/07/2020	1H0103	ID - EARTH	105_HBGN	R	Sundries	1ME730	16498	APRIL - MONTHLY PMI'S	JOB CARRIED OUT - CARRY OUT PMI'S DURING APRIL.	254.45	0	0	0	254.45
200311-00	SVC00243	104/16/2020	1H0103	ID - EARTH	105_HBGN	R	Sundries	1ME730		MARCH - PMI'S	JOB CARRIED OUT - CARRY OUT PMI'S DURING MARCH. REAR STABALIZER BAR BOLTS LOOSE, LOCTITE AND TENSION BOLTS.	218.1	8.56	0	20	246.66
200128-01	SVC00242	03/18/2020	1H0103	ID - EARTH	105_HBGN	R	Sundries	1ME730	16251	FEBRUARY - PMI'S	JOB CARRIED OUT - CARRY OUT PMI. FIND AND REPAIR BREAK IN HEAD LIGHT CIRCUIT AND REVOLVING LIGHT CIRCUIT. ASSESS CONDITION.	327.15	0	385	20	732.15
200203-01	SVC00241	102/26/2020	1H0103	ID - EARTH	105_HBGN	R	Suspensior	1ME730	16317	REAR STABILISER ARM BEARING	ODOMETER - 16251 HOURS	218.1	861.98	210	40	1330.08
200203-01	SVC00241	102/19/2020	1H0103	ID - EARTH	105_HBGN	S	Service	1ME730		S1A - 250HR SERVICE	JOB CARRIED OUT - ASSESS WORN STABALISER BAR ON REAR DIFF. REMOVE BAR AND PRESSURE WASH PRODUCT OFF. REMOVE SEIZED BOLTS HOLDING BUSH IN. PRESS OUT OLD BUSH AND PRESS NEW ONE IN.	36.35	49.48	140	25	250.83
200103-00	SVC00239	01/30/2020	1H0103	ID - EARTH	105_HBGN	R	Sundries	1ME730		JANUARY - PMI'S	JOB CARRIED OUT - CARRY OUT SERVICE AND CHECKOVER.	218.1	0	0	50	268.1
191210-00	SVC00239	01/20/2020	1H0103	ID - EARTH	105_HBGN	R	Sundries	1ME730		COMPLETE DECEMBER PMI'S	JOB CARRIED OUT - CARRY OUT PMI'S DURING JANUARY. WASH OUT CORES.	109.05	0	0	30	139.05
											JOB CARRIED OUT - CARRY OUT PMI'S DURING DECEMBER. REMOVE GRILL AND WASH CORES.					

191223-00	SVC002392	01/20/2020	1H0103	ID - EARTH1105_HBGN' A	Sundries	1ME730	16250	IMPACT DAMAGE RHS MIRROR	1ME730	109.05	0	0	30	139.05
									ODOMETER - 16250 HOURS					
									JOB CARRIED OUT - IMPACT DAMAGE TO RH SIDE MIRROR. REMOVE MIRROR FROM VEHICLE. USING OXY, HEAT AND STRAIGHTEN FRAME. REINSTALL AND ADJUST.					
200108-00	SVC002392	01/20/2020	1H0103	ID - EARTH1105_HBGN' R	Electrical	1ME730	16250	REPLACE HORN ASSEMBLY	1ME730	109.05	340.63	0	30	479.68
									ODOMETER - 16250 HOURS					
									JOB CARRIED OUT - NO HORN, TEST AND INSPECT, FOUND BOTH HORNS FAILED. REMOVE COVERS AND REPALCE BOTH HORNS. DRILL AND TAP BROKEN BOLTS DUS TO BEING SEIZED.					
191031-00	SVC002354	11/27/2019	1H0103	ID - EARTH1105_HBGN' R	Sundries	1ME730	16150	NOVEMBER - PMI'S	1ME730	445.5	0	0	60	505.5
									ODOMERTER - 16150 HOURS					
									JOB CARRIED OUT - CARRY OUT PMI'S DURING NOVEMBER. SEAL UP LEAKING WINDSCREEN. WASHED CORES X3. REPLACED AIR FILTER.					
191010-00	SVC002344	11/06/2019	1H0103	ID - EARTH1105_HBGN' R	Engine	1ME730		replace cooling cores	1ME730	3084.4	11697.12	1525	50	16356.52
									ODOMETER - 16057 HOURS					
									JOB CARRIED OUT - REMOVE INTERCOOLER, COVER ALL PIPES AND HOT PRESSURE WASH CORE. REMOVE FAN SHROUD, FAN AND RADIATOR CRADLE. REMOVE CORE FROM CRADLE. PASINT NEW RADIATOR CORES AND AFTER COOLER. MODIFY RADIATOR CRADLE TO FIT NEW CORES, DUE TO BEING THICKER. SEAL UP GAP BETWEEN RADIATOR CORES. FIT NEW RADIATOR AND AFTER COOLER TO MACHINE. FILL AND BLEED COOLANT SYSTEM. DOOR LATCH STICKING, REMOVE SKIN, FREE UP LATCH AND LINKAGES. DROP RADIATORS AND INTERCOOLER TO NEW NORFOLK RADIATOR.					

191010-001	SVC002353	11/06/2019	1H0103	ID - EARTH1 105_HBGN' R	Air Con	1ME730		REPLACE A/C CONDENSOR	1ME730	181.75	595.21	175	45	996.96
									ODOMETER - 16057 HOURS					
									JOB CARRIED OUT - TEST OPERATION OF A/C, FOUND LOW ON GAS AND CONDENSOR BLOCKED. REPLACE CONDENSOR, VAC SYSTEM, REGAS AND TEST OPERATION.					
191021-001	SVC002352	11/06/2019	1H0103	ID - EARTH1 105_HBGN' S	Service	1ME730	16057	S1D - 2000HR SERVICE	1ME730	1199.55	2068.84	0	60	3328.39
									ODOMETER - 16057 HOURS					
									JOB CARRIED OUT - CARRY OUT SERVICE AND CHECKOVER.					
190925-001	SVC002337	10/30/2019	1H0103	ID - EARTH1 105_HBGN' S	Sundries	1ME730	16090	COMPLETE SEPTEMBER PMI	1ME730	290.8	49.4	210	30	580.2
									JOB CARRIED OUT - CARRY OUT PMI'S DURING OCTOBER. HOT WASH COOLING CORES. REPAIRED WIRING TO REVOLVING LIGHT. TOP UP OIL.					
191002-001	SVC002345	10/15/2019	1H0103	ID - EARTH1 105_HBGN' R	Bodywork	1ME730		FITUP SUPPLIED WINDOW LHS	1ME730	0	307.36	105	0	412.36
									JOB CARRIED OUT - FIT NEW WINDOW SEALS.					
190828-001	SVC002315	09/10/2019	1H0103	ID - EARTH1 184_INT S	Service	1ME730		S1 A SERVICE	TRAVEL TO NYRSTAR CARRIED OUT S1 A SERVICE AS PER SERVICE SHEET	416	372.25	0	43.75	832
190820-001	SVC002316	08/22/2019	1H0103	ID - EARTH1 105_HBGN' R	Sundries	1ME730		Replace Wiper Blade	1ME730	72.7	8.1	0	0	80.8
									JOB CARRIED OUT - REMOVE AND REPLACE WORN WIPER BLADE.					
190806-001	SVC002312	08/20/2019	1H0103	ID - EARTH1 182_INT R	Lathe	1ME730		MACHINE 2 TRAY SAFETY PINS	MACHINE 2 TRAY SAFETY PINS WITH RETAINING CLIPS	290.8	83.31	0	14.5	388.61
190815-001	SVC002314	08/20/2019	1H0103	ID - EARTH1 105_HBGN' R	Sundries	1ME730		6 MONTH TEST FIRE EXTINGUISHER	1ME730	36.35	0	0	0	36.35
									JOB CARRIED OUT - CARRIED OUT 6 MONTHLY TEST ON FIRE EXTINGUISHER.					
190807-001	SVC002308	08/19/2019	1H0103	ID - EARTH1 184_INT R	Sundries	1ME730		CARRY OUT REPAIRS BEFORE WORK	TRAVEL TO NYRSTAR CARRY OUT REPAIRS BEFORE WORK REPLACE REVERSE LIGHT REPAIR TAIL LIGHT WIRING REPLACE BLOWN HEADLIGHT GLOBE CHECK AIR CON SYSTEM REPAIR MOUNTING PLATES AND REPLACE TAIL GATE SEAL	612.75	65.57	0	30.5	708.82
190806-001	SVC002233	08/07/2019	1H0103	ID - EARTH1 184_INT R	Hydraulic	1ME730	15745 HRS	REPLACE BLOWN HYDRAULIC HOSES	REPLACE BLOWN HYDRAULIC HOSES, WORK CARRIED OUT BY PIRTEK AND ORGANISED BY ERNIE	0	0	1013.99	0	1013.99

190719-00	SVC002302	07/31/2019	1H0103	ID - EARTH1105_HBGN	R	Electrical	1ME730	15698HRS	DIAGNOSE HEAD LIGHT FAULT	1ME730	0	0	63.63	0	63.63
										ODOMETER - 15698 HOURS					
										JOB CARRIED OUT - DIAGNOSE FAILED HEAD LIGHT SWITCH.					
190605-00	SVC002253	07/22/2019	1H0103	ID - EARTH1121_INT	R	Tyres	1ME730		HALITRAX 23.5R25 88 HR25 L3/E3	HALITRAX 23.5R25 88 HR25 L3/E3 X 4 + ORING 25" + FOT OTR X 4 + SERVICE FEE B SELECT MOONAH 21160	0	9805.44	0	0	9805.44
190715-00	SVC002296	07/19/2019	1H0103	ID - EARTH1105_HBGN	R	Sundries	1ME730	15691	RESEAL WINDSCREEN	1ME730	72.7	0	0	30	102.7
										ODOMETER - 15691 HOURS					
										JOB CARRIED OUT - REPORTED WINDOW NOT SEALING AROUND BOTTOM. SILICONED BOTTOM OF WINDOW, UNTIL WINDOW CAN BE REMOVED AND RESEALED.					
190129-00	SVC002197	06/20/2019	1H0103	ID - EARTH1105_HBGN	R	Bodywork	1ME730		REPLACE LHS WINDOW/CAB	1ME730	0	418.65	0	0	418.65
										JOB CARRIED OUT - REPLACE LH SIDE CAB WINDOW.					
190226-00	SVC002211	06/20/2019	1H0103	ID - EARTH1105	R	Starter Motor	1ME730	15298	REPLACE U/S STARTER MOTOR	1ME730	109.05	993.7	0	0	1102.75
										JOB CARRIED OUT - REPLACE U/S STARTER MOTOR.					
190513-00	SVC002243	05/19/2019	1H0103	ID - EARTH1184_INT	S	Service	1ME730		S1 A SERVICE	TRAVELLED TO NYRSTAR CARRIED OUT THE REQUIRED SERVICE AND SAFETY INSPECTIONS AS PER SERVICE SHEET	163.4	278.44	0	20.5	462.34
190513-00	SVC002258	05/15/2019	1H0103	ID - EARTH1184_INT	R	Brake	1ME730		ADJUST PARK BRAKE	TRAVEL NYRSTAR , ADJUST PARK BRAKE AND CHECK OPERATION	122.55	0	0	12.5	135.05
190329-00	SVC002232	04/13/2019	1H0103	ID - EARTH1184_INT	R	Sundries	1ME730		CHECK OVER BEFORE WORK	CHECK OVER BEFORE WORK CHECK AND TENSION ALL WHEEL BOLTS REMOVE AND REPLACE AIR FILTER , TOP UP COOLANT AND CLEAN PRODUCT FROM AROUND BRAKE PEDAL REPLACE INNER CAB FILTERS TRAVEL NYRSTAR AND RETURN	367.65	474.13	0	12.5	854.28
190314-00	SVC002223	03/21/2019	1H0103	ID - EARTH1184_INT	S	Service	1ME730		S1 B SERVICE	S1 B SERVICE AS PER SERVICE SHEET TRAVEL NYRSTAR AND RETURN	408.5	725.18	0	32.5	1166.18
190208-00	9990	02/27/2019	1H0103	ID - EARTH1105_HBGN	R	Differential	1ME730		OPERATORATED WITH DIFF LOCKS O		72.7	0	0	0	72.7

190128-00	SVC002197	02/12/2019	1H0103	ID - EARTH1 121_INT	R	Tyres	1ME730	111073	Puncture repair	PUNCTURE REPAIR CARRIED OUT BY B SELECT MOONAH ON NYRSTAR WHARF	0	0	326.36	0	326.36
190131-00	SVC002201	02/08/2019	1H0103	ID - EARTH1 105_HBGN	R	Sundries	1ME730		REPAIR TAILGATE CHAINS	1ME730	72.7	0	0	35	107.7
190110-00	SVC002184	02/05/2019	1H0103	ID - EARTH1 184_INT	R	Brake	1ME730		REPLACE PARK BRAKE PADS	JOB CARRIED OUT - REPLACED MISSING TAIL GATE CHAIN LINKAGE. REPLACE PARK BRAKE PADS REPLACE TRAY ANGLE SENSOR AND ROD CHECK PARK BRAKE NOT WORKING AND FOUND PADS WORN OUT REMOVE AND REPLACE BRAKE PADS, ADJUST BRAKES AND TEST OPERATE. TESTED OK CHECK REPORTED BRAKE RELEASE FAULT WITH M737 WHILE ON SITE , FOUND OPERATOR TO BE PARKING UNIT AND USING RETARDER LEVER NOT PARKBRAKE SWITCH TRAVEL NYRSTAR AND RETURN	490.2	1387.37	0	18.75	1896.32
190124-00	SVC002193	01/31/2019	1H0103	ID - EARTH1 184_INT	R	Electrical	1ME730	15168 HRS	REPLACE UHF ANTENNA AND CABLE	CHECK UHF FAULT, REPLACE FAULTY ANTENNA AND LEAD. TESTED OK TRAVEL NYRSTAR	122.55	47	0	6.25	175.8
190111-00	SVC002185	01/24/2019	1H0103	ID - EARTH1 105_HBGN	R	Engine	1ME730		FAULT CODE AND ENG AIR FILTER	1ME730	181.75	49.85	0	0	231.6
190114-00	SVC002190	01/24/2019	1H0103	ID - EARTH1 184_INT	R	Sundries	1ME730		REPAIRS BEFORE WORK	JOB CARRIED OUT - VEHICLE HAS E01 MAINTENANCE CODE ON DASH. CHANGED BLOCKED AIR FILTER. CHECKED OVER MOTOR. WENT INTO DASH AND FOUND FAULT CODE FOR TRANSMISSION. AUTO ELEC TO LOOK AT VEHICLE. TRAVEL NYRSTAR AND RETURN REPAIRS BEFORE WORK CHECK FAULT CODES, FOUND BODY TILT FAULT. REPAIRED DAMAGED WIRING AND TESTED OK REPLACE DAMAGED UHF MOUNTING BRACKET CHECK TRAY DECENT FAULT, FOUND TRAY SENSOR FAULTY. REMOVE AND REPLACE SENSOR AND ADJUST TO SUIT. CHECK OVER ALL LIGHTS	546.05	10.5	0	45.75	602.3
190110-00	SVC002184	01/16/2019	1H0103	ID - EARTH1 184_INT	S	Service	1ME730	15138 HRS	S1 A SERVICE	S1 A SERVICE AS PER SERVICE SHEET TRAVEL NYRSTAR AND RETURN	297.2	301.09	0	27.5	625.79

181121-001	SVC002156	12/13/2018	1H0103	ID - EARTH1 121_INT	R	Tyres	1ME730		FIT OTR TYRE AND SEALING RING	FIT OTR TYRE AND SEALING RING AS PER JASON HAZELL CARRIED OUT BY B SELECT MOONAH WORK ORDER 16274	0	582.72	0	0	582.72
181121-001	SVC002173	12/13/2018	1H0103	ID - EARTH1 121_INT	R	Tyres	1ME730		FIT OTR TYRE AND SEALING RING	FIT OTR TYRE AND SEALING RING AS PER JASON HAZELL AEOLUS 23.5R25**185B AL37 TYRES FITTED BY B SELECT MOONAH ON INVOICE SVC00215981	0	4180	0	0	4180
180918-001	SVC002121	11/29/2018	1H0103	ID - EARTH1 182_INT	R	Sundries	1ME730		STEAM CLEAN AS REQUIRED	STEAM CLEAN AS REQUIRED	363.5	0	0	0	363.5
181105-001	SVC002156	11/27/2018	1H0103	ID - EARTH1 105_HBGN	R	Brake	1ME730	14913	ADJUST PARK BRAKE	1ME730	109.05	0	0	0	109.05
										ODOMETER - 14913 HOURS					
										JOB CARRIED OUT - DIAGNOSE REPORTED BRAKE FAULTS. COMPLETED TESTS, CHOCKED WHEELS AND ADJUSTED PARK BRAKE. TESTED OPERSATION AND DELIVERED BACK TO WHARF.					
181031-001	SVC002151	11/07/2018	1H0103	ID - EARTH1 105_HBGN	R	Sundries	1ME730	14912	COMPLETE PMI INSPECTION	1ME730	109.05	75.93	0	0	184.98
										ODOMETER - 14912 HOURS					
										JOB CARRIED OUT - CARRY OUT PMI. REMOVED FRONT GRILL AND WASHED RADIATOR CORES. REPLACED WORN OUT CABIN FILTER. TOP INTERCOOLER PIPE NEEDS REPLACING, SOFT/CRACKING. LEFT STEER TYRE WORN. RADIATOR NEEDS REMOVING TO CLEAN OFF HARD PRODUCT.					
181022-001	SVC002146	11/06/2018	1H0103	ID - EARTH1 184_INT	R	Hydraulic	1ME730	14886 HRS	RESEAL STEERING CYLINDER	PARK UNIT IN WORKSHOP AND POSITION RIGHT HAND FRONT ON JACKSTAND. REMOVE RIGHT HAND FRONT WHEEL, REMOVE RIGHT HAND STEER CYLINDER AND STRIP. CLEAN ALL PARTS AND REASSEMBLE WITH NEW SEALS AND BUSH. REFIT CYLINDER TO MACHINE AND CONNECT HOSES, REFIT WHEEL AND TENTION BOLTS, REMOVE FROM JACKSTAND AND TEST OPERATION ALL OK	805.9	530.44	0	40	1376.34

181022-00	SVC00214	11/06/2018	1H0103	ID - EARTH	184_INT	S	Service	1ME730	14886 HRS	S1 C SERVICE	CARRIED OUT S1 C SERVICE AS PER SERVICE SHEET TAKE OIL SAMPLES AND GREASE DRIVE LINE REPLACE RIGHT HAND REVOLVING LIGHT ASSEMBLY REPLACE GLOBES IN REAR WORK LIGHTS CHECK ALL TYRE PRESSURES	515.1	1380.92	0	31	1927.02
180803-00	SVC00209	09/28/2018	1H0103	ID - EARTH	184_INT	R	Suspension	1ME730	14786 HRS	REPAIR SUSPENSION STRUT	REPAIR SUSPENSION STRUT REMOVE RIGHT HAND REAR WHEEL, REMOVE STRUT AND CHANGE OVER WITH SPARE UNIT. REFIT WHEEL AND CHARGE STRUT WITH NITROGEN TRAVEL IMPACT AND RETURN	857.85	0	0	65	922.85
180831-00	SVC00211	09/10/2018	1H0103	ID - EARTH	184_INT	R	Bodywork	1ME730	14861 hrs	REFIT DOOR SEAL	TRAVELLED TO NYRSTAR, REFIT DOOR SEAL AND SECURE INTO PLACE	81.7	0	0	12.5	94.2
180828-00	SVC00210	08/29/2018	1H0103	ID - EARTH	121_INT	R	Tyres	1ME730	14842	replace worn tyre	REPLACE WORN TYRE CARRIED OUT BY B SELECT MOONAH AT NYRSTAR NOTE FRONT TYRES URGENTLY REQUIRE REPLACING	0	485.36	0	0	485.36
180810-00	SVC00210	08/14/2018	1H0103	ID - EARTH	105_HBGN	R	Brake	1ME730		INSPECT AND ADJUST HAND BRAKE	1ME730 ODOMETER - 14820 HOURS JOB CARRIED OUT - PARK BRAKE FAULT, NOT HOLDING. ADJUSTED HAND BRAKE TO SPECIFICATION AND TESTED OPERATION.	181.75	0	0	0	181.75
180813-00	SVC00209	08/13/2018	1H0103	ID - EARTH	184_INT	R	Sundries	1ME730	14823 HRS	REPLACE SEAT CONTROL SWITCH	TRAVELLED TO IMPACT FERTILISERS, REPLACED FAULTY SEAT CONTROL SWITCH.	216.9	0	0	36	252.9
180731-00	SVC00209	10/31/2018	1H0103	ID - EARTH	184_INT	R	Bodywork	1ME730	NOT PROVIDED	REPLACE FRONT SCREEN	REPLACE FRONT SCREEN CARRIED OUT BY HOBART AUTOGLASS	0	0	890.91	0	890.91
180713-00	SVC00208	07/18/2018	1H0103	ID - EARTH	184_INT	R	Bodywork	1ME730		REPAIR BATTERY BOX LID	TRAVELLED TO NYRSTAR, REMOVE BATTERY BOX LID AND FREE UP HINGES, REFIT LID AND LOCK UP BOX	122.55	0	0	12.5	135.05
180629-00	SVC00207	07/03/2018	1H0103	ID - EARTH	105_HBGN	R	Electrical	1ME730		REPLACE FAILED BATTERIES	1ME730 JOB CARRIED OUT - USE SECOND HAUL TRUCK TO JUMP START. REMOVE CORRODED BATTERY HOLD DOWN BRACKET. FITTED NEW BATTERIES TO VEHICLE. REPLACE WORN OUT BATTERY TERMINAL CONNECTOR.	399.85	395.68	0	0	795.53

180531-00	SVC00205	06/19/2018	1H0103	ID - EARTH	184_INT	R	Brake	1ME730	14652 HRS	REPLACE BRAKE COOLING PIPES ON	TRAVELLED TO NYRSTAR, CHECKED OIL LEAK CENTRE AXLE, FOUND BOTH BRAKE COOLING PIPES CORRODED AND LEAKING, REMOVE PIPES FROM 1ME648 IN WORKSHOP AND FIT TO 1ME730 TO GET UNIT BACK TO WORK, TRAVELLED BACK TO NYRSTAR, FIT NEW PIPES TO 1ME648 WHEN THEY ARRIVED FROM JAPAN	1099.03	1558.45	0	68.75	2726.23
180531-00	SVC00205	05/31/2018	1H0103	ID - EARTH	121_INT	R	Tyres	1ME730	14648	FIT OTR TYRE X 2 + O-RING X 2	FIT OTR TYRE X 2 + O-RING X 2 + TYRE ROTATION + CALL OUT TO NYRSTAR CARRIED OUT BY B SELECT SUPPLY B/STON 23.5R25 MS VLTTL DE2 SERIAL NUMBERS F7B381937 & F7B381938 POSITIONS 3&4 CARRIED OUT ON THE 29/05/2018 OUT OF HOURS TO ENSURE LOAD OUT COULD BE COMPLETED	0	6712.72	1232.6	0	7945.32
180530-00	SVC00205	05/30/2018	1H0103	ID - EARTH	121_INT	R	Sundries	1ME730		SUPPLY HD10W TRANS OIL	SUPPLY HD10W TRANS OIL PARTS ONLY	0	173.6	0	0	173.6
180516-00	SVC00204	05/22/2018	1H0103	ID - EARTH	184_INT	S	Service	1ME730	14635 HRS	S1 A SERVICE	TRAVELLED TO NYRSTAR, CARRIED OUT S1 A SERVICE AS PER SERVICE SHEET, REMOVE CLEAN AND REFIT DIFF BREATHERS	241.05	277.07	0	29.5	547.62
180413-00	SVC00203	04/17/2018	1H0103	ID - EARTH	184_INT	R	Suspensior	1ME730	14515	REPLACE SHRODER VALVE & REGAS	REPLACE SHRODER VALVE & REGAS REAR STRUT CARRIED OUT BY KOMATSU	0	0	355.07	0	355.07
180319-00	SVC00201	03/21/2018	1H0103	ID - EARTH	182_INT	R	Lathe	1ME730		REPAIRS TO DAMAGED STRUT ROD	REPAIRED DAMAGED STRUT ROD	181.49	0	0	9	190.49

180305-00\	SVC00201\	03/20/2018	1H0103	ID - EARTH1 184_INT	R	Hydraulic	1ME730	14514 HRS	RESEAL REAR STRUTT	TRAVELLED TO SITE, CHECK REAR STRUT FOR REPORTED LEAK,FOUND SEALS LEAKING. TRAVELLED BACK TO SITE, ISOLATE UNIT AND REMOVE TORQUE ROD AND BRACKET. TRY TO REMOVE PINS AND FOUND SIEZED, TRAVEL BACK TO LA WSHOP TO PICK UP STANDS , JACK AND HYDRAULIC CYLINDER. RETURN TO UNIT AND JACK UP TO PLACE ON STANDS, REMOVE LEFT HAND REAR WHEEL TO GAIN ACCESS TO PINS. PUSH LOCATING PINS OUT WITH HYDRAULIC CYLINDER AND REMOVE STRUT, STRIP STRUT AND CLEAN ALL PARTS, HAVE ROD REPAIRED AND REASSEMBLE STRUT WITH NEW SEALS. REFIT STRUT TO MACHINE AND FILL WITH OIL TO CORRECT LEVEL, REFIT TORQUE ROD AND WHEEL AND SET UNIT UP TO CORRECT HEIGHT FOR KOMATSU TO RECHARGE STRUTT WITH NITROGEN	1822.9	2494.7	0	100	4417.6
180223-00\	SVC00200\	03/13/2018	1H0103	ID - EARTH1 105_HBGN	R	Sundries	1ME730		EXHAUST REPAIRS	1ME730	2289.42	30.35	0	20	2339.77
										JOB CARRIED OUT - EXHAUST REPAIRS					
180202-00\	SVC00200\	02/27/2018	1H0103	ID - EARTH1 186_INT	R	Sundries	1ME730	14391 HRS	REPLACE BEARINGS IN LIFT CYLIN	REMOVE R/HAND LIFT CYLINDER , HAVE LINE BORED READY FOR REFIT, REFIT LIFT CYLINDER WITH NEW PIN AND SELF ALIGNING BEARING, REPLACE TOP PIN AND BEARING IN LEFT HAND CYLINDER,REPLACE FRONT AND REAR WIPER BLADES, REPLACE FIRE EXTINGUISHER	1498.36	526	0	50	2074.36
180215-00\	SVC00200\	02/21/2018	1H0103	ID - EARTH1 184_INT	R	Engine	1ME730	14402 HRS	REPLACE BROKEN FAN BELTS	TRAVELLED TO NYRSTAR, FIT NEW BELTS TO MACHINE AT NYRSTAR AND REFIT BELTS TO 1ME645	414.93	211.48	0	21	647.41
180213-00\	SVC00200\	02/14/2018	1H0103	ID - EARTH1 182_INT	R	Milling	1ME730		WELD UP CYLINDER ROD EYE	WELD UP CYLINDER ROD EYE	196.68	0	0	9.8	206.48
180214-00\	SVC00200\	02/14/2018	1H0103	ID - EARTH1 121_INT	R	Tyres	1ME730		ROTATE TYRES X 2	ROTATE TYRES CARRIED OUT BY RUBAND	0	0	140	0	140

180122-01	SVC001994	02/06/2018	1H0103	ID - EARTH	184_INT	S	Service	1ME730	14400 HRS	S1 B SERVICE	CARRIED OUT S1 B SERVICE AS PER SERVICE SHEET, REPLACED BLOWN R/HAND HEAD LIGHT GLOBE, RAISE TRAY TO GREASE MACHINE, FOUND RH TRAY LIFT CYLINDER TO HAVE COLLAPSED TOP BEARING, REQUIRES REMOVING FOR REPAIR, DIFF EXTENSION BREATHER HOSES NEED REPLACING, CRACKS IN REAR TRAYSIDES NEED WELDING AND TYRES NEED REPLACING.	405.51	429.02	0	25	859.53
180123-00	SVC001985	02/06/2018	1H0103	ID - EARTH	184_INT	R	Engine	1ME730		CLEAN RADIATOR AND COOLER CORE	CHECKED COOLERS EXTERNALLY BLOCKED, REMOVED A/C CONDENSOR AND LAYED TO SIDE, REMOVED INTERCOOLER AND FOUND LEAK, FOUND RADIATOR TO BE BADLY BLOCKED, ATTEMPT TO CLEAN OUT COOLER FINS WITH DESOLVING CHEMICAL, STILL BLOCKED, DRAINED COOLANT AND STORED FOR LATER, REMOVED RAIDTAORS, DRIVE TO NEW NORFOLK RADIATOR REPAIRS/ CLEANING, RETURN TO LA AND CONTINUE CLEAING OUT FRONT OF MACHINE FROM PRODUCT BUILD UP, REMOVED DOOR TRIM TO LUBRICATE WINDOW REGULATOR, REMOVED REAR WINDOW SCREEN GUARD AND CLEANED WINDOW, TRAVELLED BACK TO NEW NORFOLK TO PICK UP RADIATOR AND INTERCOOLER, REASSEMBLED AND REFITTED RADIATOR, FOUND MOUNTS FOR INTERCOOLER TO HAVE DAMAGED THREADS, REMOVED AND RETAP THREADS, MOUNT INTERCOOLER AND CONDENSOR, REMOUNT ENGINE FAN AND SHROUDS, REFILL COOLANT WITH STORED COOLANT, START UP UNIT AND BLEED COOLING SYSTEM, TEST ALL	2092.88	14.9	1180	175	3462.78
180131-00	SVC001994	02/06/2018	1H0103	ID - EARTH	184_INT	R	Electrical	1ME730	14400 HRS	REPLACE SIEZED STARTER MOTOR	CHECKED STARTING FAULT, FOUND STARTER MOTOR TIGHT AND SIEZING UP, REMOVE AND REPLACE FAULTY STARTER MOTOR, START UNIT AND TESTED OK	175.7	965.25	0	9	1149.95
171206-00	SVC001970	01/31/2018	1H0103	ID - EARTH	184_INT	R	Bodywork	1ME730	14400 HRS	REPLACE OPERATORS SEAT AND DOO	TRAVELLED TO NYRSTAR, REMOVED CAB DOOR, HAVE NEW HINGES WELDED TO DOOR FRAME AND REFIT DOOR TO DUMPER, TIDY UP PAINT WORK WHERE NEW HINGES FITTED, REMOVE AND REPLACE BROKEN OPERATORS SEAT.	749.84	3619.86	0	50	4419.7

171201-00	SVC00196	12/05/2017	1H0103	ID - EARTH 184_INT	R	Sundries	1ME730	13225 HRS	CHECK OVER BEFORE BOAT	TRAVELLED TO NYRSTAR, CHECKED OVER BEFORE BOAT, TOP UP ENGINE OIL	160.7	8.14	0	6.25	175.09
171128-00	SVC00196	11/29/2017	1H0103	ID - EARTH 105_HBGN	R	Sundries	1ME730		ASSESS DRIVERS SEAT	1ME730	71.35	0	0	0	71.35
										ODOMETER - 14231 HOURS					
										JOB CARRIED OUT - TEMP REPAIR OF SEAT FOR OUTLOAD. FIELD SERVICE TO FOLLOW UP WITH REPAIRS.					
171109-00	SVC00195	11/10/2017	1H0103	ID - EARTH 105_HBGN	R	Electrical	1ME730	14225 HRS	FITUP DAYTIME RUNNING LIGHTS	1ME730	178.38	0	0	20	198.38
										ODOMETER - 14225 HOURS					
										JOB CARRIED OUT - FIT UP OF DAY TIME RUNNING LIGHTS.					
171101-00	SVC00195	11/06/2017	1H0103	ID - EARTH 184_INT	R	Sundries	1ME730	14172 HRS	CHECK OPERATORS SEAT	TRAVELLED TO IMPACT, CHECKED OPERATORS SEAT AND PACK WITH RAG TO STOP BACK COLLAPSING DURING OUTLOAD	40.18	0	0	12.5	52.68
171023-00	SVC00194	10/30/2017	1H0103	ID - EARTH 184_INT	R	Sundries	1ME730	14168 HRS	CARRY OUT PMI INSPECTION AND	TRAVELLED TO NYRSTAR, CARRIED OUT PMI INSPECTION AND FIT BATTERY LOCK OUT ISOLATOR SWITCH, ADJUST PARK BRAKE AND REPLACE WIPER BLADE, CHECK AND REPAIR TAIL GATE SEALS	441.93	204.25	0	34.5	680.68
170905-00	SVC00193	10/06/2017	1H0103	ID - EARTH 105_HBGN	R	Electrical	1ME730		RH/S REV LIGHT, WIRING LH/S	TEST REVOLVING LIGHT CIRCUIT. FOUND A BROKEN POWER WIRE. REPAIR WIRE AND ORDER NEW LIGHT TO REPLACE BROKEN RH REVOLVING LIGHT.	107.03	46.75	0	0	153.78
170911-00	SVC00192	09/26/2017	1H0103	ID - EARTH 184_INT	S	Service	1ME730	14123 HRS	S1 A SERVICE	TRAVEL TO NYRSTAR CARRY OUT S1 A SERVICE AS PER SERVICE SHEET REMOVE , CLEAN AND REFIT DIFF BREATHERS REPAIR TAIL GATE SEAL REMOVE AND REPLACE DAMAGED REVOLVING LIGHT	397.26	328.07	0	37.5	762.83
170727-00	SVC00189	07/27/2017	1H0103	ID - EARTH 121_INT	R	Tyres	1ME730	13866 HOL	CALLOUT PUNCTURE REPAIR	CALLOUT PUNCTURE REPAIR CARRIED OUT BY B SELECT MOONAH WORKS ORDER 6557	0	16.36	182.7	0	199.06

170707-00\	SVC00188	07/20/2017	1H0103	ID - EARTH	184_INT	S	Service	1ME730	13924	HOL	S1 D SERVICE	S1 D SERVICE AS PER SERVICE SHEET REMOVE AND REPLACE ALL DIFF BREATHERS, REMOVE TRANSMISSION SCREEN , CHECK FOR COMTAMINATION , CLEAN AND REFIT ADJUST PARK BRAKE AND TEST OPERATION TRAVEL NYRSTAR AND RETURN. NOTE**** WENT TO NYRSTAR TO SERVICE THIS UNIT ON 11/07/17 BUT TOLD NOT AVAILABLE BECAUSE OF WORK COMITMENTS	892.48	2140.73	0	65	3098.21
170630-00\	SVC00188	07/11/2017	1H0103	ID - EARTH	184_INT	R	Bodywork	1ME730	13866	HRS	CHECK STIFF DOOR HINGES	CHECK STIFF DOOR HINGES, LUBRICATE AND FREE UP TRAVEL NYRSTAR	80.35	0	0	6.25	86.6
170616-00\	SVC00187	06/19/2017	1H0103	ID - EARTH	121_INT	R	Tyres	1ME730			CALLOUT PUNCTURE REPAIR	CALLOUT PUNCTURE REPAIR REPLACE TUBLESS VALVE CARRIED OUT BY RUBAND	0	0	86.5	0	86.5
170619-00\	SVC00187	06/19/2017	1H0103	ID - EARTH	184_INT	R	Trays/Buck	1ME730	13811	HRS	PUMP UP FRONT TYRE REPAIR WO	14/6/17 TRAVELLED TO SITE, CHECKED OVER UNIT BEFORE WORK 15/6/17 TRAVELLED BACK TO SITE, PUMPED UP LHF TYRE 18/6/17 TRAVELLED BACK TO SITE, PUMPED UP LHF TYRE, REPAIRED WORK LIGHT WIRING	455.26	9.14	0	48	512.4
170329-00\	SVC00184	106/15/2017	1H0103	ID - EARTH	105_HBGN	R	Tyres	1ME730	13602		CHECK & ADJUST TYRE PRESSURES	ARRANGE FOR B SELECT TO CHECK AND INFLATE TYRES. LH/F LOW.	0	0	60	0	60
170606-00\	SVC00187	06/08/2017	1H0103	ID - EARTH	121_INT	R	Tyres	1ME730			CALL OUT TO REPAIR PUNCTURE	CALL OUT TO REPAIR PUNCTURE ON LHF OF UNIT M730 AT NYRSTAR CARRIED OUT BY B SELECT WORK ORDER 6008	0	182.7	0	0	182.7
170601-00\	SVC00187	106/06/2017	1H0103	ID - EARTH	184_INT	R	Sundries	1ME730	13768	HRS	CHECK OVER BEFORE WORK	TRAVEL TO NYRSTAR, CHECK OVER UNIT BEFORE GOING TO WORK AND REPAIRED TAIL GATE RUBBER BRACKET AS REQUIRED.	120.53	0	0	18.5	139.03
170517-00\	SVC00186	05/23/2017	1H0103	ID - EARTH	184_INT	R	Trays/Buck	1ME730	13745	HRS	REPLACE TAIL GATE RUBBER	REMOVED AND REPLACED DAMAGED TAIL GATE SEALING RUBBER. REPLACED DAMAGED HOLD DOWN BOLTS	243.93	0	0	12	255.93
170411-00\	SVC00184	05/09/2017	1H0103	ID - EARTH	184_INT	R	Electrical	1ME730	13692	HRS	REPLACE REVOLVING LIGHT	PARTS ONLY TO SUPPLY NEW REVOLVING LIGHT AND SUPPLY OPERATOR CAN OF BRAKE CLEAN	0	81.64	0	0	81.64
170427-00\	SVC00185	05/03/2017	1H0103	ID - EARTH	184_INT	R	Bodywork	1ME730	13709	HRS	REPLACE WINDOW REGULATOR	TRAVEL TO HBMI , REMOVE AND REPLACE FAULTY WINDOW REGULATOR ASSEMBLY AND CHECK OPERATION. TESTED OK RETURN LA	160.7	706.23	0	83	949.93
170405-00\	SVC00184	04/18/2017	1H0103	ID - EARTH	184_INT	S	Service	1ME730	13674	HRS	S1 A SERVICE	CARRIED OUT S1 A SERVICE AS PER SERVICE SHEET	324.28	271.66	0	21	616.94
170405-00\	SVC00184	04/11/2017	1H0103	ID - EARTH	184_INT	R	Air Con	1ME730			CHANGE AIRCON FILTERS	CHANGE AIRCON FILTERS AS REQUESTED	43.05	276.6	0	0	319.65

170321-00	SVC00183	03/28/2017	1H0103	ID - EARTH184_INT	R	Sundries	1ME730	13569 hrs	PMI INSPECTION BEFORE WORK	TRAVELLED TO NYRSTAR, CARRIED OUT PMI INSPECTION BEFORE UNIT GOES TO WORK, FOUND WIPER MOTOR SIEZED AND DOOR HINGES SEIZING UP, LUBRICATED DOOR HINGES BUT STILL HARD TO SHUT DOOR, REPLACED WIPER BLADE	200.88	37.86	0	12.5	251.24
170322-00	SVC00183	03/28/2017	1H0103	ID - EARTH184_INT	R	Electrical	1ME730	13569 hrs	REPLACE FAULTY WIPER MOTOR	TRAVELLED TO NYRSTAR REMOVE SIEZED WIPER MOTOR AND FIT NEW WIPER MOTOR	200.88	734.59	0	22.5	957.97
170207-00	SVC00181	02/28/2017	1H0103	ID - EARTH105	R	Brake	1ME730	13490	FAILED BRAKE LINE LH/CENTRE	1ME730	209.86	0	133.33	0	343.19
										ODOMETER - 13490 HOURS					
										JOB CARRIED OUT - FIND LEAKING HOSE, WASH AREA OFF. REMOVE FAILED COPPER HOSE AND INSTALL HYD HOSE SUPPLIED BY ENZED.					
170227-00	SVC00182	02/27/2017	1H0103	ID - EARTH184_INT	R	Tyres	1ME730	13550 HRS	PUMP UP L/HAND FRONT TYRE	PUMP UP L/HAND FRONT TYRE AND CHECK FOR LEAKS	80.35	0	0	25	105.35
170206-00	SVC00181	02/22/2017	1H0103	ID - EARTH105	R	Air Con	1ME730	13481	DIAGNOSE/ASSESS AC OPERATION	TRAVEL NYRSTAR AND RETURN	174.88	0	0	0	174.88
										ODOMETER - 13481 HOURS					
										JOB CARRIED OUT - TEST A/C, FOUND AND REPAIRE A BROKEN WIRE IN PRESSURE SWITCH CIRCUIT.					
170131-00	SVC00181	02/14/2017	1H0103	ID - EARTH184_INT	R	Sundries	1ME730	13486	REPLACE FAULTY A/C COMPRESSOR	TRAVELLED TO NYRSTAR, CHECKED REPORTED AC NOT WORKING BUT TEST OK AT TIME OF INSPECTION, COMPLETE CHECK OVER OF VEHICLE PRIOR TO OUTLOAD BOAT, REPLACED RHR WORK LIGHT GLOBE, CLEANED FILTERS, CHECKED AC NOT WORKING AGAIN, COMPLETE TEST AND FOUND COMPRESSOR GETTING SIGNAL BUT NOT SWITCHING ON, REMOVE AND REPLACED AC COMPRESSOR , REAPLCED RECEIVER DRYER AND RECHARGED SYSTEM ALL OK	694.48	593.25	0	102.5	1390.23
161219-00	SVC00179	01/25/2017	1H0103	ID - EARTH184_INT	S	Service	1ME730	13447 HRS	S1 B SERVICE	TRAVELLED TO NYRSTAR, CARRIED OUT S1 B SERVICE AS PER SERVICE SHEET	426.16	656.51	0	39	1121.67

170111-00\	SVC001806	01/24/2017	1H0103	ID - EARTH184_INT	R	Air Con	1ME730	13477 HRS	REPAIR AIR CON FAULTS	TRAVELLED TO NYRSTAR, CHECKED AIR CON SYSTEM AND FOUND GAS TO BE LOW AND TX VALVE FAULTY, DISMANTLED SYSTEM AND REMOVED FAULTY PARTS, SOURCED NEW PARTS. TRAVELLED BACK TO SITE, FIT NEW PARTS , REPLACED OUT CAB FILTER AND FILLED UNIT WITH GAS, TEST OK	327.15	417.66	0	133.5	878.31
170111-00\	SVC001803	01/17/2017	1H0103	ID - EARTH105_HBGN	A	Bodywork	1ME730	13477 HRS	Replace broken mirror	REPLACE MISSING RH MIRROR ASSY, MODIFIED BRACKET TO SUIT, CHARGE TO TRANSPORT AS PER WAYNE GOSS	80.35	213.49	0	0	293.84
170109-00\	SVC001800	01/13/2017	1H0103	ID - EARTH105_HBGN	R	Air Con	1ME730		DIAGNOSE A/C FAULTS TX VALVE	JOB CARRIED OUT - DIAGNOSE A/C FAULTS, FOUND TO BE FAULTY TX VALVE.	139.9	0	0	0	139.9
161121-00\	SVC001778	12/06/2016	1H0103	ID - EARTH184_INT	R	Sundries	1ME730	13279	PRE INLOAD / OUTLOAD INSPECTIO	TRAVELLED TO NYRSTAR, CHECKED UNIT OVER BEFORE WORK, BLOW OUT ALL FILTERS, CHECK AIR CON WORKING PROPERLY, REPAIRED WORN WIRES IN ARTICULATION POINTS, REMOVED AND REPLACED FAULTY BATTERY ISOLATORS	522.29	432.12	0	51	1005.41
161115-00\	SVC001775	11/15/2016	1H0103	ID - EARTH184_INT	R	Trays/Buck	1ME730	13235 HRS	CHECK TAIL GATE SEAL	TRAVEL IMPACT FERTILISERS AND CHECK TAIL GATE SEAL (SEAL OK) AND CHECK OIL LEVELS	64.58	0	0	0	64.58
161104-00\	SVC001770	11/09/2016	1H0103	ID - EARTH105_HBGN	R	Hydraulic	1ME730		FAILED BRAKE HYD HOSE	JOB CARRIED OUT - DIAGNOSE HYD LEAK. FAILED ARTIC BRAKE HOSE. SOURCE PARTS ENZED, REMOVE AND FIT UP NEW HOSE.	349.75	0	618.78	0	968.53
160928-00\	SVC001749	10/26/2016	1H0103	ID - EARTH184_INT	R	Electrical	1ME730	13178 HRS	REPAIR UHF COAX & EXHAUST LEAK	REPLACE PLUG ON UHF COAXIAL CABLE, LIFT CAB TO GAIN ACCESS TO EXHAUST PIPES, REMOVE AND REPLACE EXHAUST FLEX PIPE NEAR MUFFLER, WRAP EXHAUST TUBE IN LAGGING AND REFIT COVERS, REPAIRED SIEZED BONNET LATCH, LOCATE LEAK IN A/CON SYSTEM, REMOVE AND REPLACE CHARGE VALVE AND RECIEVER DRYER, RECHARGE SYSTEM	2420.62	283.61	0	50	2754.23
161018-00\	SVC001761	10/21/2016	1H0103	ID - EARTH121_INT	R	Tyres	1ME730		FIT 6 23.5R25 TYRES + O-RINGS	FIT COP X 6 PLUS O-RINGS X 6 CARRIED OUT BY RUBAND	0	90	480	0	570
161004-00\	SVC001757	10/12/2016	1H0103	ID - EARTH186_INT	S	Service	1ME730	13183 HRS	S1 A SERVICE	CARRIED OUT S1 A SERVICE AS PER SERVICE SHEET	209.85	239.1	0	15.5	464.45
160720-00\	SVC001713	09/06/2016	1H0103	ID - EARTH121_INT	R	Tyres	1ME730		6 X XHA2 23.5 X HM300 TYRES	SUPPLY XHA2 23.5 X 5 HM300 TYRES X 6 PLUS DELIVERY	0	14853.8	0	0	14853.8

160715-00\	SVC00171\	07/29/2016	1H0103	ID - EARTH\ 186_INT	R	Sundries	1ME730		CHECK UNIT OVER BEFORE WORK	CHECK UNIT OVER BEFORE WORK CLEAN RADIATOR AFTER COOLER AND CONDENSOR CORES PRESSURE WASH UNIT AND PARK IN WORKSHOP CLEAN AIR CON AND ENGINE AIR FILTERS CHECK ALL FLUID LEVELS FABRICATE NEW CHAINS FOR TRAY SAFETY LOCK PINS FIT NEW HYDRAULIC BREATHER REPLACE WIPER MOTOR AND WASHER PUMP REPLACE HEAD LIGHT INSERTS REPLACE STROBE LIGHT AND REVERSE ALARM GREASE UNIT AND PARK IN BACK YARD	1488.93	1739.3	0	50	3278.23
160711-00\	SVC00171\	07/21/2016	1H0103	ID - EARTH\ 105_HBGN	R	Brake	1ME730		FAILED RHSF HYD HOSE (BRAKES)	1ME730 JOB CARRIED OUT - HYDRAULIC LEAK FROM STEEL BRAKE PIPE ON RH FRONT DRIVE AXLE. FITTED FLEX HOSE, MADE UP FROM ENZED.	102.38	0	175.9	0	278.28
160617-00\	SVC00169\	06/28/2016	1H0103	ID - EARTH\ 105_HBGN	R	Tyres	1ME730		REPLACE & TENSION WHEEL STUDS	1ME730 JOB CARRIED OUT - INSPECT MISSING WHEEL STUDS. FIT NEW WHEEL BOLTS AND TENSION ALL.	170.64	214.3	0	0	384.94
160623-00\	SVC00169\	06/24/2016	1H0103	ID - EARTH\ 105_HBGN	R	Electrical	1ME730		REPAIR FLASHING LIGHT WIRES	1ME730 JOB CARRIED OUT - REPAIR CORRODED WIRES TO FLASHING LIGHT. CHECK AM/FM RADIO AERIAL, AERIAL BROKEN OFF BASE.	68.25	0	0	0	68.25
160531-00\	SVC00169\	06/06/2016	1H0103	ID - EARTH\ 184_INT	R	Electrical	1ME730	12979 HR	repair head lights	TRAVELLED TO NYRSTAR, CHECK REPORTED LIGHT FAULT AND FOUND TO BE OK, CHECKED CODES AND FOUND ACTIVE CODE DK54KX BODY POSITION SENSOR OUTSIDE RANGE, REQUIRED SERVICE BOOK TO DIAGNOSE, TRAVELLED BACK TO SITE, CARRIED OUT TESTES ON CIRCUIT, FOUND SENSOR TO BE OUT OF ADJUSTMENT, READJUSTED TO SPECS AND TEST OK, REPAIRED WIRING UNDER TRAY TO PARK LIGHT CIRCUIT DUE TO CORROSION.	476.18	0	0	29.5	505.68
160530-00\	SVC00168\	05/31/2016	1H0103	ID - EARTH\ 105_HBGN	R	Tyres	1ME730		LOOSE WHEEL STUDS-TENSION ALL	1ME730 JOB CARRIED OUT - TIGHTENED ALL WHEEL BOLTS.	68.25	0	0	0	68.25

160526-00	SVC001686	05/27/2016	1H0103	ID - EARTH1 184_INT	R	Differential	1ME730		CHECK REAR AXLE FOR WEAR AS	CHECK REAR AXLE FOR WEAR AS REQUESTED BY CAPPO AFTER BAD SAMPLE FRONT AXLE 5MM MIDDLE AXLE 0MM REAR AXLE 0MM	78.75	0	0	0	78.75
160516-01	SVC001683	05/24/2016	1H0103	ID - EARTH1 184_INT	S	Service	1ME730	12941 HR	S1 C SERVICE	TRAVELLED TO IMPACT, CARRIED OUT S1 C SERVICE AS PER SCHEDULE. UNBLOCKED WINDSCREEN WASHER NOZZLE.	676.73	1463.17	0	45	2184.9
160510-00	SVC001678	05/17/2016	1H0103	ID - EARTH1 184_INT	R	Sundries	1ME730	12850	PRE INLOAD INSPECTION	TRAVELLED TO NYRSTAR, CHECKED OVER MACHINE BEFORE INLOAD, REPLACED PRIMARY AIR FILTER AND LHR CAB LIGHT GLOBE, TEST OPERATION OK	78.75	65.66	0	11	155.41
160419-00	SVC001666	05/03/2016	1H0103	ID - EARTH1 184_INT	R	Electrical	1ME730	12420	REPLACE TX VALVE & UHF AERIAL	TRAVELLED TO NYRSTAR. REPLACED TX VALVE AND REGAS AC, TESTED OK, REPLACED UHF AERIAL	393.75	30	0	58	481.75
160329-00	SVC001657	04/04/2016	1H0103	ID - EARTH1 121_INT	R	Tyres	1ME730		FIT COP + O-RINGS	FIT COP + O-RINGS x 3	0	165	0	0	165
160122-00	SVC001624	03/29/2016	1H0103	ID - EARTH1 184_INT	R	Air Con	1ME730	12420 HR	REPAIR AIR CON FAULT	TRAVEL TO IMPACT AND CHECK AIR CON PRESSURES FOUND LOW TOP UP GAS AND RECHECK FOUND CONDENSOR CORE BLOCKED RESTRICTING AIR FLOW CLEANED CORE REPLACED FILTERS AND TX VALVE, RECHECKED OK RETURN TO LA	1446.38	466.76	0	25	1938.14
160324-00	SVC001626	03/29/2016	1H0103	ID - EARTH1 184_INT	R	Sundries	1ME730	12707	REPAIR HEATER FAULT & PRE INLO	TRAVELLED TO NYRSTAR. UNDONE HEATER TAP AND CHECKED OPERATION. CHECKED TAIL GATE SEAL ETC. CHECKED FOR EOI FAULT ETC BUT COULD NOT FAULT AT TIME OF INSPECTION.	157.5	0	0	11	168.5
160316-00	SVC001650	03/23/2016	1H0103	ID - EARTH1 184_INT	S	Service	1ME730	12655	S1 A SERVICE	TRAVELLED TO NYRSTAR. CARRIED OUT S1 A SERVICE AS PER SERVICE SHEET. CHECKED OVER AND CHASED UP FAULT CODES. REPAIRED REVOLVING LIGHT/REPLACE FLASH TUBE (GLOBE)	275.63	294.63	0	30.5	600.76
151106-00	SVC001598	03/18/2016	1H0103	ID - EARTH1 105_HBGN	R	Sundries	1ME730	NA	SUPPLY IGN KEY	1ME730 JOB CARRIED OUT - SUPPLY IGNITION KEY.	0	7.46	0	0	7.46
160229-00	SVC001642	03/07/2016	1H0103	ID - EARTH1 105	R	Electrical	1ME730		CHECK AND DIAGNOSE FAULT CODE	1ME730 JOB CARRIED OUT - CHECK FAULT CODES. TRAY UP POTENTIOMETER OUT OF SPEC. RESET AND CLEAR FAULT CODES.	342.83	0	0	0	342.83

160212-00	SVC00164	02/26/2016	1H0103	ID - EARTH	105_HBGN	R	Electrical	1ME730		DIAGNOSE FAULT CODE FAULTS	1ME7360	34.13	0	0	0	34.13
											JOB CARRIED OUT - DIAGNOSE FAULT CODE FAULT.					
160127-00	SVC00162	01/31/2016	1H0103	ID - EARTH	105	R	Sundries	1ME730		DELIVER HM300'S IMPACT FERT	1ME730	204.75	0	0	0	204.75
											JOB CARRIED OUT - DELIVE X3 HM300'S TO IMPACT AND NYRSTAR, AS PER ERNIE BRUSCH, READY FOR SHIPPING.					
160127-00	SVC00162	01/31/2016	1H0103	ID - EARTH	105_HBGN	R	Air Con	1ME730		CALL OUT - A/C FAULTS	1ME730	157.5	0	0	0	157.5
											JOB CARRIED OUT - DIAGNOSE A/C FAULTS. HOT WASH BLOCKED CONDENSOR.					
160112-00	SVC00161	01/28/2016	1H0103	ID - EARTH	184_INT	S	Service	1ME730	12360	S1 B SERVICE	TRAVELLED TO NYRSTAR, WAITED AN HOUR FOR DUMPER TO BECOME AVAILABLE, CARRIED OUT S1 B SERVICE AS PER SERVICE SHEET, ADJUST BELTS, FIT GRIP TAPE TO STEPS	511.88	670.15	0	43.7	1225.73
151209-00	SVC00161	12/30/2015	1H0103	ID - EARTH	105_HBGN	R	Electrical	1ME730		REPAIR HEAD LIGHT FAULTS	1ME730	477.75	0	0	0	477.75
											JOB CARRIED OUT - FIND AND REPAIR BROKEN WIRE FOR LOW BEAM IN HARNESS. REPALCE BLOWN GLOBES. TEST AND REPLACE FAULTY FLASHING LIGHT.					
151228-00	SVC00161	12/30/2015	1H0103	ID - EARTH	105_HBGN	R	Engine	1ME730		REPORTED OVERHEATING FAULTS	1ME730	102.38	0	0	0	102.38
											JOB CARRIED OUT - DIAGNOSE MACHINE HEAT FAULTS. HOT WASH COOLING CORES.					
151209-00	SVC00160	12/15/2015	1H0103	ID - EARTH	105_HBGN	R	Hydraulic	1ME730		LOW HYD OIL	1ME737	68.25	56.52	0	0	124.77
											JOB CARRIED OUT - COMPLETE PMI, ADD HYD OIL DUE TO LEVEL BEING LOW.					
151001-00	SVC00157	10/07/2015	1H0103	ID - EARTH	184_INT	R	Sundries	1ME730	11982	PRE OUTLOAD INSPECTION	TRAVEL TO NYRSTAR CHECK OVER UNIT, TOP UP COOLANT	39.38	0	0	5.5	44.88
150930-00	SVC00157	09/30/2015	1H0103	ID - EARTH	105	R	Sundries	1ME730	11982	PMI - CLEAN WINDOWS	1ME730	34.13	0	0	0	34.13
											ODOMETER - 11982 HOURS					
											JOB CARRIED OUT - PMI - CLEANED SUPER PHOSPHATE OFF WINDOWS.					
150805-00	SVC00154	09/11/2015	1H0103	ID - EARTH	105	R	Electrical	1ME730		INSTALL LED FLASHING LIGHT	1ME730	102.38	118.31	0	0	220.69
											JOB CARRIED OUT - FIT NEW LED REVOLVING LIGHT.					

150901-00	SVC00156	09/10/2015	1H0103	ID - EARTH	184_INT	R	Electrical	1ME730	11979	REPLACE WORKLIGHTS & BONNET	REPLACE WORKLIGHTS & BONNET CATCH	196.88	388.05	0	10	594.93
150825-00	SVC00155	09/08/2015	1H0103	ID - EARTH	184_INT	S	Service	1ME730	11979	S1 D SERVICE	COMPLETED THE REQUIRED SERVICE AND SAFETY CHECKS AS PER SERVICE SCHEDULE	1869	2304.85	0	55	4228.85
150831-00	SVC00155	08/31/2015	1H0103	ID - EARTH	184_INT	R	Brake	1ME730	11961	ADJUST PARK BRAKE	CHECK AND CLEAR FAULT CODES TRAVELED TO IMPACT FERTILIZERS TO ADJUST LOOSE PARK BRAKE	78.75	0	0	11	89.75
150820-00	SVC00155	08/27/2015	1H0103	ID - EARTH	105_HBGN	R	Sundries	1ME730	11914HR	COMPLETE PMI'S	1ME730	73.51	0	0	0	73.51
											ODOMETER - 11715 HOURS					
											JOB CARRIED OUT - COMPLETE PMI TO UNIT.					
150805-00	SVC00154	08/12/2015	1H0103	ID - EARTH	105	R	Sundries	1ME730		PRESSURE CLEAN RADIATOR & PMI	1ME730	307.13	0	0	0	307.13
											JOB CARRIED OUT - PMI INSPECTION, STEAM CLEAN RADIATOR CORES. GREASE MACHINE. CHECK ALL FUNCTIONS.					
150807-00	SVC00154	08/12/2015	1H0103	ID - EARTH	105_HBGN	R	Sundries	1ME730		REPLACE FAILED TAILGATE RUBBER	1ME730	170.63	0	0	0	170.63
											JOB CARRIED OUT - REMOVED AND REPAIRED TAILGATE RUBBER INSIDE STRIP.					
150528-00	SVC00151	05/29/2015	1H0103	ID - EARTH	121_INT	R	Tyres	1ME730		Puncture repair	PUNCTURE REPAIR CALLOUT RUBAND 1 O- 0 RING + VALVE + CALLOUT FEE	31.5	180	0		211.5
150518-00	SVC00150	05/27/2015	1H0103	ID - EARTH	105_HBGN	R	Trays/Buck	1ME730	11724	CALL OUT - BROKEN TAILGATE PIN	CALALOUT TO REPAIR BROKEN TAILGATE, FABRICATE NEW PINS AND FIT TO TAILGATE STRAIGHTENING BRACKS, TEST OPERATION ALL GOOD.	1176.01	0	0	0	1176.01
150518-00	SVC00150	05/22/2015	1H0103	ID - EARTH	105	R	Electrical	1ME730	11715	WORK LIGHTS NOT WORKING	1ME730	68.25	0	0	0	68.25
											ODOMETER - 11715 HOURS					
											JOB CARRIED OUT - REPAIR BLOWN WORK LIGHTS.					
150518-00	SVC00150	05/22/2015	1H0103	ID - EARTH	105_HBGN	R	Tyres	1ME730	11715	FLATE TYRE - PUMP UP	1ME730	68.25	0	0	0	68.25
											ODOMETER - 11715 HOURS					
											JOB CARRIED OUT - INFLATE FLAT TYRES.					
150514-00	SVC00150	05/21/2015	1H0103	ID - EARTH	184_INT	R	Trays/Buck	1ME730	11714 HR	REMOVE & REPAIR TAILGATE	REMOVED TAILGATE, REMOVED DAMAGED SEAL FLAT BAR, FABRICATE NEW MOUNT AND FIT, FIT NEW RUBBER, REFIT TAILGATE	1485.23	38.2	0	50	1573.43
150514-00	SVC00150	05/19/2015	1H0103	ID - EARTH	186_INT	S	Service	1ME730	11715 HR	S1 A SERVICE	CARRIED OUT S1 A SERVICE AS PER SHEET, REPLACE FAULTY GREASE NIPPLES AND CLEAN SUPER FROM REAR CAB WINDOW AS REQUESTED	279.31	262.55	0	19	560.86

150515-00	SVC001504	05/19/2015	1H0103	ID - EARTH	186_INT	R	Hydraulic	1ME730	11715 HR	REPAIR OIL LEAK NEAR HYD TANK	LOW OIL LEVEL IN TANK, REMOVE PANEL TO GAIN ACCESS TO BACK OF TANK, REMOVE HYD MANIFOLD AND REPLACE SEALING GASKETS, REFIT PANELS, FILL WITH OIL AND RUN TO CHECK FOR LEAKS, TESTED OK	341.25	125.32	0	17	483.57
150408-00	SVC001485	04/20/2015	1H0103	ID - EARTH	184_INT	R	Hydraulic	1ME730	11670	CHECK REPORTED OIL LEAK	TRAVELLED TO NYRSTAR, INSPECT REPORTED HYD OIL LEAK, REMOVED PANELS NEAR TANK TO FIND LEAK, FLOAT TRUCK TO LA W/SHOP, LIFT CAB DRAIN HYD TANK, REMOVED AND REPLACED LEAKING O RING COUPLINGS, REFILLED HYD OIL AND TEST, LOWER CAB, GREASE MACHINE, CHECKED LIGHTS AND ALL FLUIDS ETC	630	384.55	0	48	1062.55
150331-00	SVC001481	04/02/2015	1H0103	ID - EARTH	184_INT	R	Brake	1ME730	11664	REPAIR LEAKING BRAKE PRESSURE	TRAVELLED TO NYRSTAR, REMOVED LEAKING BRAKE PRESSURE TUBE TO RHS CENTER AXLE, REPAIRED TUBE AND REFIT TO UNIT, TEST OPERATION ALL OK	282.98	0	0	25	307.98
150318-00	SVC001472	03/24/2015	1H0103	ID - EARTH	184_INT	R	Air Con	1ME730	11600	CLEAN CONDENSOR & EVAPORATOR	TRAVELLED TO IMPACT, CHECKED AIR CON AND CLEANED OUT EVAPORATOR, CLEANED OUT CONDENSOR AND CHECKED OPERATION	433.13	0	0	38	471.13
150310-00	SVC001468	03/17/2015	1H0103	ID - EARTH	186_INT	R	Air Con	1ME730	11488 HR	SERVICE & REPAIR AIR CON SYSTE	SERVICE & REPAIR AIR CON SYSTEM, REPLACE TX VALVE & RECEIVER DRYER TRAVEL IMPACT FERTILIZERS AND CHECK AIR CON SYSTEM FOUND TO NOT BE OPERATING PROPERLY REMOVE OPERATORS SEAT REMOVE AND REPLACE TX VALVE EVAC AND RECHARGE SYSTEM REPLACE SEAT AND CAB FILTERS REPAIR CAB AIR VENTS TEST RUN AND CHECK OUTPUT AT VENTS TEMP WAS 6 DEGREES	341.25	474.25	0	64.25	879.75
150310-00	SVC001468	03/16/2015	1H0103	ID - EARTH	184_INT	S	Service	1ME730	11487	S1 B SERVICE	TRAVELLED TO IMPACT, CARRIED OUT S1 B SERVICE AS PER SCHEDULE	322.35	716.81	0	30.5	1069.66
150306-00	SVC001467	03/12/2015	1H0103	ID - EARTH	184_INT	R	Sundries	1ME730	11458	PRE IMPACT INLOAD INSPECTION	TRAVELLED TO IMPACT, CHECKED TAILGATE SEAL, GREASED MACHINE, TOP UP FLUIDS AND CLEANED OUT AIR FILTERS	236.25	55.98	0	23	315.23
150218-00	SVC001463	03/04/2015	1H0103	ID - EARTH	121_INT	R	Tyres	1ME730		SUPPLY AEOLUS TYRES X 6 23.5/2	SUPPLY AEOLUS TYRES X 6 23.5/2 RUBAND TYRES AS PER PAUL KELLEHER 18/2/15	0	13050	0	0	13050

150114-00	SVC001447	01/30/2015	1H0103	ID - EARTH	186_INT	R	Sundries	1ME730	11404 HR	REPLACE TAIL LIGHT ASSY REPAI	REPLACE TAIL LIGHT ASSY REPAIR BONNET CATCH GENERAL CHECK OVER BEFORE WORK CUT HOLE IN BONNET TO RELEASE CATCH REMOVE AND REPAIR LATCH REFIT AND ADJUST LOCK MAKE COVER PLATE AND FIT OVER HOLE REMOVE AND REPLACE RIGHT REAR TAIL LIGHT ASSY REPLACE RUBBER CUSHIONS ON REAR LIGHT BRACKET REPAIR WORK LIGHT	887.26	192.8	0	42	1122.06
150121-00	SVC001443	01/21/2015	1H0103	ID - EARTH	105_HBGN	R	Air Con	1ME730	11417	AIR CON FAULTS	1ME730	273	18	0	0	291
											ODOMETER - 11417 HOURS					
											JOB CARRIED OUT - TEST A/C. FOUND TO BE LOW IN GAS. DEGAS SYSTEM, VACUUM TEST AND REGAS.					
150109-00	SVC001437	01/16/2015	1H0103	ID - EARTH	184_INT	R	Bodywork	1ME730		REPAIR BONNET NOT OPENING FAUL	TRAVELLED TO SPRING HILL, INSPECTED BONNET LATCH AND REPAIR SO BONNET WOULD OPEN	157.5	0	0	52	209.5
141219-00	SVC001431	12/19/2014	1H0103	ID - EARTH	184_INT	R	Tyres	1ME730	11386	PUMP UP REAR TYRES	TRAVEL TO DAM SITE, PUMP UP 4 REAR TYRES, INSPECT BONNET LATCH NOT WORKING	78.75	0	0	22	100.75
141215-00	SVC001428	12/17/2014	1H0103	ID - EARTH	184_INT	R	Tyres	1ME730	11372	CHECK & ADJUST TYRE PRESSURES	TRAVELLED TO PIPELINE, PUMP UP TYRES	78.75	0	0	44	122.75
141201-00	SVC001420	12/02/2014	1H0103	ID - EARTH	186_INT	R	Engine	1ME730	11327 HR	FINISH ENGINE REPAIRS	FINISH ENGINE REPAIRS	392.44	0	0	0	392.44
141126-00	SVC001417	11/28/2014	1H0103	ID - EARTH	186_INT	R	Engine	1ME730	11327 HR	CHECK ENGINE MISSFIRE UNDER LO	CHECK ENGINE MISSFIRE UNDER LOAD CHECK FUEL LINES BETWEEN TANK AND LIFT PUMP FOR RESTRCTION REPLACE PRIMARY FUEL FILTER REPLACE AIR CLEANER AND CLEAN PRE CLEANER CHECK TURBO BOOST AND FUEL PRESSURE	255.94	188.75	0	12.5	457.19
141103-01	SVC001409	11/12/2014	1H0103	ID - EARTH	184_INT	R	Trays/Buck	1ME730	11222	REPLACE TAILGATE RUBBER & TURB	TRAVEL TO NYRSTAR, REMOVED TAILGATE SEAL, CLEAN ALL PARTS, REPLACED STRIPPED NUTS, REFIT NEW SEAL, GREASE MACHIEN AND INSPECT ALL FLUIDS ETC, REPLACED TURBO HOSE AS REQUIRED.	708.75	589.55	0	40.5	1338.8
141104-00	SVC001405	11/12/2014	1H0103	ID - EARTH	184_INT	S	Service	1ME730		S1 A SERVICE	TRAVEL TO NYRSTAR, CARRIED OUT S1 A SERVICE AS PER SCHEDULE	236.25	259.94	0	28.7	524.89

141017-00\	SVC001396	10/31/2014	1H0103	ID - EARTH184_INT	R	Electrical	1ME730	11173	REPLACE ELEC WINDOW SWITCH	TRAVEL TO BRINKTOP RD, INSPECT POWER WINDOW FAULT, CHECK FUSES, RELAY ETC, FAULT FOUND TO BE IN SWITCH, REMOVE FUSE TO ISOLATE WINDOW, PICK UP PARK AND TRAVEL BACK TO SITE AND FIT NEW SWITCH TO UNIT, TEST OPERATION	118.13	125.03	0	39	282.16
141028-00\	SVC001401	10/31/2014	1H0103	ID - EARTH105_HBGN	R	Electrical	1ME730		REPLACE HEAD LIGHT BULBS	JOB CARRIED OUT - REMOVE HEAD LIGHT GUARD, REPLACE GLOBES, REFIT GUARD.	68.25	0	0	0	68.25
141006-00\	SVC001386	10/07/2014	1H0103	ID - EARTH184_INT	R	Electrical	1ME730	11127	REPAIR REVOLVING LIGHT FAULT	TRAVEL TO ORIELTON, REPLACED REVOLVING LIGHT GLOBE	39.38	19.72	0	33	92.1
140930-00\	SVC001387	09/30/2014	1H0103	ID - EARTH184_INT	R	Hydraulic	1ME730	11112	Top up hydraulic oil	TRAVEL TO PIPELINE SITE, TOP UP HYDRAULIC OIL AS REQUIRED	86.1	32.67	0	33	151.77
140826-00\	SVC001379	09/17/2014	1H0103	ID - EARTH184_INT	S	Service	1ME730	10992	S1 C SERVICE	TRAVEL TO PIPELINE CARRIED OUT S1 C SERVICE AS PER SCHEDULE	466.2	1457.03	0	93	2016.23
140901-00\	SVC001371	09/04/2014	1H0103	ID - EARTH184_INT	R	Air Con	1ME730	10962	CLEAN OUT A/C CONDENSOR	TRAVEL TO PIPELINE, CLEANED OUT CONDENSOR AND FILTERS AS REQUIRED	78.75	0	0	33	111.75
140818-00\	SVC001362	08/26/2014	1H0103	ID - EARTH184_INT	R	Tyres	1ME730	10867	PUMP UP TYRE	TRAVEL TO DAM SITE, PUMP UP MIDDLE LEFT TYRE SPRAY WITH SOAP TO FIND WHERE LEAKING	78.75	0	0	11	89.75
140818-00\	SVC001362	08/21/2014	1H0103	ID - EARTH184_INT	R	Bodywork	1ME730	10867	REPAIR BONNET LATCH	TRAVEL TO PIPELINE, REPAIRED FAULTY BONNET LATCH AND PUMPED UP TYRES AS REQUIRED	125.48	0	0	39.5	164.98
140821-00\	SVC001365	08/21/2014	1H0103	ID - EARTH121ADMIN	R	Tyres	1ME730		PUNCTURE REPAIR RUBAND 109328	PUNCTURE REPAIR RUBAND 109328 + TUBLESS VALVES + STRIP AND FIT + O-RINGS	0	95	0	0	95
140808-00\	SVC001357	08/12/2014	1H0103	ID - EARTH184_INT	R	Tyres	1ME730	10865	PUMP UP TYRES	TRAVEL TO PIPELINE, PUMPED UP TYRES AS REQUIRER	78.75	0	0	55	133.75
140730-00\	SVC001351	07/31/2014	1H0103	ID - EARTH184_INT	R	Tyres	1ME730	10836	CHECK TYRE PRESSURES	TRAVEL TO PIPELINE, CHECKED TYRE PRESSURES AND PUMPED UP AS REQUIRED	118.13	0	0	77	195.13
140723-00\	SVC001347	07/24/2014	1H0103	ID - EARTH184_INT	R	Bodywork	1ME730	10802	SEAL UP LEAKING ROOF	TRAVEL TO PIPELINE, SEAL UP LEAKING ROOF	100.28	19.06	0	32.5	151.84
140715-00\	SVC001342	07/18/2014	1H0103	ID - EARTH184_INT	R	Tyres	1ME730	10786	CHECK TYRE PRESSURES	TRAVEL TO PIPELINE, CHECKED TYRE PRESSURES AND ADJUSTED AS REQUIRED.	78.76	0	0	44	122.76
140616-01\	SVC001325	06/20/2014	1H0103	ID - EARTH184_INT	R	Trays/Buck	1ME730	10689	REPLACE LIFT CYL PIN & BEARING	TRAVEL TO TEA TREE, REMOVE AND REPLACE LIFT RAM BEARING AS REQUIRED. WELDING SHOP MADE UP TOOL TO ASSIST	703.51	319.02	0	102.2	1124.73
140612-00\	SVC001324	06/17/2014	1H0103	ID - EARTH184_INT	S	Service	1ME730	10688	S1 A SERVICE	TRAVEL TO TEA TREE, CARRIED OUT S1 A SERVICE AS PER SCHEDULE.	210	265.81	0	62	537.81

140523-00\	SVC00131\	05/30/2014	1H0103	ID - EARTH\ 186_INT	R	Differential	1ME730	10620 HR	RESEAL ALL HUB COVERS	RESEAL ALL HUB COVERS CHECK TRAY OPERATION NOT SITTING ON CHASSIS GENERAL CHECK OVER DRAIN OIL FROM ALL FINAL DRIVES REMOVE ALL PLANETARY COVERS PRESS OUT PLANETARY SHAFTS AND REPLACE ALL O RINGS REFIT COVERS AND FILL WITH OIL REPAIR POWER WINDOW IN CAB DOOR RESEAL BRAKE RESERVOIR DRAIN TAP REPLACE BLOWN PARK AND WORK LIGHT GLOBES REMOVE CAB DOOR REPAIR POWER WINDOW AND REFIT DOOR	1442.71	312.08	0	50	1804.79
140529-00\	SVC00131\	05/30/2014	1H0103	ID - EARTH\ 182_INT	R	Lathe	1ME730		MACHINE KNOBS AS PER SAMPLE		170.63	72.85	0	8.5	251.98
140519-01\	SVC00131\	05/27/2014	1H0103	ID - EARTH\ 105_HBGN	R	Sundries	1ME730		RETENSION WHEEL NUTS	1ME730	34.13	0	0	0	34.13
140424-00\	SVC00129\	04/29/2014	1H0103	ID - EARTH\ 184_INT	R	Trays/Buck\	1ME730	9445	INSPECT TAILGATE DAMAGE	JOB CARRIED OUT - RE-TENSION WHEEL NUTS. TRAVEL TO NYRSTAR, INSPECT TAILGATE DAMAGE AND CHECK OPERATION.	112.5	0	0	14.4	126.9
140404-00\	SVC00128\	04/28/2014	1H0103	ID - EARTH\ 105	R	Bodywork	1ME730		REPAIR BONNET LATCH	1ME730	138.5	336.72	0	0	475.22
140305-00\	SVC00128\	03/26/2014	1H0103	ID - EARTH\ 105	R	Engine	1ME730	10453	INDUCTION HOSE TO TURBO	JOB CARRIED OUT - LUBRICATED BONNET LATCH, REMOVED AND REPLACED BONNET LATCH.	32.5	0	0	0	32.5
140311-00\	SVC00127\	03/19/2014	1H0103	ID - EARTH\ 184_INT	S	Service	1ME730	10453	S1 B - 500 HR SERVICE	JOB CARRIED OUT - REPOSITION INTAKE HOSE AND CLAMP FORWARD OF SPLIT IN HOSE. TRAVEL TO NYRSTAR, CARRY OUT S1 B - 500 HR SERVICE. REPLACE BLOWN WORK LIGHT GLOBE ***OIL FILTER WAS OLD EX COTTER DAM STOCK THAT WAS UNOPENED ***FILTER NOT CHARGED OUT.	337.5	652.98	0	30.1	1020.58
140219-00\	SVC00126\	03/12/2014	1H0103	ID - EARTH\ 184_INT	R	Electrical	1ME730	10403	repair head lights	TRAVEL TO IMPACT, REPAIR LHS HEAD LIGHT	75	16.9	0	9.6	101.5
140305-00\	SVC00127\	03/12/2014	1H0103	ID - EARTH\ 105	R	Engine	1ME730	10453	PMI - PRESSURE CLEAN CORES	1ME730	162.5	0	0	0	162.5
										ODOMETER - 10453 HOURS					
										JOB CARRIED OUT - PRESSURE CLEAN COOLING CORES DUE TO PRODUCT BUILD UP. CARRY OUT PREVENTATIVE INSPECTION.					

140307-00	SVC001271	03/12/2014	1H0103	ID - EARTH	105	R	Electrical	1ME730		ARTIC ELECTRICAL REPAIRS	1ME730	32.5	0	0	0	32.5
											JOB CARRIED OUT - ARTIC ELECTRICAL REPAIRS, REMOVE TUBE, TAPE UP ELECTRICAL WIRES.					
140307-00	SVC001271	03/12/2014	1H0103	ID - EARTH	105	R	Bodywork	1ME730		BONNET LATCH REPAIR	1ME730	32.5	0	0	0	32.5
											JOB CARRIED OUT - FREE UP BONNET LATCH CABLE, LUBRICATE HINGES AND CABLE.					
140219-00	SVC001264	02/27/2014	1H0103	ID - EARTH	105_HBGN	R	Sundries	1ME730		bonnet latch repairs	1ME730	65	0	0	0	65
											JOB CARRIED OUT - CHECK AND LUBE X3 BONNET LATCHES ON HAUL TRUCKS FOR OUT LOAD, CHECK OPERATION.					
140128-00	SVC001245	02/12/2014	1H0103	ID - EARTH	184_INT	R	Hydraulic	1ME730	10397	REPAIR LHS STEER CYL LEAK	TRAVEL TO NYRSTAR, INSPECT STEER CYLINDER LEAKING LHS. REMOVE AND CLEAN AND RESEAL LHS STEER CYLINDER. REFIT TO UNIT AS REQUIRED.	1062.5	1243.28	0	78.8	2384.58
131205-00	SVC001226	12/11/2013	1H0103	ID - EARTH	105	R	Electrical	1ME730		HEADLIGHTS - BLOWN GLOBES	1ME730	65	16.9	0	0	81.9
											JOB CARRIED OUT - REPLACE BLOWN HEAD LIGHT GLOBE.					
131126-00	SVC001217	11/28/2013	1H0103	ID - EARTH	184_INT	S	Service	1ME730	10220	S1 A - 250 HR SERVICE	TRAVELLED TO NYRSTAR, CARRIED OUT S1 A 250 HR SERVICE AS PER SCHEDULE.	166.25	268.93	0	13.1	448.28
131127-01	SVC001215	11/28/2013	1H0103	ID - EARTH	184_INT	R	Trays/Buck	1ME730	10220	REPAIR TAIL GATE RUBBER	TRAVEL TO IMPACT, CLEAN UP WORK AREA, REMOVE OLD RUBBER AND FIT NEW ONE.	300	0	0	14.4	314.4
131127-01	SVC001215	11/28/2013	1H0103	ID - EARTH	184_INT	R	Engine	1ME730	10220	CLEAN OUT RADIATOR/COOLER ASSY	TRAVEL TO IMPACT, WASH OUT RADIATORS. CLOGGED WITH NYRSTAR/IMPACT MATERIAL	75	0	0	4.8	79.8
131125-00	SVC001216	11/27/2013	1H0103	ID - EARTH	184_INT	R	Electrical	1ME730	10220	REPLACE U/S BATTERIES	TRAVEL TO HOBART TO COLLECT NEW BATTERIES. TRAVEL TO NYRSTAR. FIT NEW BATTERY TO UNIT. CHECKED FAULT CODES. CHECKED CHARGE RATE.	225	472.12	0	24	721.12
131101-00	SVC001206	11/13/2013	1H0103	ID - EARTH	184_INT	R	Bodywork	1ME730	10218	REPLACE DOOR SEAL	TRAVEL TO NYRSTAR. REMOVED OLD DOOR SEALS. CLEAN UP DOOR. FIT NEW DOOR SEALS DRIVERS SIDE ONLY AS REQUIRED.	140	557.05	0	14.6	711.65
131002-00	SVC001190	10/11/2013	1H0103	ID - EARTH	105	R	Electrical	1ME730		Repair Revolving light	1ME730	32.5	9.63	0	0	42.13
											JOB CARRIED OUT - REPAIRED FAULTY REVOLVING LIGHT, REPLACED GLOBE.					

131004-00	SVC00118	10/11/2013	1H0103	ID - EARTH	105_HBGN	R	Electrical	1ME730	10189	check and clear fault codes	1ME730	65	0	0	0	65
											ODOMETER - 10189 HOURS					
											JOB CARRIED OUT - CHECK AND CLEAN ENGINE FAULT CODES.					
130902-00	SVC00117	09/13/2013	1H0103	ID - EARTH	184_INT	R	Electrical	1ME730	10110	REPLACE U/S SEAT SWITCH	TRAVEL TO IMPACT, REPLACE U/S SEAT SUSPENSION CONTROL SWITCH, INSPECT SEAT SUSPENSION FAULT, FOUND TO HAVE A U/S OPERATION SWITCH, ORDER NEW PARTS, RETURN TO MACHINE, DISASSEMBLE SEAT SWITCH ASSY, REPLACE SWITCH AND TEST OPERATION.	257.5	209	0	28.8	495.3
130808-00	SVC00114	08/16/2013	1H0103	ID - EARTH	182_INT	R	Lathe	1ME730		MACHINE TAILGATE SPACERS	MACHINE TAILGATE SPACERS	65	0	0	0	65
130731-00	SVC00114	08/15/2013	1H0103	ID - EARTH	184_INT	R	Hydraulic	1ME730	10009	REPAIR LEAKING HYD VALVE	REPAIR LEAKING HYD VALVE ON STEERING/HOIST/PPC PUMP, RAISE CAB, REMOVE LEAKING HYDRAULIC BLOCK, MACHINE OUT CRACKED WELD ON PIPE TO BLOCK, PREP AREA AND REWELD, REFIT WITH NEW O RINGS, STEAM CLEAN AREA AND TEST FOR LEAKS, LOWER CAB AND TEST DRIVE.	1007.5	114.79	0	0	1122.29
130812-00	SVC00115	08/14/2013	1H0103	ID - EARTH	184_INT	R	Trays/Buck	1ME730	10009	REPAIR & REFIT TAILGATE	REPAIR & REFIT TAILGATE, REMOVE BROKEN PARTS FROM TAILGATE PIVOT, CLEAN UP PARTS, FIT TAILGATE TO BODY AND WELD ON RETAINERS.	450.5	0	0	0	450.5
130726-00	SVC00113	07/31/2013	1H0103	ID - EARTH	184_INT	R	Trays/Buck	1ME730	10007	REMOVE DAMAGED TAIL GATE	REMOVE DAMAGED TAIL GATE FOR TRANSPORT BACK TO WORKSHOP FOR REPAIR	337.5	0	0	14.4	351.9
130702-00	SVC00112	07/30/2013	1H0103	ID - EARTH	184_INT	R	Electrical	1ME730	9915	REPAIR REVERSE ALARM & TAPE	TRAVEL TO IMPACT, REPAIR REVERSE ALARM, CLEAN OUT SPEAKER, SPEAKER ON REVERSE ALARM WAS FULL OF SUPER FROM IMPACT, REMOVE OLD WORN OUT GRIP TAPE AND APPLY NEW GRIP TAPE.	177.5	43.82	0	9.6	230.92
130717-00	SVC00113	07/30/2013	1H0103	ID - EARTH	184_INT	S	Service	1ME730	9963	S1 D - 2000 HR SERVICE	TRAVEL TO IMPACT, CARRIED OUT S1 D - 2000 HR SERVICE AS PER SCHEDULE	702.5	2335.96	0	14.4	3052.86
130723-00	SVC00113	07/30/2013	1H0103	ID - EARTH	184_INT	R	Hydraulic	1ME730	9981	CALL OUT - HYD VALVE LEAK	CALL OUT TO IMPACT, HYD VALVE LEAK, REMOVE FRONT WHEEL AND REMOVE VALVE, WELD UP CRACK AS A TEMPORARY FIX, REFIT WHEEL, ASSISTED BY PIRTEK	775	151.58	744.38	28.8	1699.76

130723-00	SVC00113	07/25/2013	1H0103	ID - EARTH	184_INT	R	Electrical	1ME730	9951	INSPECT ELECTRIC WINDOW OPERAT	TRAVEL TO NYRSTAR, INSPECT ELECTRIC WINDOW OPERATION, WAS REPORTED THAT THE WINDOW WAS STUCK DOWN, OPERATED WINDOW UP AND DOWN A DOZEN TIMES, COULD NOT FAULT.	112.5	0	0	14.4	126.9
130528-00	SVC00110	05/30/2013	1H0103	ID - EARTH	184_INT	R	Electrical	1ME730	9865 HR	Replace tray sensor	TRAVEL TO IMPACT, REPLACE TRAY SENSOR	227.5	739.82	0	9.6	976.92
130515-00	SVC00106	05/29/2013	1H0103	ID - EARTH	184_INT	R	Tyres	1ME730	9765 HR	PUMP UP FLAT TYRES	PUMP UP FLAT TYRES RUBAND 76443 FIT 2 X RUNOUTS AND ROTATE 4 X WHEEL + 2 O-RINGS 16/05/2013	114.5	320	0	0	434.5
130517-00	SVC00110	05/21/2013	1H0103	ID - EARTH	184_INT	R	Electrical	1ME730	9780	REPLACE WORK LIGHT & WHEELS	REPLACED WIPER BLADES, REPLACED WORK LIGHT GLOBE, GENERAL CHECK OVER VEHICLE, TENSIONED WHEEL NUTS	282.5	14.41	0	0	296.91
130411-00	SVC00108	04/30/2013	1H0103	ID - EARTH	184_INT	S	Service	1ME730	9717	S1 A - 250 HR SERVICE	TRAVEL TO OATLANDS, CARRIED OUT S1 A - 459 250 HR SERVICE AS PER SCHEDULE.	255.47	0	0	110.4	824.87
130124-00	SVC00104	03/12/2013	1H0103	ID - EARTH	184_INT	S	Service	1ME730	9420	S1 B - 500 HR SERVICE	CARRIED OUT SERVICE AS PER SCHEDULE.	450	679.91	0	0	1129.91
130214-00	SVC00105	02/27/2013	1H0103	ID - EARTH	184_INT	R	Engine	1ME730	9375	REPLACE BROKEN FAN BELTS	TRAVEL TO COPPING. REPAIR VALVE BANK LEAK, REMOVE VALVE BANK AND DISASSEMBLE, RESEAL AND REASSEMBLE VALVE BANK, REFIT VALVE BANK INTO MACHINE AND TEST.	300	175.65	0	96	571.65
121119-00	SVC00101	12/07/2012	1H0103	ID - EARTH	184_INT	R	Electrical	1ME730	9097	INSPECT BATTERY FAULT	TRAVELLED TO NYRSTAR. CHECK AND CLEAN BATTERY TERMINAL AND POLISH WINDOWS.	341	0	0	14.4	355.4
121114-00	SVC00100	11/26/2012	1H0103	ID - EARTH	184_INT	R	Trays/Buck	1ME730	9062	REPLACE TAILGATE RUBBER	TRAVELLED TO NYRSTAR. FITTED NEW RUBBER TO TAILGATE AS REQUIRED.	487.5	390	0	19.2	896.7
121002-00	SVC00098	10/09/2012	1H0103	ID - EARTH	184_INT	S	Service	1ME730	9041	S1 C - 1000 HR SERVICE	TRAVELLED TO IMPACT. CARRIED OUT SERVICE AS PER SCHEDULE.	616	1440.89	0	9.6	2066.49
121003-00	SVC00098	10/09/2012	1H0103	ID - EARTH	184_INT	R	Electrical	1ME730	9036	REPLACE U/S REVOLVING LIGHT	TRAVELLED TO IMPACT. REPLACED FLASHING LIGHT AS REQUIRED.	107.5	107.24	0	9.6	224.34
120828-00	SVC00095	08/29/2012	1H0103	ID - EARTH	184_INT	R	Sundries	1ME730	8932	REPAIR BONNET CABLE& TAILLIGHT	TRAVELLED TO NYRSTAR. REPAIRED BONNET CABLE AND FITTED. INSPECTED SEAT. REPAIRED WIRING FAULT TO TAIL LIGHTS.	379.5	10	0	18	407.5
120801-00	SVC00094	08/28/2012	1H0103	ID - EARTH	186_INT	R	Electrical	1ME730	57,208 km	CHECK LIGHTS AND REPAIR AS NEC	LOCATE AND REPAIR BREAK IN TAIL LIGHT WIRING FIT NEW LED COMBINATION LIGHTS	187.25	112.01	0	0	299.26
120809-00	SVC00094	08/14/2012	1H0103	ID - EARTH	184_INT	R	Electrical	1ME730	8846	REPAIR TAIL LIGHT FAULT	TRAVELLED TO IMPACT. REPAIRED TAIL LAMPS AND BRAKE LIGHTS AS REQUIRED. ALSO REPAIRED UHF FAULT.	266	34.26	0	9	309.26
120727-00	SVC00094	08/03/2012	1H0103	ID - EARTH	184_INT	S	Service	1ME730	8775	S1 A - 250 HR SERVICE	CARRIED OUT SERVICE AS PER SCHEDULE. REPLACED TANK SIGHT GLASS AND TOOK OIL SAMPLES AS REQUIRED.	357.5	288.47	0	0	645.97

120719-00\	SVC00093\	07/25/2012	1H0103	ID - EARTH\	186_INT	R	Sundries	1ME730	8663	REFIT TAIL BOARD AND CHECK	REFIT TAIL BOARD AND CHECK IT SEALS ON TRAY REPLACE MIRROR BROKEN IN TRANSIT GIVE UNIT GENERAL CHECK OVER	590	151.52	0	0	741.52
120518-00\	SVC00089\	05/25/2012	1H0103	ID - EARTH\	186_INT	R	Trays/Buck\	1ME730		REFIT TAIL BOARD REMOVE AFTER	REFIT TAIL BOARD REMOVE AFTER WEEKEND LOAD OUT	241	10	0	0	251
120518-00\	SVC00089\	05/25/2012	1H0103	ID - EARTH\	186_INT	S	Service	1ME730	8,478 HOU	S1 B SERVICE	S1 B SERVICE CARRIED OUT SERVICE AS REQUIRED REMOVED TAILGATE, REPACKED AIRCLEANER 103-6242 BRENT CLIFFORD	383.5	670.3	0	3.5	1057.3
120418-00\	SVC00088\	05/18/2012	1H0103	ID - EARTH\	184_INT	R	Electrical	1ME730	8310HRS	REPAIR UHF WIRING AND EXHAUST	TRAVEL TO NYRSTAR. REPLACE UHF VOLTAGE REDUCER. CHECK OUT SEAT FAULT AND REMOVED COVERS ON EXHAUST TO FIND EXHAUST LEAK. TIGHTEN LOOSE CLAMP.	207	121.75	0	18	346.75
120430-00\	SVC00088\	05/04/2012	1H0103	ID - EARTH\	186_INT	R	Trays/Buck\	1ME730		REMOVE TAIL BOARD	REMOVE TAIL BOARD AS REQUIRED	114.5	0	0	0	114.5
120328-00\	SVC00086\	04/05/2012	1H0103	ID - EARTH\	186_INT	R	Tyres	1ME730	8215.8 HRS	REPAIR TYRE - B/SELECT 59205	TRAVEL TO HBMI AND REPLACE WORN TYRES. FIT TYRE/TUBE IDS/AGS 18+ TUBELESS O-RING E/MOVER SVC CALL OUT NORM HRS 15 MIN ARRANGED BY PAUL KELLEHER	0	756.32	0	0	756.32
120330-00\	SVC00086\	04/04/2012	1H0103	ID - EARTH\	184_INT	S	Service	1ME730	8268	S1 A - 250 HR SERVICE	TRAVELLED TO IMPACT. CARRIED OUT 250HR SERVICE AS PER SCHEDULE. FOUND SEAT HAS ALOT OF MOVEMENT. DRAINED WASTE OIL	383	256.94	0	12.5	652.44
120306-00\	SVC00085\	03/27/2012	1H0103	ID - EARTH\	186_INT	R	Tyres	1ME730	8213 HRS	TYRE REPAIRS - BSELECT 59080	CALLOUT REMOVE AND REPLACE DAMAGED TYRE AS REQUIRED	0	414.52	0	0	414.52
120319-00\	SVC00086\	03/22/2012	1H0103	ID - EARTH\	184_INT	R	Electrical	1ME730	8261	REPAIR BLOWN HEADLIGHT	TRAVELLED TO IMPACT. REPLACED BLOWN HEAD LIGHT GLOBE	69	14.77	0	9	92.77
120220-00\	SVC00086\	03/20/2012	1H0103	ID - EARTH\	186_INT	R	Trays/Buck\	1ME730		REMOVE REPLACE TAIL GATE	REMOVE AND REPLACE TAILGATE AS REQUIRED	236	10	0	0	246
120305-00\	SVC00085\	03/15/2012	1H0103	ID - EARTH\	186_INT	R	Tyres	1ME730	LOOSE	TYRE REPAIRS RUBAND 65008	Supply and fit tyres as required	0	1320	0	0	1320
120123-00\	SVC00082\	02/15/2012	1H0103	ID - EARTH\	182_INT	R	Sundries	1ME730		MOVE TAILGATES IN THE WORKSHOP	WORK ON TAIL GATES	118	0	0	0	118
120111-00\	SVC00082\	01/31/2012	1H0103	ID - EARTH\	184_INT	S	Service	1ME730	7988	S1 D-SERVICE	TRAVELLED TO HBMI. CARRIED OUT SERVICE AS PER SCHEDULE	822	2009.48	0	54	2885.48
120119-00\	SVC00082\	01/31/2012	1H0103	ID - EARTH\	186_INT	R	Electrical	1ME730		NEW TAILLIGHTS REMOVETAILGATE	NEW TAILLIGHTS REMOVETAILGATE - REPLACE BOTH TAIL LIGHTS WITH NEW LED UNITS, REMOVE TAIL GATE AFTER IMPACT LOAD OUT.	643.5	161.03	0	0	804.53
111202-00\	SVC00080\	01/11/2012	1H0103	ID - EARTH\	186_INT	R	Trays/Buck\	1ME730	7813 hrs	REMOVE TAIL GATE AND REFIT	REMOVE AND REFIT TAILGATE AS REQUIRED	408	0	0	0	408
111202-00\	SVC00081\	01/11/2012	1H0103	ID - EARTH\	186_INT	R	Trays/Buck\	1ME730	7813 hrs	REMOVE TAIL GATE AND REFIT	Remove tailgate for truck to be used at HBMI.	177	20	0	0	197
111219-00\	SVC00081\	12/29/2011	1H0103	ID - EARTH\	182_INT	R	Trays/Buck\	1ME730		WELD UP CRACK IN TAILGATE PIVO	WELD UP CRACK IN TAILGATE PIVOT	323	16.15	0	0	339.15

111213-00	SVC000812	12/15/2011	1H0103	ID - EARTH	184_INT	R	Electrical	1ME730	7854	REPAIR LIGHTS AS REQUIRED	TRAVEL TO HBMI. REPAIR ALL LIGHTS AS REQUIRED.	228	0	0	9	237
111108-00	SVC000798	11/18/2011	1H0103	ID - EARTH	184_INT	R	Bodywork	1ME730	7706	REPLACE REAR VISION MIRROR	TRAVEL TO HOBART TIP. REPLACE BROKEN MIRROR	138	156.87	0	13.5	308.37
111108-00	SVC000798	11/16/2011	1H0103	ID - EARTH	184_INT	S	Service	1ME730	7729	S1 B - 500 HR SERVICE	TRAVEL TO TIP. CARRIED OUT 500 HR SERVICE AS PER SCHEDULE	507.5	783.78	0	13.5	1304.78
111115-00	SVC000797	11/16/2011	1H0103	ID - EARTH	184_INT	R	Electrical	1ME730	7729	REPAIR FAULT IN WINDOW & LIGHT	TRAVEL TO HOBART TIP. CHECK FOR HEADLIGHT AND ELECTRIC WINDOW FAULT. LOCATE SHORT CIRCUIT IN GLOBE AND REPLACE. REPLACE BROKEN WIRE IN DOOR FOR ELECTRIC WINDOW.	207	0	0	18	225
110916-00	SVC000770	11/08/2011	1H0103	ID - EARTH	184_INT	R	Sundries	1ME730	7361	WEEKLY TIDY UP AND INSPECTION	TRAVEL TO IMPACT. CHANGE AIR CLEANER, GREASE AND CHECK OVER	183	14.2	0	9	206.2
111017-00	SVC000782	10/25/2011	1H0103	ID - EARTH	182_INT	R	Sundries	1ME730		RESEAL TAILGATE AS NEEDED	reseal dumper as needed	466.5	0	0	0	466.5
110907-00	SVC000782	10/14/2011	1H0103	ID - EARTH	184_INT	R	Electrical	1ME730		FIT TRAVEL ALARM FOR PULP MILL	FIT TRAVEL ALARM FOR PULP MILL	118	577.4	0	0	695.4
110915-00	SVC000770	09/23/2011	1H0103	ID - EARTH	184_INT	R	Electrical	1ME730	7561	REPLACE REVOLVING LIGHT ETC	TRAVEL TO IMPACT. REPLACE FLASHING LIGHT, REPAIR CO-AXLE CABLE FOR UHF AND REFIT.	172.5	87.89	0	9	269.39
110908-00	SVC000765	09/16/2011	1H0103	ID - EARTH	184_INT	S	Service	1ME730	7360	S1 A - 250 HR SERVICE	TRAVEL TO NYRSTAR. CARRIED OUT 250 HR SERVICE AS PER SCHEDULE.	325.25	256.21	0	4.5	585.96
110905-00	SVC000741	09/06/2011	1H0103	ID - EARTH	184_INT	R	Trays/Buck	1ME730	7258	RESEAL LEAKING TAILGATE	30/8 TRAVEL TO IMPACT. RESEAL TAIL GATE 31/8 TRAVEL BACK TO IMPACT AND PUMPT UP REAR TYRES AND RE WIRE REAR TAIL LIGHTS	632	0	0	27	659
110905-00	SVC000740	09/06/2011	1H0103	ID - EARTH	184_INT	R	Sundries	1ME730	7259	WEEKLY INSPECTION AND TIDY UP	TRAVEL TO IMPACT. CHECK OVER UNIT. CHANGE AIR CLEANER	127	0	0	9	136
110714-00	SVC000745	08/31/2011	1H0103	ID - EARTH	122_INT	R	Tyres	1ME730	7077.1HRS	TYRE REPAIRS BSELECT 54835	TYRE REPAIRS BSELECT 54835	0	258.16	0	0	258.16
110809-00	SVC000760	08/31/2011	1H0103	ID - EARTH	122_INT	R	Tyres	1ME730		FIT TYRES AT HBMI P KELLEHER	FIT TYRES AT HBMI P KELLEHER	0	1005	0	0	1005
110819-00	SVC000756	08/30/2011	1H0103	ID - EARTH	184_INT	R	Service	1ME730	7198	WEEKLY INSPECTION AND TIDY UP	TRAVEL TO IMPACT. CHECK OVER, CHANGE AIR FILTER. SUBLET FILTER RECYCLING TO CLEAN AIR ELEMENT	217.5	288.46	32.8	9	547.76
110826-00	SVC000757	08/30/2011	1H0103	ID - EARTH	184_INT	R	Sundries	1ME730	7209	WEEKLY INSPECTION AND TIDY UP	TRAVEL TO IMPACT. CHECKOVER UNIT. REPLACE AIR CLEANER	138	0	0	9	147
110803-00	SVC000743	08/04/2011	1H0103	ID - EARTH	184_INT	R	Electrical	1ME730	7171	REACTIVATE ELECTRIC WINDOWS	CHECK ELECTRIC WINDOWS NOT WORKING. REMOVED CENTRE CONSOLE RECONNECTED SWITCH WIRING. TEST OPERATION.	88.5	5	0	0	93.5
110610-00	SVC000726	07/27/2011	1H0103	ID - EARTH	184_INT	R	Sundries	1ME730	7070	REPAIR SEAT SUSPENSION BASE	TRAVEL TO HBMI. INSPECT SEAT. OK. REMOVE BROKEN GREASE NIPPLE. FIT NEW NIPPLE AND GREASE.	76	407.84	0	0	483.84
110714-00	SVC000737	07/27/2011	1H0103	ID - EARTH	184_INT	S	Service	1ME730	7156	S1 C - 1000 HR SERVICE	TRAVEL TO HBMI. CARRIED OUT 1000 HR SERVICE AS PER SCHEDULE. CLEAN UP WORK AREA.	456	1784.99	0	25.2	2266.19
110601-00	SVC000718	07/08/2011	1H0103	ID - EARTH	184_INT	R	Service	1ME730	6946	S1 A - 250 HR SERVICE	CARRIED OUT 250HR SERVICE AS PER SCHEDULE	59	242.18	278.69	0	579.87

110614-00	SVC00071	06/16/2011	1H0103	ID - EARTH	184_INT	R	Sundries	1ME730	6946	REPAIR AIR CON SYSTEM	TRAVELLED TO IMPACT. CHECKED A/C PRESSURE AND OPERATION. CARRIED OUT A/C SERVICE AND REPAIRED COMPRESSOR WIRING FAULT. TESTED SYSTEM	290.75	0	0	14.4	305.15
110601-00	SVC00070	06/01/2011	1H0103	ID - EARTH	184_INT	R	Engine	1ME730	6897 HRS	C/OUT CLEAN INTERCOOLER	CALLOUT TO IMPACT. BLOW OUT AIR CON, RADIATTOR, INTERCOOLER, AIR CLEANER AND REPLACED BLOWN FUSE AND TESTED OK	368	0	0	49.5	417.5
110421-00	SVC00070	05/31/2011	1H0103	ID - EARTH	186_INT	R	Trays/Buck	1ME730	6746 hrs	REMOVE TAIL GATE AND REPLACE	tailgate was removed so that the truck could go to the quarry and cart rock. When the job was complete the tailgate was re-installed.	536.25	41.96	0	0	578.21
110328-00	SVC00067	04/06/2011	1H0103	ID - EARTH	122_INT	R	Tyres	1ME730	6706 HRS	TYRE REPAIRS BSELECT 52917	TYRE REPAIRS BSELECT 52917	0	726.32	0	0	726.32
110321-00	SVC00066	03/30/2011	1H0103	ID - EARTH	184_INT	S	Service	1ME730	6705	S1 B - 500 HR SERVICE	TRAVELLED TO NYRSTAR. CARRIED OUT 500HR SERVICE AS PER SCHEDULE	521	733.99	0	13.5	1268.49
110209-00	SVC00064	03/23/2011	1H0103	ID - EARTH	184_INT	R	Bodywork	1ME730	6569	REPLACE L/H DOOR REGULATOR ETC	TRAVELLED TO CAMBRIDGE AND PICKED UP PARTS FROM KOMATSU. TRAVELLED TO IMPACT AND REPLACED LEFT DOOR WINDOW REGULATOR AND ADJUST AND CHECKED OPERATION	452	1468.73	0	86.4	2007.13
110318-00	SVC00066	03/21/2011	1H0103	ID - EARTH	184_INT	R	Electrical	1ME730	6666	DISCONNECT POWER WINDOWS	DISCONNECT POWER WINDOWS AND LOCATE WIRING FAULT	138	0	0	0	138
110218-00	SVC00065	02/25/2011	1H0103	ID - EARTH	184_INT	R	Engine	1ME730		REPAIR OVERHEATING FAULT	TRAVELLED TO SITE AT BREADALBANE AND CLEAN OUT RADIATOR, AFTERCOOLER AND A/C CONDENSOR.	14.75	0	128.13	0	142.88
110208-00	SVC00065	02/24/2011	1H0103	ID - EARTH	122_INT	R	Sundries	1ME730		STORE ISSUE FEB PG 103-3885	STORE ISSUE FEB PG 103-3885	0	9.95	0	0	9.95
110207-00	SVC00064	02/23/2011	1H0103	ID - EARTH	186_INT	R	Electrical	1ME730		REPAIRS TO WORK LIGHTS	Repaired wiring to the work lights.	138	0	0	0	138
110131-01	SVC00064	02/03/2011	1H0103	ID - EARTH	184_INT	R	Electrical	1ME730	6455	CHECK L/H POWER WINDOW	TRAVELLED TO IMPACT/ DISMANTLE AND CHECKED OVER ELECTRIC WINDOWS ON LEFT HAND SIDE. FOUND UNIT MISSING. ORDERED NEW WINDOW WINDER ASSEMBLY AND REASSEMBLED DOOR	241.5	0	0	9	250.5
101208-00	SVC00062	01/27/2011	1H0103	ID - EARTH	184_INT	S	Service	1ME730	6161	S1 D - 2000 HR SERVICE	TRAVELLED TO IMPACT. CARRIED OUT 2000HR SERVICE AS PER SCHEDULE. REMOVED BRACKET PEDAL AND CLEAN. REFITTED BRACKET PEDAL RUBBER	818	3188.39	0	13.5	4019.89
110105-00	SVC00063	01/20/2011	1H0103	ID - EARTH	122_INT	R	Sundries	1ME730		STORE ISSUE JAN PG 103-3695	STORE ISSUE JAN PG 103-3695	0	73.06	0	0	73.06
110107-00	SVC00063	01/19/2011	1H0103	ID - EARTH	182_INT	A	Trays/Buck	1ME730		REMOVE R/H TAILGATE ARM & STRA	REMOVE R/H TAILGATE ARM & STRAIGHTEN, CHECK PIVOT PIN & MACHINE NEW UNIT IF REQUIRED	1198.5	0	0	0	1198.5

110113-00:SVC000636	01/18/2011	1H0103	ID - EARTH184_INT	S	Service	1ME730	6417 HRS	S1 A - 250 HR SERVICE	CARRIED OUT 250HR SERVICE AS PER SCHEUDLE AND REPL;ACE RIGHT FRONT HEAD LIGHT GLOBE AND LEFT REAR TAIL LIGHT GLOBE	414	241.87	0	0	655.87
101230-00:SVC000629	12/31/2010	1H0103	ID - EARTH184_INT	R	Bodywork	1ME730	6263	REPAIR DAMAGED DOOR SEAL	TRAVELLED TO IMPACT. REPLACED BLOCKED AIR FILTERS AND REPLACED DAMAGED DOOR RUBBER	103.5	0	0	0	103.5
101201-00:SVC000615	12/09/2010	1H0103	ID - EARTH184_INT	R	Trays/Buck	1ME730	5948	REPAIR BROKEN TAILGATE PIVOT	DRIVE TO IMPACT AND IDENTIFY FAULT OR DAMAGE. FOUND RETAINER ON PIN FOR DOOR LINK ARM BROKEN OFF. TOOK PHOTOS AND RETURNED TO WORKSHOP AND REPORTED FAULTS TO P STELFOX	241.5	0	0	5.4	246.9
101112-00:SVC000610	11/24/2010	1H0103	ID - EARTH184_INT	S	Service	1ME730	5902	S1 A - 250 HR SERVICE	CARRIED OUT 250HR SERVICE AS PER SCHEDULE. REPLACE MISSING GREASE NIPPLE FROM TAIL SHAFT. REPLACED LEFT FRONT PARK LIGHT GLOBE	379.5	335.54	0	2.7	717.74
101103-00:SVC000603	11/17/2010	1H0103	ID - EARTH184_INT	R	Hydraulic	1ME730	5813	REPAIR HYD LEAK UNDER CAB	TRAVELLED TO IMPACT. LIFT CAB TO LOCATE OIL LEAK AND FOUND CRACKS PIPE. REMOVED PIPE AND HAD K JUVAKKA REPAIR PIPE. REFITTED PIPE AND TESTED	310.5	0	0	9	319.5
101020-00:SVC000595	10/27/2010	1H0103	ID - EARTH122_INT	R	Sundries	1ME730		STORE ISSUE OCT PG 103-3286	STORE ISSUE OCT PG 103-3286	0	18.3	0	0	18.3
101015-00:SVC000592	10/20/2010	1H0103	ID - EARTH122_INT	R	Sundries	1ME730		STORE ISSUE OCT PG 103-3271	STORE ISSUE OCT PG 103-3271	0	21	0	0	21
100917-00:SVC000575	09/30/2010	1H0103	ID - EARTH182_INT	R	Trays/Buck	1ME730	35362KMS	ATTATCH HUNGRY BOARDS TO SIDES	CLEAN TOP OF TRAY SIDES FROM HEAVY BUILD UP OF SUPER. REMOVE SIDE ARM TO REPAIR PIVOT POINT CRACKS AND MACHINE NEW PIN AND REFIT. CHANGE BRACKETS TO INSIDE OF TRAY AND WELD OFF. SIDE MATERIAL SALVAGED FROM QUARRY	2157	666.33	0	0	2823.33
100602-00:SVC000543	09/22/2010	1H0103	ID - EARTH184_INT	R	Brake	1ME730	5212	REPLACE BROKEN BRAKE PIPES	02/06 - TRAVELLED TO BRIGHTON SUB DIVISION AND REMOVED DAMAGED BRAKE COOLING PIPING AT CENTRE AXLE. HAD TEMPORARY HOSES AND FITTINGS FITTED TO ENABLE UNIT TO CONTINUE OPERATING. ORDERED NEW PIPING - EX JAPAN. 09/07 - RETURNED TO UNIT AND REPLACED HOSES WITH REGULATION PIPING.	714.5	730.14	610	48.6	2103.24
100915-00:SVC000577	09/22/2010	1H0103	ID - EARTH184_INT	S	Service	1ME730	5547	S1 B - 500 HR SERVICE	TRAVELLED TO IMPACT FERTILIZER. SERVICED UNIT AS PER SCHEDULE. REPAIRED REAR WIPER OPERATION. REPLACED GREASE NIPPLES IN CENTRE PIVOT	552	146.66	0	23.4	722.06
100818-00:SVC000555	08/25/2010	1H0103	ID - EARTH182_INT	R	Trays/Buck	1ME730	33640	SEAL AROUND TAILGATE AS REQUES	SEAL UP TAILGATE WITH SUPPLIED RUBBER AND WELD ON FLATBAR AS NEEDED	855.5	41.52	0	0	897.02

100726-00	SVC000554	08/23/2010	1H0103	ID - EARTH	186_INT	R	Trays/Buck	1ME730	5370	REMOVE DAMAGED TAIL GATE	REMOVED TAIL GATE FROM TRAY, REMOVE PINS FROM ARMS, REMOVE WIORE ROPS, FIT NEW CHAINS TO ARMS, REFIT TAILGATE AND CHECK OPERATION. The truck was inspected and greased. the mirrors were swapped form one truck to the other as it was required out on site.	796.5	420.91	0	0	1217.41
100727-00	SVC000547	08/10/2010	1H0103	ID - EARTH	182_INT	R	Sundries	1ME730		REPAIR DAMAGED TAIL GATE	REPAIR BENT TAIL GATE, INSTALL AND FASTEREND TAIL GATE AASSEMBLY	512	0	0	0	512
100809-00	SVC000554	08/10/2010	1H0103	ID - EARTH	182_INT	R	Sundries	1ME730		SEAL UP DAMAGED TAIL GATE PLUS	STRAIGHTEN BENT LUGS, SEAL TAILGATE AND REPAIR CRACKS	959.5	55.88	0	0	1015.38
100729-00	SVC000550	07/30/2010	1H0103	ID - EARTH	184_INT	R	Trays/Buck	1ME730	5289	SEAL TAILGATE ON UNIT	TRAVELLED TO NYRSTAR AND SEALED UP TAILGATE TO TRAY WITH PREFABRICATED CHUTEX STRIP. STRIP SUPPLIED AGAINST 1ME737.	359.5	0	0	22.5	382
100727-00	SVC000547	07/29/2010	1H0103	ID - EARTH	182_INT	R	Lathe	1ME730		MACHINE MODIFIED PIVOT PINS	MACHINE MODIFIED PIVOT PINS	324.5	154.64	0	0	479.14
100630-00	SVC000542	07/21/2010	1H0103	ID - EARTH	186_INT	S	Service	1ME730	5256	S1 A - 250 HR SERVICE	Service unit as required "A" Remove and replace broken grease nipple	550	217.56	0	2.7	770.26
100705-00	SVC000532	07/21/2010	1H0103	ID - EARTH	182_INT	R	Lathe	1ME730		MACHINE CHROME BOTTOM STRIKER	MACHINE & CHROME 4 BOTTOM STRIKER BARS FOR BONNET LATCH AS REQUESTED BY PETER STELFOX	26	6.46	100	0	132.46
100709-00	SVC000543	07/21/2010	1H0103	ID - EARTH	184_INT	R	Trays/Buck	1ME730	5263	REPLACE BROKEN TAILGATE PINS	TRAVELLED TO BRIGHTON. DISMANTLE TAIL GATE, MEASURE UP SHIMS AND FIT TO TAIL GATE. PICK UP NEW STROP SHACKLES AND FIT. CHANGE OUT BRAKE COOLING PIPE	407.5	105.79	0	36	549.29
100630-00	SVC000532	07/14/2010	1H0103	ID - EARTH	182_INT	R	Lathe	1ME730		MACHINE TAILGATE PINS AS REQUE	MACHINE TAILGATE PINS AS REQUESTED	432.5	20.02	0	0	452.52
100709-00	SVC000538	07/14/2010	1H0103	ID - EARTH	182_INT	R	Lathe	1ME730		MACHINE 6 SHIMS AS REQUESTED B	MACHINE 6 SHIMS AS REQUESTED BY RICKI DODGE	132.75	3.63	0	30	166.38
100630-00	SVC000536	07/09/2010	1H0103	ID - EARTH	186_INT	R	Trays/Buck	1ME730		REPAIR TAILGATE	Refit tail gate Modify Turnbuckles Remove door linings and check operation on window winder, refit door lining Fit new bonnet latch and adjust as required Adjust and test operation of tailgate	1041.5	35.2	0	0	1076.7
100625-00	SVC000535	07/07/2010	1H0103	ID - EARTH	184_INT	R	Bodywork	1ME730	5241	REPLACE BROKEN BONNET CATCH	TRAVELLED TO UNIT AND REPLACED BONNET STRICKER	93.5	0	0	0	93.5
100603-00	SVC000515	06/04/2010	1H0103	ID - EARTH	184_INT	R	Hydraulic	1ME730	5140	REPAIR HYDRAULIC HOSE	TRAVELLED TO BRIGHTON. FIT SPIRAL WRAP TO DAMAGED HOSE AMD CARRY OUT REPAIRS TO HOSE	126.5	3.25	0	45	174.75
100524-00	SVC000506	05/27/2010	1H0103	ID - EARTH	122_INT	R	Sundries	1ME730		PARTS REQ MAY 103-2332	PARTS REQ MAY 103-2332	0	110.64	0	0	110.64
100526-00	SVC000508	05/26/2010	1H0103	ID - EARTH	184_INT	R	Sundries	1ME730	5160	REPAIR SEAT ASSEMBLY	TRAVELLED TO BRIGHTON. CARRY OUT REPAIRS TO SEAT ASSEMBLY	99	0	0	67.5	166.5

100517-00\	SVC000507	05/25/2010	1H0103	ID - EARTH184_INT	R	Sundries	1ME730	5146 hrs	SEAT DAMPER REPAIRS	TRAVELLED TO MACHINE. REMOVE OPERATORS SEAT. DISASSEMBLE AND REPLACE DAMPERS. REASSEMBLE AND REFITTED TO MACHINE	93.5	528.69	0	0	622.19
100518-00\	SVC000500	05/18/2010	1H0103	ID - EARTH184_INT	R	Sundries	1ME730	5130	DAMAGED GREASE NIPPLE	TRAVELLED TO MACHINE. REMOVE DAMAGED GREASE NIPPLE FRO LEFT AND RIGHT BODY LIFT CYLINDERS PURGE BEARINGS	72	0	0	0	72
100517-01\	SVC000500	05/17/2010	1H0103	ID - EARTH184_INT	R	Electrical	1ME730		REPLACE REVOLVING LIGHT GLOBE	TRAVELLED TO UNIT AND REPLACED REVOLVING LIGHT GLOBE	36	8.51	0	0	44.51
100427-00\	SVC000487	05/13/2010	1H0103	ID - EARTH184_INT	S	Service	1ME730	5012	S1 C - 1000 HR SERVICE	TRAVELLED TO BRIGHTON. CARRIED OUT 1000HR SERVICE AS PER SCHEDULE. REPLACE BONNET STRIKER AND ADJUST REPAIRED BONNET STAY RELEASE CABLE. FITTED REVOLVING LIGHT	781	1554.35	0	25.2	2360.55
100316-00\	SVC000463	03/31/2010	1H0103	ID - EARTH184_INT	S	Service	1ME730	4760	S1 B - 500 HR SERVICE	CARRY OUT 500HR SERVICE AS PER SCHEDULE	55	524.14	581.76	0	1160.9
100315-01\	SVC000463	03/16/2010	1H0103	ID - EARTH184_INT	R	Engine	1ME730	4622	CHECK UNIT FOR OVERHEATING	TRAVELLED TO BRIGHTON AND BLOW OUT RADIATOR, AIR CON AND OIL COOLER	93.5	0	0	13.5	107
091204-00\	SVC000449	03/11/2010	1H0103	ID - EARTH186_INT	R	Sundries	1ME730		GENERAL CHECK OVER	inspect the dump truck and top up oils as required.	137.5	32.4	0	0	169.9
091203-00\	SVC000455	03/04/2010	1H0103	ID - EARTH122_INT	R	Tyres	1ME730	N/A	NEW TYRES FOR DUMPER AS PER	NEW TYRES FOR DUMPER AS PER	0	20550	0	0	20550
091019-00\	SVC000428	02/17/2010	1H0103	ID - EARTH186_INT	R	Sundries	1ME730	3943hours	REPAIR WINDOW GROUP	Repair the window group, as the window wouldn't stay up.	82.5	0	0	0	82.5
100121-00\	SVC000429	02/05/2010	1H0103	ID - EARTH184_INT	S	Service	1ME730	4470	S1 A - 250 HR SERVICE	TRAVELLED TO BRIGHTON AND CARRIED OUT 250HR SERVICE AS PER SCHEDULE. FIT NEW FIRE EXTINGUISHER AND BRACKET	412.5	282.83	0	38.7	734.03
091218-00\	SVC000414	01/11/2010	1H0103	ID - EARTH122_INT	R	Sundries	1ME730		STORE ISSUE DEC.PG REQ.1400,	STORE ISSUE DEC.PG REQ.1400,	0	115.79	0	0	115.79
091130-00\	SVC000422	01/08/2010	1H0103	ID - EARTH122_INT	R	Tyres	1ME730	4100 HRS	TYRE REPAIRS B SELECT 44085	TYRE REPAIRS B SELECT 44085	0	486.36	0	0	486.36
091207-00\	SVC000422	01/08/2010	1H0103	ID - EARTH122_INT	R	Tyres	1ME730	4176	TYRE REPAIRS B SELECT 44270	TYRE REPAIRS B SELECT 44270	0	360.9	0	0	360.9
091208-00\	SVC000422	01/08/2010	1H0103	ID - EARTH122_INT	R	Tyres	1ME730	N/A	TYRE FIT UP B SELECT 44290	TYRE FIT UP B SELECT 44290	0	1843.56	0	0	1843.56
100105-00\	SVC000420	01/06/2010	1H0103	ID - EARTH184_INT	R	Tyres	1ME730	4186	SET UP UNIT FOR TYRE REPAIRS	Travelled to Brighton.	66	0	0	13.5	79.5
091218-00\	SVC000415	12/21/2009	1H0103	ID - EARTH184_INT	R	Hydraulic	1ME730	4246	REPAIR LEAK AT HYDRAULIC TANK	Set up unit for tyres to be changed TRAVELLED TO BRIGHTON AND REPLACE FAULTY O-RING IN HYDRAULIC TANK AND CHANGE OUT FLASHING LIGHT GLOBE	126.5	0	0	27	153.5
091209-00\	SVC000409	12/16/2009	1H0103	ID - EARTH184_INT	S	Service	1ME730	4217	S1 D - 2000 HR SERVICE	TRAVELLED TO BRIGHTON AND CARRIED OUT 2000HR SERVICE AS PER SCHEDULE	785.5	2361.07	0	45	3191.57

091126-00	SVC00041	12/10/2009	1H0103	ID - EARTH	184_INT	R	Bodywork	1ME730	4156	REPLACE BONNET LOCK ASSEMBLY	TRAVELLED TO BRIGHTON. REPLACE DAMAGED BONNET LATCHING MECHANISM AND ADJUST	196	491.18	0	13.5	700.68
091109-00	SVC00039	12/04/2009	1H0103	ID - EARTH	184_INT	R	Engine	1ME730	3984	REPAIR CRACKED INTERCOOLER	TRAVELLED TO BRIGHTON AND REMOVE INTERCOOLER FOR REPAIR. REFIT INTERCOOLER AND TEST	430	41.58	0	63	534.58
091111-00	SVC00039	12/04/2009	1H0103	ID - EARTH	184_INT	R	Bodywork	1ME730	4020KMS	DISMANTLE DRIVERS DOOR CHECK	TRAVELLED TO BRIGHTON AND CHECK LIFT CYLINDERS. DISMANTLE DRIVER DOOR TO REPAIR WINDOW WINDER AND FOUND WINDER ASSEMBLY MISSING. REASSEMBLE DOOR	198	628.8	0	58.5	885.3
091120-00	SVC00039	11/20/2009	1H0103	ID - EARTH	184_INT	R	Electrical	1ME730	3943	repair work lights	Repair reverse alarm and work light as required	165	0	0	0	165
091110-00	SVC00039	11/11/2009	1H0103	ID - EARTH	184_INT	R	Sundries	1ME730	3983	DRILL OUT BROKEN NIPPLE	TRAVELLED TO BRIGHTON AND DRILL OUT BROKEN GREASE NIPPLE ON LEFT HAND SIDE REAR STRUT AND FIT NEW NIPPLE	82.5	0	0	18	100.5
091023-00	SVC00038	11/05/2009	1H0103	ID - EARTH	184_INT	S	Service	1ME730	3963	S1 A - 250 HR SERVICE	TRAVELLED TO BRIGHTON. CARRIED OUT 250HR SERVICE AS PER SCHEDULE. FOUND THAT THE INTERCOOLER HAD A LEAK IN THE BOTTOM LEFT HAND CORNER	483	308.12	0	56.7	847.82
091020-00	SVC00037	10/23/2009	1H0103	ID - EARTH	122_INT	R	Sundries	1ME730		STORE ISSUE OCT.PG REQ.1017,	STORE ISSUE OCT.PG REQ.1017,	0	100.49	0	0	100.49
090713-00	SVC00032	09/04/2009	1H0103	ID - EARTH	122_INT	R	Sundries	1ME730		PARTS REQ. JULY 25198	PARTS REQ. JULY 25198	0	29.5	0	0	29.5
090819-00	SVC00034	09/04/2009	1H0103	ID - EARTH	122_INT	R	Sundries	1ME730		PARTS REQ AUG 21407	PARTS REQ AUG 21407	0	484.32	0	0	484.32
090828-00	SVC00035	09/04/2009	1H0103	ID - EARTH	122_INT	R	Sundries	1ME730	N/A	REQ N/O 21412 - FUEL CAP	REQ N/O 21412 - FUEL CAP	0	220.02	0	0	220.02
090622-00	SVC00031	07/06/2009	1H0103	ID - EARTH	184_INT	S	Service	1ME730	3669	S1 B - 500 HR SERVICE	S1 B - 500 HR SERVICE : TRAVEL TO DELORAINE. CARRY OUT SERVICE AND CHECKS ON UNIT. * ALL PARTS SUPPLIED THROUGH KOMATSU LAUNCESTON - PETER STELFOX	635	724.27	0	108	1467.27
090615-00	SVC00030	06/26/2009	1H0103	ID - EARTH	122_INT	R	Sundries	1ME730		REFER JUNE REQ.PG 25183		0	67	0	0	67
090515-00	SVC00029	06/18/2009	1H0103	ID - EARTH	184_INT	S	Sundries	1ME730	3370	REPLACE AIR COND FILTERS ETC	REPLACE AIR CONDITIONER FILTERS	27.5	526.89	0	0	554.39
090429-00	SVC00028	05/13/2009	1H0103	ID - EARTH	184_INT	S	Service	1ME730	3370	S1 A - 250 HR SERVICE	S1 A - 250 HR SERVICE : TRAVEL TO DELORAINE. CARRY OUT A - TYPE SERVICE AND CHECKS. * ALL FILTERS SUPPLIED THROUGH KOMATSU LAUNCESTON ! USED: 40 LITRES OF MX MOBILE ENGINE OIL : 2 X MOBILE GREASE CARTRIDGES TRAVEL DISTANCE 150 KMS	340.5	232.33	0	137.7	710.53

090424-00	SVC00028	04/29/2009	1H0103	ID - EARTH	184_INT	R	Electrical	1ME730	3,324 hrs	REVOLVING LIGHT	REVOLVING LIGHT : TRAVELLED TO DELORAINE. REPAIRED BARE WIRE IN LUME ON REVOLVING LIGHT,AND REFIT AND TEST.	175.5	0	0	108	283.5
090207-00	SVC00023	03/26/2009	1H0103	ID - EARTH	122_INT	R	Sundries	1ME730		REFER REQ.26783 FEB PG	REFER REQ.26783 FEB PG	0	97	0	0	97
090120-00	SVC00022	03/19/2009	1H0103	ID - EARTH	122_INT	R	Sundries	1ME730		PARTS REQ JAN 26778	PARTS REQ JAN 26778	0	67	0	0	67
090220-00	SVC00024	02/23/2009	1H0103	ID - EARTH	184_INT	S	Service	1ME730	3111 HRS	S1 C - 1000 HR SERVICE	TRAVELLED TO SITE. CARRY OUT 1000HR SERVICE AS PER SCHEDULE AND REPLACED FLASHING LIGHT	1451	1544.44	0	377.2	3372.64
071010-00	SVC00002	02/20/2009	1H0103	ID - EARTH	184_INT	S	Service	1ME730	1116	S1 - C 1000 HR SERVICE	TRAVELLED TO ZEEHAN. SERVICED UNIT AS PER 1000 HR SERVICE SCHEDULE.	630	942.16	0	255	1827.16
090123-00	SVC00023	01/27/2009	1H0103	ID - EARTH	184_INT	R	Sundries	1ME730	2926	CLEAN WINDOW CHANNEL AND HOOK	CLEAN WINDOW CHANNEL travel to deloraine 125klm clean out window channel hook up uhf radio	228	0	0	112.5	340.5
090108-00	SVC00022	01/19/2009	1H0103	ID - EARTH	184_INT	R	Sundries	1ME730	2868	PRE HIRE INSPECTION & REPAIRS	TRAVEL TO HBMI AND CHECK OIL LEVELS AND INSPECT UNIT. RETURNED AND REPAIRED FOLLOWING: FABRICATED AND FITTED REPLACEMENT R/H CAB STEP (NEW PARTS \$1200.00). REPAIRED L/H CAB STEP. DISASSEMBLED STEERING WHEEL AND CONTROL COLUMN AND REPLACED LIGHT/INDICATOR CONTROL AND REASSEMBLED. REPLACED R/H REAR VISION MIRROR AND REVOLVING LIGHT GLOBE.	805	504.41	0	135	1444.41
081211-00	SVC00021	12/23/2008	1H0103	ID - EARTH	184_INT	S	Service	1ME730	2836	S1 A - 250 HR SERVICE	CARRY OUT S1-A 250HR SERVICE AS PER SCHEDULE	320	189.39	0	2.7	512.09
081211-00	SVC00021	12/11/2008	1H0103	ID - EARTH	184_INT	S	Service	1ME730	2149	REFER KOMATSU REVF001479	TRAVELLED TO SISTERS HILL COMPLETE SERVICE REPAIR BROKEN LIGHTS	0	0	6992.22	0	6992.22
081017-00	SVC00019	11/13/2008	1H0103	ID - EARTH	122_INT	R	Tyres	1ME730		TYRE REPLACEMENTS R HAZELL	TYRE REPLACEMENTS R HAZELL	0	23532	0	0	23532
080924-00	SVC00017	09/30/2008	1H0103	ID - EARTH	184_INT	R	Electrical	1ME730	2536.	REPLACE TAIL LIGHT ETC.	TRAVELLED TO RANLAGH. REPAIR CAB GUARD ON TRAY, FIT NEW TAIL LIGHT LANS, REPAIR HYDRAULIC BRACKETS AND EXTRACT BROKEN BOLTS	115	85.93	0	67.5	268.43
080829-00	SVC00015	09/22/2008	1H0103	ID - EARTH	184_INT	S	Service	1ME730	2470hrs	S1 D - 2000 HR SERVICE.	S1 D - 2000 HR SERVICE. Perform 2000hr service as required	1501	1749.6	0	2.7	3253.3
080826-00	SVC00015	08/28/2008	1H0103	ID - EARTH	122_INT	R	Sundries	1ME730		REFER REQ.13333 PG	REFER REQ.13333 PG	0	16.05	0	0	16.05
080728-00	SVC00014	08/08/2008	1H0103	ID - EARTH	186_INT	R	Service	1ME730	2291	Inspect Park Brake	INSPECT PARK BRAKE Found it to be out of adjustment, cleaned the brake unit and performed adjustment tested operation. found all okay.	300	0	0	0	300
080617-00	SVC00012	07/05/2008	1H0103	ID - EXCAV	122_INT	R	Sundries	1ME730		REFER REQ.13311	REFER TO REQ 13311	0	24	0	0	24

080401-01	SVC00007	06/20/2008	1H0103	ID - EXCAV/ 184_INT	R	Trays/Buck	1ME730	1675 hrs	REPAIR BROKEN TURNBUCKLES	TRAVELLED TO DEE LAGOON. CLEAN UP MOUNTING POINTS, FIT BOTH TAILGATE ARMS AND FIT TAILGATE, REPAIR BROKEN TURNBUCKLES, FIT CABLES AND ADJUST, TEST OPERATION	611.25	0	0	80	691.25
080401-01	SVC00012	06/20/2008	1H0103	ID - EXCAV/ 184_INT	R	Trays/Buck	1ME730	1675 hrs	REPAIR BROKEN TURNBUCKLES	REPAIR BROKEN TURN BUCKLES	276.25	7.59	0	0	283.84
080530-00	SVC00011	06/03/2008	1H0103	ID - EXCAV/ 122_INT	R	Sundries	1ME730		REFER REQ.17200 PG	REFER TO REQ 17200	0	93.6	0	0	93.6
080528-00	SVC00011	05/29/2008	1H0103	ID - EXCAV/ 122_INT	F	Tyres	1ME730		CALL FIT CUSTOMER OWN PRODUCT	1ME730 ODO - 1884 HRS	0	546.84	0	0	546.84
										DUGGAN AND PARKER TYRE SERVICE TRAVEL TO DEE LAGOON FIT RUNOUT					
080528-00	SVC00011	05/29/2008	1H0103	ID - EXCAV/ 122_INT	F	Tyres	1ME730		FIT RUNOUT	ARRANGED BY DARREN McCONNOR 1ME730 ODO - 1835 HRS	0	460.52	0	0	460.52
										DUGGAN AND PARKER TYRE SERVICE TRAVEL TO DEE LAGOON REMOVE DAMAGE TYRE AND FIT RUN OUT					
										ARRANGED BY DARREN McCONNOR					
080507-00	SVC00010	05/19/2008	1H0103	ID - EXCAV/ 122_INT	R	Sundries	1ME730		REQ MAY 17192		0	69.78	0	0	69.78
080514-00	SVC00010	05/19/2008	1H0103	ID - EXCAV/ 122_INT	R		1ME730		PARTS AS 17193		0	62.6	0	0	62.6
080508-00	SVC00010	05/14/2008	1H0103	ID - EXCAV/ 184_INT	S	Service	1ME730	1940 HRS	S1 A - 250 HR SERVICE.	TRAVELLED TO DEE LAGOON. CARRIED OUT SERVICE AS PER SCHEDULE	700	211.12	0	120	1031.12
080501-00	SVC00009	05/02/2008	1H0103	ID - EXCAV/ 184_INT	R	Bodywork	1ME730	1857	ADJUST BONNET CATCHES	UNIT: 1ME730 ODOMETER: 1857	70	0	0	0	70
										ADJUST BONNETT CATCHES AND CHECK REVOLVING LIGHT.					
080326-00	SVC00008	04/28/2008	1H0103	ID - EXCAV/ 184_INT	S	Service	1ME730	1650	S1 B - 500 HR SERVICE.		260	0	0	0	260
080326-00	SVC00009	04/28/2008	1H0103	ID - EXCAV/ 184_INT	S	Service	1ME730	1650	S1 B - 500 HR SERVICE.	Performed 500 hour service as required.	0	0	1860.35	0	1860.35
080409-00	SVC00008	04/10/2008	1H0103	ID - EXCAV/ 184_INT	R	Trays/Buck	1ME730		REMOVE BROKEN TAILGATE	TRAVELLED TO DEE LAGOON. REMOVE BROKEN TAILGATE SIDE BEAMS AND RETURN TO WORKSHOP FOR REPAIRS	331.25	0	0	180	511.25
080221-00	SVC00005	02/26/2008	1H0103	ID - EXCAV/ 184_INT	R	Bodywork	1ME730	1422	REPLACE BROKEN MIRROR.	REMOVE AND REPLACE MIRROR ON LEFT HAND GUARD	52.5	458.05	0	0	510.55
080107-00	SVC00001	01/30/2008	1H0103	ID - EXCAV/ 182_INT	W	Trays/Buck	1ME730		REPAIR CRACKS	WARRANTY REPAIRS TO TRAY TAIL GATE PIVOTS AS PER SERVICE NEWS AT 06445	793.75	27.96	0	0	821.71
071126-00	SVC00002	01/23/2008	1H0103	ID - EXCAV/ 184_INT	S	Service	1ME730	1374	S1 A - 250 HR SERVICE.	CARRIED OUT SERVICE AND CHECK AS PER SCHEDUEL	136.25	190.47	0	2	328.72

080108-00	SVC00001	01/11/2008	1H0103	ID - EXCAV/ 186_INT	W	Electrical	1ME730	7511k 1373	WARRANTY ON KOMATSU,RADIO SPKR	UNIT: 1ME730 ENGINE NO. 00562906 ODOMETER: 7511 k 1373.8 hours	22.5	0	0	0	22.5
071120-01	SVC00002	12/06/2007	1H0103	ID - EXCAV/ 122_INT	R	Sundries	1ME730		PARTS AS PER REQ 16615	REPLACE RADIO SPEAKER LEFT HAND SIDE WITH NEW SPEAKER SUPPLIED BY KOMATSU.	0	81.8	0	0	81.8

Applied filters:Posted_Date is on or after 01/01/1900Equipment_ID is 1ME730