03801978

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba K06-1

Vehicle Standards and Inspections
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

DECAL
VOID WITHOUT DECAL

Manitoba
A794670

Date Inspection Started	13 (DAY)	09 (MO.)	25 (YR.)
Date Inspection Completed	25 (DAY)	08 (MO.)	25 (YR.)
Inspection Expiry Date	31 (DAY)	08 (MO.)	26 (YR.)

Station Number: A6224 — Station Name: Wildwood Transport Inc — City: Oak
Mechanic Number: M7606 — Mechanic Signature: [signature] — Station Phone Number: 20

Vehicle Owner: Wildwood Transport Inc
Address: 100 Oakland Rd — City: Oak Bluff — Province: MB — Postal Code: R3R 3S3 — Phone:

☒ Pass/Safe Vehicle
☒ Fail/Unsafe Vehicle
☐ Fail/Hazardous

Licence Number: TD7267 — Prov.: MB — NSC #: — — Odometer Reading: 535326 — Odom. Type: ☐ km ☒ mi
Vehicle Identification Number: 1RND49A267R915905 — Make: Peterbilt — Model: [illegible] — Year: 2007 — Unit #: 5810
☑ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

___Truck GVWR ____ KGS ___Truck Tractor ___Trailer X Semi-Trailer ___Bus ___School Bus ___Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
N/A		**Section 1 - Power Train:** Defects (if any)
X	X	**Section 2 Suspension:** Defects (if any) All shocks X - 7a
X	X	**Section 3 - Brake Systems:** 3H (3A) Defects (if any) — Circle Brake Type: Glad hands X - 13a; bf shoes X - 15b; Clevis pins X - 16c; Brake valve 525 X - 8a; ABS X - 20c
N/A		**Section 4 - Steering:** Defects (if any)
X		**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any)
X		**Section 6 - Lamps:** Defects (if any)
X	X	**Section 7 - Electrical System:** Defects (if any) ~~ABS light~~ X-4
X		**Section 8 - Body:** Defects (if any)
X	X	**Section 9 - Tire & Wheel:** Defects (if any) Wheel Seal RF X - 1c
X		**Section 10 - Coupling Devices:** Defects (if any)

Brake Inspection Type: (A) B C D E — Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining L	Lining R	Drum/Rotor L	Drum/Rotor R	Stroke L	Stroke R
1	3/4	NEW	16.562	16.555	1 1/2	1 1/2
2	11/16	5/8	16.590	16.595	1 1/2	1 1/2
3						
4						
5						
	Final Measurement					

Axle	Tread Depth Initial L		Initial R		Corrected L		Corrected R		Air Pressure Initial L		Initial R		Corrected L		Corrected R	
1	18	18	12	12					105	105	105	105				
2	15	15	13	13					105	105	105	105				
3																
4																
5																

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: W/D # 23672 Retorque Tag #42876

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Signature — Date: _____

FVS6022-01-(R-09/15)

Ce document peut être obtenu en français sur demande

COPY IN CAB - PLEASE ENSURE CERTIFICATE IS SIGNED - NOT FOR REGISTRATION