

03801978

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE



Vehicle Standards and Inspector
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920



Date Inspection Started: 18 08 25
 Date Inspection Completed: 25 08 25
 Inspection Expiry Date: 31 08 26

Station Number: A6224
 Station Name: Wildwood Transport Inc
 City: Oak Bluff
 A794670

Mechanic Number: M7606
 Mechanic Signature: [Signature]
 Station Phone Number: 204-957-9866

Vehicle Owner: Wildwood Transport Inc
 Address: 100 Oakland Rd
 City: Oak Bluff
 Province: MB
 Postal Code: R3R 3S3
 Phone: [Blank]

Pass/Safe Vehicle
 Fail/Unsafe Vehicle
 Fail/Hazardous

Licence Number: TD7262
 Prov.: MB
 NSC #: -

Odometer Reading: 535,326
 Odom. Type: km mi

Vehicle Identification Number: 1RND48A267R015805
 Make: Retriever
 Model: Retriever
 Year: 2007
 Unit #: 5810

Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck GVWR KGS Truck Tractor Trailer Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																						
N/A		Section 1 - Power Train: Defects (if any)																																																																						
X	X	Section 2 Suspension: Defects (if any) All shocks X - 7a																																																																						
X	X	Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type Glad hands X - 13a LF shoes X - 15b Clevis pins X - 16c Brake valve SRS X - 8a ABS X - 20e Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																						
N/A		Section 4 - Steering: Defects (if any)																																																																						
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																						
X		Section 6 - Lamps: Defects (if any)																																																																						
X	X	Section 7 - Electrical System: Defects (if any) ABS light X																																																																						
X		Section 8 - Body: Defects (if any)																																																																						
X	X	Section 9 - Tire & Wheel: Defects (if any) Wheel Seal RF X - 3c																																																																						
		<table border="1"> <thead> <tr> <th rowspan="3">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>18</td> <td>18</td> <td>12</td> <td>12</td> <td>105</td> <td>105</td> <td>105</td> <td>105</td> </tr> <tr> <td>2</td> <td>15</td> <td>15</td> <td>18</td> <td>18</td> <td>105</td> <td>105</td> <td>105</td> <td>105</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected		L	R	L	R	L	R	L	R	1	18	18	12	12	105	105	105	105	2	15	15	18	18	105	105	105	105	3									4									5								
Axle	Tread Depth				Air Pressure																																																																			
	Initial			Corrected		Initial		Corrected																																																																
	L	R	L	R	L	R	L	R																																																																
1	18	18	12	12	105	105	105	105																																																																
2	15	15	18	18	105	105	105	105																																																																
3																																																																								
4																																																																								
5																																																																								
X		Section 10 - Coupling Devices: Defects (if any)																																																																						

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: w/o # 23637 Retorque Tag # 42876

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.
Vehicle received without repairs by: _____ Date: _____
Signature