

03801970

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE



Vehicle Standards and Inspection
Box 45064 Regent Postal Office
Winnipeg, MB, R2C 5C7
1-204-985-0920



Date Inspection Started: 13 06 25
 Date Inspection Completed: 18 06 25
 Inspection Expiry Date: 30 06 26

Station Number: A6224 Wildwood Transport Inc
 Station Name: Wildwood Transport Inc
 City: Oak Bluff
 A794662
 Mechanic Number: M76016
 Mechanic Signature: [Signature]
 Station Phone Number: 204-957-8866
 Vehicle Owner: Wildwood Transport Inc
 Address: 100 Oakland Rd
 City: Oak Bluff MB
 Province: MB
 Postal Code: R5G 0A4
 Phone: [Blank]

Pass/Safe Vehicle
 Fail/Unsafe Vehicle
 Fail/Hazardous

Licence Number: TB95810
 Prov.: MB
 NSC #: [Blank]

Vehicle Identification Number: 1RND4BAZ16R014284
 Make: Retriever Model: Step Year: 2006 Unit #: 5807

Odometer Reading: 457,787
 Odom. Type: km mi

Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck GVWR KGS Truck Tractor Trailer Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
N/A		Section 1 - Power Train: Defects (if any)
X	X	Section 2 Suspension: Defects (if any) Rear shocks X-7a
X	X	Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type Glad hands X-13a Front shoes X-15b Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection
N/A		Section 4 - Steering: Defects (if any)
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
X		Section 6 - Lamps: Defects (if any)
X		Section 7 - Electrical System: Defects (if any)
X	X	Section 8 - Body: Defects (if any) Floor boards X-5b Dolly crank handle X-22c
X	X	Section 9 - Tire & Wheel: Defects (if any) LFO tread X-2c
X		Section 10 - Coupling Devices: Defects (if any)

Axle	Lining		Drum/Rotor		Stroke	
	L	R	L	R	L	R
1	NEW	NEW	16.518	16.563	1 1/2	1 1/2
2	3/4	3/4	16.574	16.584	1 1/2	1 1/2
3						
4						
5						
Final Measurement						

Axle	Tread Depth				Air Pressure					
	Initial		Corrected		Initial		Corrected			
	L	R	L	R	L	R	L	R		
1	2	12	16	16	18	18	105	105	105	105
2	10	10	15	16			105	105	105	105
3										
4										
5										

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: w/o #23360 Torque Tag # 42768

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Date: _____
Signature

PRESENT THIS COPY WHEN REGISTERING VEHICLE