

03801966

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE



Vehicle Standards and Inspection
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920



A794658

Date Inspection Started: 02 06 25
Date Inspection Completed: 09 06 25
Inspection Expiry Date: 30 06 26

Station Number: A6224
Station Name: Wildwood Transport Inc
Mechanic Number: M7606
Mechanic Signature: [Signature]
City: [Blank]
Station Phone Number: 204-957-8866
Vehicle Owner: Wildwood Transport Inc
Address: 100 Oakland Rd
City: Oak Bluff
Province: MB
Postal Code: R3R 3J3
Phone: [Blank]

Pass/Safe Vehicle
Fail/Unsafe Vehicle
Fail/Hazardous
Licence Number: 5J3156
Prov.: MB
NSC #: [Blank]
Odometer Reading: 565,972
Odom. Type: km mi
Vehicle Identification Number: 1RND4BA256R013431
Make: Retinover
Model: Deck
Year: 2006
Unit #: 5805
 Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck KGS Truck Tractor Trailer Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

P	R	Section	Defects (if any)	Notes
N/A		Section 1 - Power Train	Defects (if any)	
X	X	Section 2 Suspension	Defects (if any)	Replaced HCV & PPV (x-5f)
X	X	Section 3 - Brake Systems	Defects (if any)	3H BA Replace glad hands (x-13a) Replace seized clevis pins (x-16c) Replace s-cam tubes (x-16a)
N/A		Section 4 - Steering	Defects (if any)	
X		Section 5 - Instruments & Auxiliary Equipment	Defects (if any)	
X	X	Section 6 - Lamps	Defects (if any)	Center 10 light (x-1j)
X		Section 7 - Electrical System	Defects (if any)	
X	X	Section 8 - Body	Defects (if any)	Dolly crank stow handle (x-22a) Weld bumper (x-12c)
X		Section 9 - Tire & Wheel	Defects (if any)	
X		Section 10 - Coupling Devices	Defects (if any)	

Axle	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	12	8	16	13	105	105	105	105
2	15	15	8	10	105	105	105	105
3			8	10				
4								
5								

Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining		Drum/Rotor		Stroke	
	L	R	L	R	L	R
1	9/16	3/4	16.575	16.572	1 1/2	1 1/2
2	13/16	13/16	16.565	16.562	1 1/2	1 1/2
3						
4						
5						
Final Measurement						

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: w/o # 23292

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Date: _____
Signature

FVS0022-01-(R-09/15)

Ce document peut être obtenu en français sur demande.

PRESENT THIS COPY WHEN REGISTERING VEHICLE