

03801974

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE



Vehicle Standards and Inspections  
Box 45064 Regent Postal Outlet  
Winnipeg, MB, R2C 5C7  
1-204-985-0920



Date Inspection Started: 07 07 25  
 Date Inspection Completed: 21 07 25  
 Inspection Expiry Date: 31 07 26

Station Number: A6224  
 Station Name: Wildwood Transport Inc.  
 City: Oak Bluff  
 A794666

Mechanic Number: M7606  
 Mechanic Signature: [Signature]  
 Station Phone Number: 204-957-8866

Vehicle Owner: Wildwood Transport Inc.  
 Address: 100 Oakland Rd  
 City: Oak Bluff  
 Province: MB  
 Postal Code: R3R3S3  
 Phone: [Blank]

Pass/Safe Vehicle  
 Fail/Unsafe Vehicle  
 Fail/Hazardous

Licence Number: 5J3154  
 Prov: MB  
 NSC #: [Blank]

Vehicle Identification Number: 1RND48A2X6R014283  
 Make: Retriever  
 Model: Deck  
 Year: 2006  
 Unit #: 5804

Odometer Reading: 478,045  
 Odom. Type:  km  mi

Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck  GVWR  KGS  Truck Tractor  Trailer  Semi-Trailer  Bus  School Bus  Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
N/A		Section 1 - Power Train: Defects (if any)
X		Section 2 Suspension: Defects (if any)
X	X	Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type Glad hands X-13a Clevis pins RF X-16c Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection
N/A		Section 4 - Steering: Defects (if any)
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
X	X	Section 6 - Lamps: Defects (if any) Nose plug X-3b Brake light X-1d Strobes X-1g 10 lights X-1j
X		Section 7 - Electrical System: Defects (if any)
X		Section 8 - Body: Defects (if any)
X		Section 9 - Tire & Wheel: Defects (if any) RF
X		Section 10 - Coupling Devices: Defects (if any)

Axle	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	16	16	11	11	105	105	105	105
2	10	10	14	14	105	105	105	105
3								
4								
5								

- THIS INSPECTION IS NOT A WARRANTY -  
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: w/o # 23516 Retorque Tag # 42860  
Inspected by Dan Repairs by Slater

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: \_\_\_\_\_ Date: \_\_\_\_\_  
Signature

PRESENT THIS COPY WHEN REGISTERING VEHICLE