

03801974

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba K06-6

Vehicle Standards and Inspections Box 45064 Regent Postal Centre Winnipeg, MB, R2C 3C7 1-204-985-0920



Date Inspection Started: 07/07/25
 Date Inspection Completed: 21/07/25
 Inspection Expiry Date: 31/07/26

Station Number: A16224
 Station Name: Wildwood Transport Inc
 City: A794666
 Mechanic Number: M7606
 Mechanic Signature: [Signature]
 Station Phone Number: 204-957-8866

Vehicle Owner: Wildwood Transport Inc.
 Address: 100 Oakland Rd
 City: Oak Bluff MB
 Postal Code: R3R353
 Phone: [Blank]

Pass/Safe Vehicle
 Fail/Unsafe Vehicle
 Fail/Hazardous

Licence Number: 5J3154
 Prov: MB
 NSC #: [Blank]
 Odometer Reading: 478,045
 Odom. Type: km mi

Vehicle Identification Number: LRND48A2X16R014283
 Make: Renault
 Model: Dece
 Year: 2006
 Unit #: 5804

Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck GWR KGS Truck Tractor Trailer Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
N/A		Section 1 - Power Train: Defects (if any)
X		Section 2 Suspension: Defects (if any)
X	X	Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type Glad hands X-15a Clevis pins RF X-16c
N/A		Section 4 - Steering: Defects (if any)
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
X	X	Section 6 - Lamps: Defects (if any) Nose plug X-3b Brake light X-1d Strokers X-1g 10 lights X-1j
X		Section 7 - Electrical System: Defects (if any)
X		Section 8 - Body: Defects (if any)
X		Section 9 - Tire & Wheel: Defects (if any) [Signature]
X		Section 10 - Coupling Devices: Defects (if any)

Axle	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	16	16	11	11	105	105	105	105
2	10	10	14	14	105	105	105	105
3								
4								
5								

Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining		Drum/Rotor		Stroke	
	L	R	L	R	L	R
1	9/16	9/16	16.416	16.348	1 1/2	1 1/2
2	3/4	9/16	16.545	16.590	1 1/2	1 1/2
3						
4						
5						

Final Measurement

- THIS INSPECTION IS NOT A WARRANTY - This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: W10# 23516 Rotorque Tag # 42860
 Inspected by Dan Repairs by Slater

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: Signature Date: