K08-1

Commercial Vehicle Inspection Report

Decal Number: GP60334
Decal Expiry Date: 2027-Oct-31
Inspection Number: 21965935 2026282

Inspection Result: PASS

FACILITY:	DEVON TRUCK SERVICE LTD / S14790	**INSP. TYPE:**	Complete	**INSP. START:**	2026-Oct-23 03:00 PM PDT
INSPECTOR:	Gill, Navreet Singh / 201425	**INSP. CLASS:**	Class 3 - Trailer and Semi-Trailer	**INSP. COMPLETE:**	2026-Oct-23 05:00 PM PDT
WORK ORDER #:		**INSP. REASON:**	Annual		

VEHICLE JUR:	British Columbia	**REGI:**	01843451	**VIN:**	2BGR0813341016461
PLATE #:	48529W	**UNIT/FLEET#:**	59B	**OWNER/LESSEE NAME:**	SAFEWAY SERVICES LTD, .
LICENCED GVW(kg):	999999	**BODY STYLE:**	Flat Deck Trailer	**ADDRESS:**	205-15299 68 AVE
VEHICLE YEAR:	2004	**ODOMETER:**			Surrey, British Columbia
MAKE:	DOEPKER	**HUB ODOMETER:**			V3S2C1, Canada
MODEL:		**BRAKE TYPE:**	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Not Applicable	
Section 2 - Suspension	Passed	
Section 3 - Brake System	**Repaired (same day)**	SECURE RUBBING HOSES
Section 3A - Air Brakes	**Repaired (same day)**	SECURE RUBBING HOSES
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Not Applicable	
Section 5 - Instruments and Auxiliary Equipment	Not Applicable	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	**Repaired (same day)**	REPAIR DECK AND WELD CRACKS
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Not Applicable	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	35	34
2	Clamp	30	Automatic	34	34

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
5	4	9	6	
9	4	5	8	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	50	70
2	32	28

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	17	15
Lining (Shoe)	19	19

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No **Road Test Date:** **Road Tester:**

Inspector: Gill, Navreet Singh **Signature:**

This Inspection Report was submitted to CVSE on 2026-Oct-23 08:55 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

10/23/2026 8:55:18 PM PDT