Commercial Vehicle Inspection Report

BRITISH COLUMBIA

Decal Number:	GP60333	Inspection Result:	
Decal Expiry Date:	2027-Oct-31		
Inspection Number:	21965929	2026282	PASS

FACILITY:	DEVON TRUCK SERVICE LTD / S14790	INSP. TYPE:	Complete	INSP. START:	2026-Oct-23 12:00 PM PDT
		INSP. CLASS:	Class 3 - Trailer and Semi-Trailer	INSP. COMPLETE:	2026-Oct-23 02:30 PM PDT
INSPECTOR:	Gill, Navreet Singh / 201425	INSP. REASON:	Annual		
WORK ORDER #:					

VEHICLE JUR:	British Columbia	REGI:	01843417	VIN:	2DEHBFZ3541016460
PLATE #:	48530W	UNIT/FLEET#:	59A	OWNER/LESSEE NAME:	SAFEWAY SERVICES LTD, .
LICENCED GVW(kg):	999999	BODY STYLE:	Flat Deck Trailer	ADDRESS:	205-15299 68 AVE
VEHICLE YEAR:	2004	ODOMETER:			Surrey, British Columbia
MAKE:	DOEPKER	HUB ODOMETER:			V3S2C1, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Not Applicable	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Repaired (same day)	FIX RUBBING HOSES REPLACE AXLE# #1 RHS BRAKE AND AXLE#3 BOTH BRAKES AND FIX ABS
Section 3A - Air Brakes	Repaired (same day)	FIX RUBBING HOSES REPLACE AXLE# #1 RHS BRAKE AND AXLE#3 BOTH BRAKES AND FIX ABS
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Not Applicable	
Section 5 - Instruments and Auxiliary Equipment	Not Applicable	
Section 6 - Lamps	Repaired (same day)	FIX MARKER LIGHTS
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Repaired (same day)	FIX DECK AND WELD CRACKS
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Not Applicable	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	34	34
2	Clamp	30	Automatic	33	34
3	Clamp	30	Automatic	35	35

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
4	4	10	10	
11	11	10	16	
5	6	9	8	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	68	21
2	76	72
3	19	21

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	15	21
Lining (Shoe)	14	15
Lining (Shoe)	21	21

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No **Road Test Date:**

Inspector: Gill, Navreet Singh **Signature:** **Road Tester:**

This Inspection Report was submitted to CVSE on 2026-Oct-23 08:47 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement