



Commercial Vehicle
Inspection Report

Decal Number: GK49145
Decal Expiry Date: 2026-Aug-31
Inspection Number: 21447090

209-1
Inspection Result:
PASS

FACILITY:	ACCELERATED MECHANICAL LTD. / S16580	INSP. TYPE:	Complete	INSP. START:	2025-Aug-01 08:30 AM PDT
INSPECTOR:	Harilstad, Milton John / 102798	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2025-Aug-01 09:30 AM PDT
WORK ORDER #:	8288	INSP. REASON:	Annual		
VEHICLE JUR:	British Columbia	REGI:	10602701	VIN:	3BPPHM7X2DF590307
PLATE #:		UNIT/FLEET#:		OWNER/LESSEE NAME:	SKELTER IMPORTS INC., DBA EXXEL TRUCK AND EQUIPMENT
PERMITTED GVW(kg):	14515	BODY STYLE:	Van	ADDRESS:	11445 KITCHEN ROAD, 11445 KITCHEN ROAD Chilliwack, British Columbia V2P6H5, Canada
VEHICLE YEAR:	2013	ODOMETER:	379493 KM		
MAKE:	PETERBILT	HUB ODOMETER:			
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:	Diesel		

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	20	Automatic	37	37	12			12	✓
2	Clamp	30	Automatic	38	38	13	13	13	13	
Comment:						Comment:				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right	
1	30	30	Lining (Shoe)	20	20	Drum	0.00	0.00	
2	30	30	Lining (Shoe)	20	20	Drum	0.00	0.00	
Comment:			Comment:			Comment:			

Inspection Comments:

Has this Vehicle been road tested?	No	Road Test Date:		Road Tester:	
Inspector:	Harilstad, Milton John	Signature:			

This Inspection Report was submitted to CVSE on 2025-Aug-01 09:42 AM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.