



Vehicle History Summary

Fleet #	LE21
Registration	XN41HR
Make	Mitsubishi
Model	(FR21)
VIN / Chassis #	JMFFM618LOMK00003
Build Date	1998

Date	Reading / Units	Type / Repairer Notes	Repairer
		Hydraulics lerak R-299	
18/02/2026	1,223 hrs	C - 1000hrs S-733 body has big cracks in it not good need to replace the floor asap rams liking needs to be replaced	
22/05/2025	778 hrs	front window, washers R-377 unblocked hose	
03/04/2025	714 hrs	fire extinguisher R-345 replaced with new one	
21/02/2025	699 hrs	B - 500hrs S-563	
27/01/2025		welding R-292 weled bracket back on	
24/07/2024	268 hrs	A - 250hrs S-340	
18/06/2024	569,038 kms 153 hrs	fire extinguisher, Lights R-197 put one in fire extinguisher replaced globe lh front park ight	
22/04/2024	43 hrs	Cab R-142 replaced cable	
25/03/2024		Registration O-38	NSW Transport
30/11/2023	561,845 kms	A - 10K S-184 not to bee driven until repairs are done	
30/11/2023	561,845 kms	Chassis R-103 put new pin on the tail gate	
17/05/2023	550,809 kms 11 hrs	A - 250hrs S-141 Please refer attached Maintenance Report Hours estimated by 50km per/h	
04/08/2021	507,774 kms	fan belt's R-60 ajust fan belt's	Internal Workshop
28/05/2021	506,572 kms	Cab R-26 Put new fire extinguisher in	Internal Workshop
11/05/2021	505,709 kms	seat R-6 pulled drivers seat out and took to a upholster to get cushion replaced.	Internal Workshop

Signed: _____

Name: _____

Date: _____