



Vehicle History Summary

Fleet #	LE42
Registration	XO49BU
Make	MERCEDES BENZ
Model	2228S/30
VIN / Chassis #	62313065219854
Build Date	11/87

Date	Reading / Units	Type / Repairer Notes	Repairer
Plant Risk Assessment I-59			
11/11/2024	1,213 hrs	A - 250hrs S-491	
08/11/2024		Registration O-79	NSW Transport
08/11/2024		CTP O-80	QBE Insurance
22/07/2024	646,499 kms 1,030 hrs	heater R-207 put red dot in back of cab	
11/07/2024	646,499 kms 1,102 hrs	mirror R-223 welled up bracket put new mirror on RH side	
22/04/2024	955 hrs	water tank R-147 cut rusted baffles out sandblast tank inside paint inside fill with baffles balls fixed drivers seat	
09/04/2024	955 hrs	C - 1000hrs S-270	
21/12/2023	646,496 kms 774 hrs	safety R-121 put safety sticker kits on	
21/12/2023	774 hrs	A - 250hrs S-196	
01/07/2023		E S-117 Service Completed. Put the new water pump on.	

Signed: _____
Name: _____
Date: _____