



Vehicle History Summary

Fleet #	LE72
Registration	44810E
Make	CAT
Model	D6TXL Bulldozer (LG72)
VIN / Chassis #	CAT00D6THDSTD00176
Build Date	2012

Date	Reading / Units	Type / Repairer Notes	Repairer
		Hydraulics lerak R-308	
04/02/2026	17,623 hrs	D - 2000hr S-721 front yorks bearings new G.E.T HYDRAULIC SUCTION pipe equalizer bar bearings rh hand pivot shaft seal reverse camera transmission pump input seal	
18/08/2025	17,337 hrs	A - 250hr S-665 pivot sharft leaking right side replaced brake valve	
18/08/2025		grease R-368 just got told to pu nipelss on all done	
19/03/2025	17,102 hrs	trans R-336 replaced modulator valve clutch 1 and 2 calibrated trans	
12/03/2025	17,062 hrs	C - 1000hr S-570 it has not been grease properly washed out coolers out RH hand side pivot shaft leaking play in the equalizer bar riper cyders are leaking	
11/03/2025		gps R-322 put tape around it and tighten it up for now	
06/02/2025		A/C R-281	Power International Auto Electrics
13/12/2024	16,714 hrs	A - 250hr S-531	
24/09/2024	16,500 hrs	B - 500hr S-474	
18/04/2024	16,038 hrs	GET R-141 corner tips and riper boots	
27/03/2024		Engine R-140 Diagnose cause of engine missfire Remove and replace engine with cat reman, Rebuild torque convertor Tidy up oil leaks and replace leaking hoses under cab and in hole,	Capital Plant Repairs (ACT) Pty Ltd
07/02/2024		Registration O-25	NSW Transport
07/02/2024		CTP O-26	NSW Transport
16/01/2024	15,829 hrs	E - 4000hr S-405 up date hrs	
16/01/2024	15,829 hrs	A - 250hr S-190	
12/12/2023	15,802 hrs	fuel leak R-113 got the fuel hose repaired	

Signed: _____

Name: _____

Date: _____