



Commercial Vehicle Inspection Report

Decal Number: GP27496
Decal Expiry Date: 2027-Jan-31
Inspection Number: 21863332

Inspection Result:

PASS

2026253

FACILITY: HARKO HEAVY DUTY LTD. / S17130
INSPECTOR: KRAJNC, HAYDEN / 202196
WORK ORDER #: ROCK RL UNIT 108
VEHICLE JUR: British Columbia
PLATE #: 84412P
LICENCED GVW(kg): 63500
VEHICLE YEAR: 2021
MAKE: INTERNATNA
MODEL:
INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Semi-annual
INSP. START: 2026-Jul-28 07:00 AM PDT
INSP. COMPLETE: 2026-Jul-28 08:25 AM PDT
REGI: 13431791
UNIT/FLEET#: 108
BODY STYLE: Truck Tractor
ODOMETER: 429196 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 3HSLGAPR1M263279
OWNER/LESSEE NAME: P.A. WALKER CAPITAL, LTD.
ADDRESS: 2-734 LAVAL CRES
Kamloops, British Columbia
V2C 5P3, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Repaired (same day) REPLACED AXLE 3 SHOCKS.
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) REPLACED 3L BRAKE POT.
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) SECURED FENDERS.
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axes	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	37	37	12			12	
2	Clamp	30L	Automatic	40	41	6	6	6	6	
3	Clamp	30L	Automatic	41	40	8	8	8	8	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axes	Left	Right	Brake Lining/Pad (mm)	Left	Right	Rotor Thickness or Drum Inside Diameter (mm)	Left	Right
1	50	50	Lining (Shoe)	17	17	Drum		
2	75	65	Lining (Shoe)	14	16	Drum		
3	55	40	Lining (Shoe)	17	18	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested?

No

Road Test Date:

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Jul-28 02:53 PM PDT.

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorizing inspectors, and designating inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSE014
7/28/2026 2:53:33 PM PDT