



# Vehicle History Summary

Fleet #	LE06
Registration	84520D
Make	Volvo
Model	ECR145CL
VIN / Chassis #	VCECR145L00110876
Build Date	2016

Date	Reading / Units	Type / Repairer Notes	Repairer
11/12/2025	9,320 hrs	<b>A - 250hr</b> S-714	
29/07/2025	8,945 hrs	<b>A - 250hr</b> S-654	
18/02/2025	8,786 hrs	<b>Hydraulics lerak</b> R-297 new hose	
05/12/2024	8,585 hrs	<b>B - 500hr</b> S-519	
25/09/2024	8,389 hrs	<b>hose</b> R-259 bend pipes and replace hoses	Enzed Service Centre Canberra
12/06/2024	8,144 hrs	<b>D - 5000hr</b> S-390 just to get hr up to date	
12/06/2024	8,144 hrs	<b>A - 500hr</b> S-310	
01/03/2024	7,938 hrs	<b>Radiator</b> R-134 new header bottle	
02/02/2024	7,808 hrs	<b>A - 500hr</b> S-210	
12/01/2024		<b>Registration</b> O-15	NSW Transport
07/09/2023	7,500 hrs	<b>A - 250hr</b> S-187 750 hr service	
24/07/2023		<b>Plant Risk Assessment</b> I-45 Refer to Plant Assessor Risk Management Report	
09/04/2023	7,266 hrs	<b>A - 250hr</b> S-132 Needs new belts	
25/11/2021	6,030 hrs	<b>D - 2000hr</b> S-58	Internal Workshop
24/09/2021		<b>A - 250hr</b> S-38	Internal Workshop
16/06/2021	5,560 hrs	<b>undercarriage</b> R-33 Replace Idler	Internal Workshop
20/05/2021	5,508 hrs	<b>undercarriage</b> R-22 Put left-hand track back on	Internal Workshop
13/05/2021	5,474 hrs	<b>B - 500hr</b> S-3 Lh front idler worn needs replacing Put new horn on as well	Internal Workshop
13/05/2021	5,474 hrs	<b>Radiator</b> R-9	Internal Workshop

Date	Reading / Units	Type / Repairer Notes	Repairer
13/05/2021	5,474 hrs	<b>Battery R-8</b> Replace with new horn	Internal Workshop
13/05/2021	5,474 hrs	<b>Engine R-7</b> Drain coolant pulled hose off cleaned up re-clamped	Internal Workshop

Signed: \_\_\_\_\_

Name: \_\_\_\_\_

Date: \_\_\_\_\_