



# Commercial Vehicle Inspection Report

Decal Number: GJ80827  
Decal Expiry Date: 2026-Jun-30  
Inspection Number: 21380408

Inspection Result:

**PASS**

**FACILITY:** DAWSON INTERNATIONAL TRUCK CENTRES LTD. / S5959  
**INSPECTOR:** BROOMFIELD, DAVID RICHARD / 112886  
**WORK ORDER #:** 4692  
**VEHICLE JUR:** British Columbia  
**PLATE #:** 2C4N3F  
**LICENCED GVW(kg):** 9001  
**VEHICLE YEAR:** 2007  
**MAKE:** GMC  
**MODEL:**

**INSP. TYPE:** Complete  
**INSP. CLASS:** Class 2 - Heavy Vehicle with LGVW 5501 kg or more  
**INSP. REASON:** Annual  
**REGI:** 00925381  
**UNIT/FLEET#:**  
**BODY STYLE:** Utility Truck  
**ODOMETER:** 390127 KM  
**HUB ODOMETER:**  
**BRAKE TYPE:** Hydraulic  
**FUEL TYPE:** Diesel

**INSP. START:** 2025-Jun-05 10:00 AM PDT  
**INSP. COMPLETE:** 2025-Jun-05 12:00 PM PDT  
**VIN:** 1GDE5C1987F417682  
**OWNER/LESSEE NAME:** ATCHISON CORAL DAWN, ATCHISON CORAL DAWN  
**ADDRESS:** PO BOX 113  
McLeese Lake, British Columbia  
V0L1P0, Canada

**Vehicle Identification (VIN)** Passed  
**Section 1 - Power Train** Passed  
**Section 2 - Suspension** Passed  
**Section 3 - Brake System** Passed  
**Section 3H - Hydraulic Brakes** Passed  
**Section 4 - Steering** Passed  
**Section 5 - Instruments and Auxiliary Equipment** Passed  
**Section 6 - Lamps** Passed  
**Section 7 - Electrical System** Passed  
**Section 8 - Frame and Body** Passed  
**Section 9A - Tires** Passed  
**Section 9B - Wheels** Passed  
**Section 10 - Coupling Devices** Passed  
**Section 11 - Other Vehicle Components** Not Applicable

Tire Tread Depth (mm)						Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Outer L	Inner L	Inner R	Outer R	Steering	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	14			14	✓	Pad	16	17	Rotor	38.60	38.40
2	13	13	13	13		Pad	12	11	Rotor	38.00	38.50

**Comment:**

## Inspection Comments:

Has this Vehicle been road tested? No  
Inspector: BROOMFIELD, DAVID RICHARD  
Road Test Date: 2/3  
Signature: [Signature]  
Road Tester:

This Inspection Report was submitted to CVSE on 2025-Jun-05 04:01 PM PDT  
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

## NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on the form is collected under the authority of section 218 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVP at the Commercial Vehicle Safety Enforcement.

CVSE0014

6/5/2025 4:01:42 PM PDT



# Commercial Vehicle Inspection Report

Decal Number: GJ80827  
Decal Expiry Date: 2026-Jun-30  
Inspection Number: 21380408

Inspection Result:  
**PASS**

FACILITY:	DAWSON INTERNATIONAL TRUCK CENTRES LTD. / S5959	INSP. TYPE:	Complete	INSP. START:	2025-Jun-05 10:00 AM PDT
INSPECTOR:	BROOMFIELD, DAVID RICHARD / 112886	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2025-Jun-05 12:00 PM PDT
WORK ORDER #:	4692	INSP. REASON:	Annual		
VEHICLE JUR:	British Columbia	REGI:	00925381	VIN:	1GDE5C1987F417682
PLATE #:	2C4N3F	UNIT/FLEET#:		OWNER/LESSEE NAME:	ATCHISON CORAL DAWN, ATCHISON CORAL DAWN
LICENCED GVW(kg):	9001	BODY STYLE:	Utility Truck	ADDRESS:	PO BOX 113
VEHICLE YEAR:	2007	ODOMETER:	390127 KM		McLeese Lake, British Columbia
MAKE:	GMC	HUB ODOMETER:			V0L1P0, Canada
MODEL:		BRAKE TYPE:	Hydraulic		
		FUEL TYPE:	Diesel		

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3H - Hydraulic Brakes	Passed
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Tire Tread Depth (mm)						Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Outer L	Inner L	Inner R	Outer R	Steering	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	14			14	✓	Pad	16	17	Rotor	38.60	38.40
2	13	13	13	13		Pad	12	11	Rotor	38.00	38.50
Comment:						Comment:			Comment:		

## Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: 9/3 Road Tester:  
Inspector: BROOMFIELD, DAVID RICHARD Signature: [Signature]

This Inspection Report was submitted to CVSE on 2025-Jun-05 04:01 PMPDT  
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

## NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

6/5/2025 4:01:42 PM PDT