

Commercial Vehicle Inspection Report

Decal Number: GN85336
Decal Expiry Date: 2027-Jan-31
Inspection Number: 21842923

K12-1
Inspection Result: **PASS**
2026232

CITY: RIGID TRUCK & TRAILER LTD / S15450
SPECTOR: HUBER, PAUL RAYMOND / 101751
DRK ORDER #:

INSPECTION TYPE: Complete
INSPECTION CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSPECTION REASON: Semi-annual

INSPECTION START: 2026-Jul-07 09:54 AM PDT
INSPECTION COMPLETE: 2026-Jul-10 09:55 AM PDT

VEHICLE JURISDICTION: British Columbia
VEHICLE #: PD5041
PERMITTED GVW(kg): 26100
VEHICLE YEAR: 2003
MAKE: INTERNATNA
MODEL:

REGISTRATION: 02214759
UNIT/FLEET#:
BODY STYLE: Flat Deck
ODOMETER: 507965 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 1HTWYAHT73J073827
OWNER/LESSEE NAME: KENROC , BUILDING MATERIALS
ADDRESS: 2401 UNITED BLVD.
Coquitlam, British Columbia
V3K 5X9, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) VISOR LIGHT OUT
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) DRIVERS SEAT CUSHION
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Not Applicable
Section 11 - Other Vehicle Components	Passed

Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	38	40	10			10	✓
2	Clamp	30	Automatic	42	42	8	8	8	8	
3	Clamp	30	Automatic	40	40	8	8	8	8	

Comment:

Comment:

Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	30	35	Lining (Shoe)	19	19	Drum		
2	85	85	Lining (Shoe)	12	11	Drum		
3	90	90	Lining (Shoe)	12	11	Drum		

Comment:


Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Is this Vehicle been road tested? No
Inspector: HUBER, PAUL RAYMOND

Road Test Date:
Signature:



Road Tester:

This Inspection Report was submitted to CVSE on 2026-Jul-10 09:55 AM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

Personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement.

SED014

07/2026 9:56:31 AM PDT