



Commercial Vehicle Inspection Report

Decal Number: GL08022
Decal Expiry Date: 2026-Mar-31
Inspection Number: 21508023

K12-2225
Inspection Result:
PASS

FACILITY:	HARKO HEAVY DUTY LTD. / S17130	INSP. TYPE:	Complete	INSP. START:	2025-Sep-23 04:02 PM PDT
INSPECTOR:	KRAJNC, HAYDEN / 202196	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2025-Sep-23 05:33 PM PDT
WORK ORDER #:	ALEX PIQUETTE 07 FREIGHTLINER	INSP. REASON:	Semi-annual		
VEHICLE JUR:	British Columbia	REGI:	13929969	VIN:	1FUJA6AV16DV34536
PLATE #:	G87650	UNIT/FLEET#:		OWNER/LESSEE NAME:	PIQUETTE, ALEX MATHEW
LICENCED GVW(kg):	45000	BODY STYLE:	Truck Tractor	ADDRESS:	4749 HEFFLEY-LOUIS CREEK RD, 4749 HEFFLEY-LOUIS CREEK RD Heffley Creek, British Columbia V0E1Z1, Canada
VEHICLE YEAR:	2006	ODOMETER:	1875628 KM		
MAKE:	FREIGHTLIN	HUB ODOMETER:			
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Repaired (same day) TIGHTENED LOOSE U-JOINT CAP BOLTS.
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) REPLACED 3L PIGGYBACK.
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Repaired (same day) ADJUSTED TOE.
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	20	Automatic	34	33	14			14	✓
2	Clamp	30L	Automatic	40	41	15	16	16	16	
3	Clamp	30L	Automatic	39	40	16	16	15	16	
Comment:						Comment:				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	65	55	Lining (Shoe)	16	17	Drum		
2	80	65	Lining (Shoe)	13	16	Drum		
3	45	81	Lining (Shoe)	18	13	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date:  Road Tester:

Inspector: KRAJNC, HAYDEN Signature: _____

This Inspection Report was submitted to CVSE on 2025-Sep-24 10:46 AMPDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.