Commercial Vehicle Inspection Report

BRITISH COLUMBIA

K14-1
2026282

Decal Number:	GP32371
Decal Expiry Date:	2027-Feb-28
Inspection Number:	21873765

Inspection Result: **PASS**

FACILITY:	A.M.T.AUTOMOTIVE MACHINEX / S4223	**INSP. TYPE:**	Complete	**INSP. START:**	2026-Aug-06 10:01 AM PDT
INSPECTOR:	GOSAL, RAGHUBIR SINGH / 105207	**INSP. CLASS:**	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	**INSP. COMPLETE:**	2026-Aug-06 12:02 PM PDT
WORK ORDER #:	21027	**INSP. REASON:**	Semi-annual		

VEHICLE JUR:	British Columbia	**REGI:**	13068023	**VIN:**	2FZHAZCV67AY89304
PLATE #:	XA6772	**UNIT/FLEET#:**		**OWNER/LESSEE NAME:**	ATEEQ TRUCKING LTD., NA
LICENCED GVW(kg):	25500	**BODY STYLE:**	Dump Truck	**ADDRESS:**	7288 SHERBROOKE STREET, 7288 SHERBROOKE STREET
VEHICLE YEAR:	2007	**ODOMETER:**	22528 KM		Vancouver, British Columbia
MAKE:	STIRLING	**HUB ODOMETER:**			V5X4E2, Canada
MODEL:		**BRAKE TYPE:**	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	**Repaired (same day)**	ADJUSTED CLUTCH FREE-PLAY
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Passed	
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Not Applicable	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24L	Automatic	30	30
2	Clamp	30L	Automatic	34	34
3	Clamp	30L	Automatic	34	34

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
18			16	✔
15	15	13	13	
15	15	15	15	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	65	65
2	45	45
3	40	45

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	15	15
Lining (Shoe)	21	21
Lining (Shoe)	20	20

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No **Road Test Date:** **Road Tester:**

Inspector: GOSAL, RAGHUBIR SINGH **Signature:**

This Inspection Report was submitted to CVSE on 2026-Aug-06 12:02 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

8/6/2026 12:02:30 PM PDT