

YO44CJ	Tyres	12.03.2024	Sydney Tyre Service	1x Tyre Puncture Repair
YO44CJ	Repairs	15.05.2024	DG Auto	<p>MAXITRANS QUINN DOG TRAILER  REGO.: YO-44CJ  KMS.: 642,846</p> <ul style="list-style-type: none"> <li>- CHECK OVER LIGHTS ON DOG TRAILER</li> <li>- FOUND 1x SIDE MARKER LIGHT NOT WORKING</li> <li>- TRACE FAULT TO CORRODED WIRE</li> <li>- CUT OUT CORRODED SECTION AND REPLACE SECTION OF WIRE</li> <li>- RE-TEST</li> <li>- FOUND OK</li> <li>- CHECK FOR LEFT HAND TAIL AND BRAKE LIGHT INOPERATIVE</li> <li>- FOUND CONNECTIONS CORRODED</li> <li>- CUT OUT CORRODED CONNECTIONS</li> <li>- RECONNECT AND REPLACE SECTIONS OF WIRE AS NEEDED</li> <li>- RE-TEST OK</li> <li>- REPLACE 1x LIGHT GROMMET AS RUBBER WENT HARD</li> <li>- RE-TEST ALL LIGHTS</li> </ul>
YO44CJ	Tyres	22.05.2024	Bridgestone Australia	1 x Puncture Repair
YO44CJ	Service	20.06.24	MSC Mechanicals	<p>TRAILER - REGO - YO44CJ</p> <p>Carried out rear axle brake reline. Supplied and fitted new brake shoes and hardware.</p> <p>Supplied and fitted new brake drums. Refitted wheels and tensioned.</p> <p>Supplied and fitted new air bag to O/S rear axle. Supplied and fitted new mudguard and bolts to N/S rear.</p> <p>Carried out brake reline on 2nd axle O/S. Supplied and fitted new brake shoes and hardware.</p> <p>Supplied and fitted new brake drums. Supplied and fitted new ABS sensor. Refitted wheels and tensioned.</p>
YO44CJ	Repairs	07.02.2025	DG Auto	<p>6/02/2025</p> <ul style="list-style-type: none"> <li>- CHECK FOR TARP NOT WORKING</li> <li>- FOUND FAULTY BATTERY</li> <li>- CHECK FOR CHARGING SYSTEM WORKING FROM FROM TRUCK</li> <li>- FOUND OK</li> <li>- CONNECTED JUMPER LEADS TO TEST TARP</li> <li>- FOUND TARP SYSTEM OK</li> </ul> <p>7/02/2025</p> <ul style="list-style-type: none"> <li>- REPLACE BATTERY</li> <li>- MODIFY BRACKET TO SUIT AS BATTERY WAS AB IT DIFFERENT IN SIZE</li> <li>- REPLACE TERMINALS AS NEEDED ON WIRES GOING TO BATTERY DUE TO CORROSION</li> <li>- TEST TARP OPERATION</li> <li>- FOUND OK</li> <li>- TEST BATTERY CHARGING</li> <li>- FOUND OK</li> <li>- RE-FIT COVER ON TO BATTERY</li> </ul>