

XO13WD	Service	01.11.2023	MSC Mechanical	Carried out service. Supplied and fitted new oil and filters. Supplied and fitted new fuel filters. Supplied and fitted new air filters. Carried out full chassis and tipper grease. Carried out 2nd steer brake reline. Supplied and fitted new brake shoes and hardware. Supplied and fitted new brake drums. Refitted wheels. Adjusted brakes. Carried out Brown Slip inspection on both truck and trailer.
XO13WD	Repairs	06.11.2023	DG Auto	KENWORTH K200 REGO.: XO-13WD KMS.: 658,877 3/11/2023 - TRAVEL TO BRINGELLY YARD WHEN VEHICLE COME BACK FROM WORK - CHECK FOR AIR CONDITIONER NOT WORKING - DROP BULL BAR AND JACK CABIN - FOUND A/C COMPRESSOR CLUTCH BROKEN - NEED TO ORDER NEW A/C COMPRESSOR - PUT CABIN BACK DOWN AND BULL BAR BACK UP 6/11/2023 - TRAVEL TO BRINGELLY YARD - DROP BULL BAR AND JACK CABIN - DE-GAS A/C SYSTEM - REMOVE A/C COMPRESSOR AND RECIEVER DRIER - FLUSH OUT A/C SYSTEM - FIT NEW A/C COMRPRESSOR - FIT NEW A/C RECIEVER DRIER - PRESURE TEST SYSTEM FOR LEAKS - FOUND OK - RE-GAS A/C SYSTEM - TESTED OK
XO13WD	Service	19.11.2023	Impeccable Fleet	662652 XO13WD Carry out B service Replace 4th axle O/S Abs Sensor. Clear fault codes Weld all cracks on subframe Carry out steer hub seal replacement on 1st axle N/S. Fit new seal, oil, gasket and brake shoes. Replace tie rod ends on 2nd axle Replace 1st axle drag link Tighten through shaft yoke nut and replace universal joint Replace leaking Coolant filter
XO13WD	Service	05.01.2024	MSC Mechanical	KENWORTH K200 - REGO - XO13WD - 672,477KM Carried out NHVR Check list on Truck - (XO13WD) Carried out "A" service. Carried out full chassis grease. Checked and adjusted brakes Checked all wheel bearings. Replaced air filter. Found all rear shocks worn. Cut off old shocks. Fitted new shocks and rubbers. Found air leak while PTO activated. Found air fitting leaking. Removed and replaced fitting.
XO13WD	Tyres	22.01.2024	South west Car & Truck Tyres	2x Strip & Fits, 2x 11R225 Runouts
XO13WD	Repairs	09.02.2024	MSC Mechanical	Checked and adjusted brakes. Repaired clearance lights. Supplied and fitted new park light to tipper body on O/S.
XO13WD	Repairs	09.02.2024	DG AUto	CHECK FOR IROS TIPPING SENSOR SAYING INCORRECT ANGLE WHEN EVERY THING IS STRAIGHT - DISCONNECT IROS SYSTEM FROM VEHICLE - TEST VEHICLE FUNCTIONS

XO13WD	Repairs	12.02.2024	MSC Mechanical	<p>Carried out general service. Replaced engine oil and filter. Replaced primary and secondary fuel filters. Replaced air filter. Carried out full chassis grease. Checked diff and gearbox oils. Checked all lights. Checked body bolts. Checked and adjusted front and rear brakes. Front brakes have 9 mm remaining. Rear brakes have 9 mm remaining. Supplied and fitted new slack adjuster to rear O/S wheel. Supplied and fitted new exhaust stack and clamps. Checked clutch fault with computer. Cleared fault.</p>
XO13WD	Repairs	22.02.2024	SAR Industries Pty Ltd	<ul style="list-style-type: none"> - Wash and degrease down gearbox and truck. - Jack up truck. Remove gearbox, clutch and flywheel. Rear main seal leaking. - Remove rear flywheel housing and starter motor. Starter motor bolts cross threaded and stripped in flywheel housing and missing one top starter motor bolt. - Remove housing, fit exchange machined housing. - Fit new engine mounts and bolts (old flywheel housing could not be reused due to the damaged threads in the starter motor bolts). - Fit new rear main seal. - Fit up machined flywheel and new clutch kit. - Rebuild front of gearbox. Remove bell housing and replace bell housing gasket. Fit new input shaft and bearing. Fit new fork and cross shafts and bushes. - Refit gearbox. - Fill up with new full synthetic gearbox oil and replace gearbox filter. - Calibrate clutch and take truck for test drive, tested all
XO13WD	Tyres	28.02.2024	Sydney Tyre Service	2x yokohama 295/80R22.5 Tyres, 4x Double Star 11R22.5 Drive Tyres
XO13WD	Repairs	07.03.2024	DG AUto	<ul style="list-style-type: none"> - FIT AND WIRE PBS TRACKER - CHECK UNIT POWERED ON
XO13WD	Repairs	09.03.2024	DG AUto	<ul style="list-style-type: none"> - CHECK FOR DOG TRAILER BODY NOT GOING UP - PULL DASH APART - CHECK SWITCHES AND POWER IN AND OUT - CHECK FOR POWER TO SOLENOIDS - FOUND POWER OK - LOCATE SOLENOID FOR BODY UP - FOUND POWER TO IT BUT SOLENOID NOT PUTTING OUT AIR TO FUNCTION - SWAP OVER AIR LINE AND POWER WIRES WITH DOLLY LOCK SOLENOID - TEST FOR BODY GOING UP TEST FOR TRAILER TARP BATTERY CHARGING TEST TARP OPERATION - TEST ALL FUNCTIONS ON TRUCK AND TRAILER TIPPER BODIES - UP AND DOWN AND TAIL GATE OPEN - CHECK ALL LIGHTS ON TRAILER WORKING
XO13WD	Tyres	14.03.2024	Royales Truck Services	1x Second Hand Tyre Change
XO13WD	Repairs	17.04.2024	Multispare	Valve QRI 3/8" & Do Not Overtake Sign
XO13WD	Service	23.04.2024	MSC Mechanical	<p>Carried out general service. Replaced engine oil and filter. Replaced primary and secondary fuel filters. Replaced air filter. Carried out full chassis grease. Checked diff and gearbox oils. Checked all lights. Checked body bolts.</p>

				Checked and adjusted front and rear brakes. Front brakes have 10 mm remaining. Rear brakes have 10 mm remaining. Refitted mudflap to rear O/S
XO13WD	Repairs	09.05.2024	Sloanebuilt	200KG Landing Legs Mount Tube
XO13WD	Service	20.06.2024	MSC Mechanical	KENWORTH K200 REGO - XO13WD - 703,375KM CHASSIS NO - GA456312 Carried out "B" service. Supplied and fitted new engine oil and filter. Supplied and fitted new primary and secondary fuel filters. Supplied and fitted new air filter. Carried out full chassis grease. Checked diff and gearbox oils. Checked all lights. Checked and adjusted front and rear brakes. Front brakes have 10 mm remaining. Rear brakes have 10 mm remaining. Trailer brakes have 10 mm remaining. Inspected for trailer lazy axle not lifting. Found trailer ABS light on dash. Checked fuses for trailer ABS. Found both fuses blown. Found short in trailer circuit. Traced EBS lead on trailer draw bar and dolly. Found lead damaged in multiple spots. Removed harness in drawbar tube. Ran new ABS harness and trailer light harness. Ran harnesses through new protective sleeve. Cable tied up and fitted new trailer electrical plugs to drawbar end. Replaced trailer plug on rear of truck. Replaced fuses. Tested ABS system. Straightened steering wheel. TRAILER - REGO - YO44CJ Carried out rear axle brake reline. Supplied and fitted new brake shoes and hardware. Supplied and fitted new brake drums. Refitted wheels and tensioned. Supplied and fitted new air bag to O/S rear axle. Supplied and fitted new mudguard and bolts to N/S rear. Carried out brake reline on 2nd axle O/S. Supplied and fitted new brake shoes and hardware. Supplied and fitted new brake drums. Supplied and fitted new ABS sensor. Refitted wheels and tensioned.
XO13WD	Tyres	24.06.2024	Sydney Tyre Service	2x New Power 11R22.5 Drive Tyres
XO13WD	Repairs	01.07.2024	MSC Mechanical	Carried out defect repairs. Replaced axle 3 left slack adjuster
XO13WD	Repairs	10.07.2024	Heavy Automatics	Truck presented with faulty solenoids, remove old solenoids and fit new ones. Fix wiring and test operation OK.
XO13WD	Service	08.08.2024	MSC Mechanical	Carried out "A" Service. Cleaned and inspected air filter. Carried out full chassis grease. Checked all lights. Checked and adjusted front and rear brakes. Front brakes have 9 mm remaining. Rear brakes have 8 mm remaining.
XO13WD	Repairs	23.08.2024	MSC Mechanical	KENWORTH K200 - REGO - XO13WD - 715,349KM Inspected for vehicle not starting. Checked power to starter motor. Found no switching power. Traced harness on engine to bottom of cab. Found wiring rubbed through under driver's side floor. Cut apart harness. Repaired wiring. Conduited harness and re-secured. Cleaned up engine harness. Tested operation. Cleared all faults.
XO13WD	Repairs	02.10.2024	MSC Mechanical	Checked oil leak at front near radiator. Found P/S oil cooler leaking. Checked hoses and fittings. Ordered cooler. Removed P/S cooler. Bolts seized in spacers, hoses seized. Supplied and fitted new oil cooler. Supplied and fitted new bolts. Topped up P/S oil.

				Bled system and tested.
XO13WD	Repairs	17.10.2024	MSC Mechanical	Carried out "B" Service. Supplied and fitted new engine oil and filter. Supplied and fitted new primary and secondary fuel filters. Supplied and fitted new air filter. Carried out full chassis grease. Checked diff and gearbox oils. Checked all lights. Checked body bolts. Checked front and rear brakes. Front brakes have 10 mm remaining. Rear brakes at 8 mm remaining.
XO13WD	Tyres	22.11.2024	Sydney Tyre Service	2 x Yokohama 295/80R22.5
XO13WD	Repairs	29.11.2024	MSC Mechanical	KENWORTH K200 - REGO - XO13WD - 729,486KM Checked front suspension and steering. Found front steer pins worn on front steer. Removed steer hubs. Found wheel bearings worn. Supplied and fitted new wheel bearings. Supplied and fitted new hub seals and lock tabs. Stripped brakes and king pins. Supplied and fitted new king pin bushes to stud axles. Supplied and fitted new brake shoes hardware and drums. Supplied and fitted new lock tabs and hub caps. Supplied and fitted new shocks x 4 to front suspension. Carried out service. Supplied and fitted new oil and filter. Supplied and fitted new fuel filters. Supplied and fitted new air filter. Carried out full chassis grease. Checked brakes. Supplied and fitted new bushes to tap. U stay on rear axle on N/S.
XO13WD	Repairs	14.10.2024	DG Auto	REGO.: XO-13WD KMS.: 721,156 - CHECK FOR RADIO BLUETOOTH SYSTEM NOT WORKING - FOR PHONE HANDS FREE CALLS - FOUND FAULT IN AM/FM RADIO - REPLACE AM/FM RADIO - RE-TEST WORKING - FOUND OK - CHECK DASH LIGHTS BEFORE PUTTING DASH BACK TOGETHER - FOUND 3x NOT WORKING - REPLACE 3x DASH GLOBE HOLDERS AS OLD ONES BROKEN - RE-TEST - FOUND OK
XO13WD	Tyres	13.01.2025	Sydney Tyre Service	1x Tyre Puncture
XO13WD	Tyres	13.01.2025	Sydney Tyre Service	1x Tyre Puncture
XO13WD	Service	23.01.2025	MSC Mechanical	Carried out "B" service. Supplied and fitted new air filter. Carried out full chassis grease. Checked diff and gearbox oils. Checked all lights. Checked body bolts. Checked brakes. 1st axle brakes have 9 mm remaining. 2nd axle brakes have 9 mm remaining. 3rd axle brakes have 8 mm remaining. 4th axle brakes have 7 mm remaining. Fixed washer jets for wiper arms. Checked over vehicle. Repaired air leaks

XO13WD	Tyres	05.03.2025	Sydney Tyre Service	2x Yokohama 295/80R22.5 143/145M RY023, 2x Balance Truck Equal
XO13WD	Tyres	25.03.2025	Sydney Tyre Service	1x Yokohama 295/80R22.5
XO13WD	Repairs	26.03.2025	DG Auto Electrics	<p>20/03/2025</p> <ul style="list-style-type: none"> - TRAVEL TO BRINGELLY YARD - CHECK FOR A/C INOPERATIVE - FOUND GAS LEVEL LOW - DE-GAS REMAINING GAS - PRESURE TEST FOR LEAKS - FOUND EVAPORATOR LEAKING - NEED TO ORDER PARTS <p>26/03/2025</p> <ul style="list-style-type: none"> - TRAVEL TO BRINGELLY YARD - PULL DASH APART - LHS - REPLACE A/C EVAPORATOR AND TX VALVE - REPLACE RECIEVER DRIER - FOUND OK - RE-GAS A/C - A/C NOW WORKING OK - PUT DASH BACK TOGETHER
XO13WD	Tyres	03.04.2025	Sydney Tyre Service	1x yokohama 295/80R22.5
XO13WD	Tyres	29.04.2025	Sydney Tyre Service	1x Second Hand Tyre
XO13WD	B Service	30.04.2025	MSC Mechanical Repairs	<p>Carried out "B" service.</p> <p>Supplied and fitted new engine oil and filter.</p> <p>Supplied and fitted new primary and secondary fuel filters.</p> <p>Supplied and fitted new air filter.</p> <p>Carried out full chassis grease.</p> <p>Checked diff and gearbox oils.</p> <p>Checked all lights. Checked body bolts.</p> <p>Checked and adjusted brakes.</p> <p>1st axle brakes have 8 mm remaining.</p> <p>2nd axle brakes at 8 mm remaining.</p> <p>3rd axle brakes have 7 mm remaining.</p> <p>4th axle brakes (new).</p> <p>Supplied and fitted new airbag assembly to rear O/S 3rd from front.</p> <p>Repaired lights.</p> <p>Supplied and fitted new mudflap.</p> <p>Carried out rear axle brake reline.</p> <p>Supplied and fitted new brake shoes to rear axle.</p> <p>Supplied and fitted new brake drums.</p> <p>Removed, refitted and tensioned tyres.</p> <p>Road tested.</p>
XO13WD	Repairs	23.05.2025	DG Auto	<p>KENWORTH K200</p> <p>REGO.: XO-13WD</p> <p>KMS.: 759,947</p> <ul style="list-style-type: none"> - TRAVEL TO BRINGELLY YARD - CHECK FOR RIGHT HAND SIDE LOW BEAM HEADLIGHT NOT WORKING - TEST FUSES - FOUND OK - REMOVE HEADLIGHT AND CHECK FOR POWER - FOUND NO POWER AT HEADLIGHT - CHECK FOR WIRING FAULT - TRACE AND REPAIR BROKEN WIRING - RE-TEST WORKING
XO13WD	Tyres	03.06.2025	Sydney Tyre Service	1 x Yokohama 295/RR22.5 + RoadService
XO13WD	Tyres	18.06.2025	Maticco Tyres	1 x 11R22.5 Tyre
				<p>Carried out "B" service.</p> <p>Supplied and fitted new engine oil and filter.</p> <p>Supplied and fitted new primary and secondary fuel filters.</p> <p>Supplied and fitted new air filter.</p>

XO13WD	B Service	03.07.2025	MSC Mechanical Repairs	<p>Carried out full chassis grease. Checked diff and gearbox oils. Checked all lights. Checked body bolts. Checked and adjusted brakes. 1st axle brakes have 9 mm remaining. 2nd axle brakes have 9 mm remaining. 3rd axle brakes have 7 mm remaining. 4th axle brakes have 7 mm remaining. Supplied and fitted new rear marker plates. Supplied and fitted new air dryer filter. Supplied and fitted new reflectors. Carried out vehicle inspection as requested.</p>
XO13WD	Repairs	09.07.2025	MSC Mechanical Repairs	<p>Inspected for leak behind cab. Found adblue hose broken at injector fitting. Supplied and fitted new fitting. Tested operation.</p>
XO13WD	Repairs	29.07.2025	Macarthur Hydraulics	<p>Replaced Hydraulic Jose from Pump to Spool Valve KENWORTH K200 - REGO - XO13WD - 774,837KM</p>
XO13WD	Repairs	13.08.2025	MSC Mechanical Repairs	<p>Carried out "A" service. Cleaned and inspected air filter. Cleaned cabin pollen filter. Carried out full chassis grease. Checked diff and gearbox oils. Checked all lights. Checked body bolts. Checked and adjusted brakes. 1st axle brakes have 8 mm remaining. 2nd axle brakes at 8 mm remaining. 3rd axle brakes have 7 mm remaining. 4th axle brakes have 8 mm remaining. Found 2nd axle P/S hub seal to have failed contaminating brakes. Removed brakes and brake drums. Replaced hub seal. Fitted new brake shoes and brake drum. Filled up hub with 85W – 140. Tensioned wheel nuts and adjusted brakes. Welded various cracks in subframe on tipper body.</p>
XO13WD	Repairs	26.03.2025	DG Auto	<p>KENWORTH K200 REGO.: XO-13WD KMS.: 748,986 20/03/2025 - TRAVEL TO BRINGELLY YARD - CHECK FOR A/C INOPERATIVE - FOUND GAS LEVEL LOW - DE-GAS REMAINING GAS - PRESURE TEST FOR LEAKS - FOUND EVAPORATOR LEAKING - NEED TO ORDER PARTS 26/03/2025 - TRAVEL TO BRINGELLY YARD - PULL DASH APART - LHS - REPLACE A/C EVAPORATOR AND TX VALVE - REPLACE RECIEVER DRIER - FOUND OK - RE-GAS A/C - A/C NOW WORKING OK - PUT DASH BACK TOGETHER</p>
				<p>KENWORTH K200 REGO.: XO-13WD KMS.: 777,664</p>

XO13WD	Repairs	27.08.2025	DG Auto	<p>26/08/2025</p> <ul style="list-style-type: none"> - TRAVEL TO BRINGELLY YARD - CHECK FOR VEHICLE BLOWING PTO FUSE WHEN ENGAUGING PTO - INSPECTED WIRING - UNABLE TO LOCATE SHORT AND WASN'T BLOWING FUSE AT THE TIME EITHER - SWAP OUT PTO SOLENOID - THEN FOUND SYSTEM BLEW FUSE, SO AIR SOLENOID IS NOT THE ISSUE - ADVISED ADRIAN WOULD BE BEST TO RE-WIRE PTO AND HOIST CONTROL SYSTEM FROM SWITCHES IN DASH TO SOLENOIDS ON CHASSIS, BUT WOULD HAVE TO COME BACK NEXT DAY <p>27/08/2025</p> <ul style="list-style-type: none"> - TRAVEL TO BRINGELLY YARD - REMOVE OLD WIRING BETWEEN SWITCHES AND SOLENOIDS - FIT NEW WIRING BETWEEN SWITCHES AND SOLENOIDS - REPLACE 2x FUSE HOLDERS NEAR MAIN FUSE BOX - RE-TEST PTO, TAIL GATE AND HOIST FUNCTIONS - FOUND OK
XO13WD	Tyres	02.10.2025	Master Truck Service	HAULSTAR 11R22.5 146/143M 16PR
XO13WD	Tyres	09.10.2025	Sydney Tyre Service	1 x Yokohama 295/80R22.5 & Disposal
XO13WD	Repairs	15.10.2025	DG Auto	<p>KENWORTH K200 REGO.: XO-13WD KMS.: 787,528 14/10/2025</p> <ul style="list-style-type: none"> - TRAVEL TO BRINGELLY YARD WHEN VEHICLE CAME BACK - CHECK FOR AIR CONDITIONER INOPERATIVE - FOUND NO AIR COMING OUT OF VENTS - FOUND BLOWER FAN NOT WORKING - TEST FOR POWER AT BLOWER FAN - FOUND OK ON ALL 4x SPEEDS - FOUND BLOWER FAN FAULTY - GAVE OLD BLOWER FAN A FEW TAPS - FOUND IT STARTED WORKING FOR NOW <p>15/10/25</p> <ul style="list-style-type: none"> - TRAVEL TO BRINGELLY - WAIT FOR VEHICLE TO FINISH WORKING - REPLACE BLOWER FAN - TEST AIR CONDITIONER OPERATION - FOUND OK
XO13WD	Repairs	22.10.2025	Heavy Automatics	<p>VEHICLE PRESENTED WITH HYDRAULIC PUMP FAILURE THAT FILLED TRANSMISSION WITH HYDRAULIC OIL. DRAIN HYDRAULIC OIL AND REMOVE PUMP, REPLACE PTO OIL SEAL AND INSTALL NEW PUMP. REPLACE DAMAGED HYDRAULIC HOSE AND OIL FILTER. FILL TANK WITH NEW HYDRAULIC OIL AND TEST OPERATION - OK</p>
XO13WD	Repairs	03.11.2025	MSC Mechanical Repairs	<p>KENWORTH K200 - REGO - XO13WD - 788,766KM Carried out "B" service.</p> <ul style="list-style-type: none"> Supplied and fitted new engine oil and filter. Supplied and fitted new primary and secondary fuel filters. Supplied and fitted new air filter. Carried out full chassis grease. Checked diff and gearbox oils. Checked all lights. Checked body bolts. Checked and adjusted brakes. 1st axle brakes have 10 mm remaining. 2nd axle brakes have 10 mm remaining. 3rd axle brakes have 7 mm remaining. 4th axle brakes have 8 mm remaining. Checked oil leak at gearbox. Found hydraulic oil in gearbox. Possible hydraulic pump leaking into gearbox. Drained coolant oil to correct level. Repaired defects. <p>Supplied and fitted new bump stop rubber block to O/S front steer.</p>

				<p>Supplied and fitted new bushes to top torque rod. Replaced bushes on front drive sway bar. Removed sway bar assembly, bolts seized. Supplied and fitted new bolt bushes and caps. Supplied and fitted new number plate light. Supplied and fitted new high beam globe. Repaired O/S hub seal leak. Removed hub assembly. Supplied and fitted new brake shoes. Supplied and fitted new hub seal. Cleaned and repacked bearings. Adjusted brakes. Supplied and fitted new gearbox oil and filter. Cleared defects.</p>
XO13WD	A Service	10.12.2025	MSC Mechanical Repairs	<p>Carried out "A" service. Supplied and fitted new engine oil and filter. Supplied and fitted new primary and secondary fuel filters. Supplied and fitted new air filter. Carried out full chassis grease. Checked diff and gearbox oils. Checked all lights. Checked body bolts. Checked and adjusted brakes. 1st axle brakes have 8 mm remaining. 2nd axle brakes have 8 mm remaining. 3rd axle brakes have 7 mm remaining. 4th axle brakes have 7 mm remaining. Repaired rego light wiring. Supplied and fitted new D/S mudflap. Supplied and fitted P/S body light. Checked air suspension low on N/S. Supplied and fitted new height control valve. Supplied and fitted new rose joint. Adjusted rod and tested.</p>
XO13WD	Repairs	22.12.2025	Quantum Mechanix	1x ECM Reprogramming and calibration file
XO13WD	Tyres	17.01.2026	Sydney Tyre Service	2 x New Power 11R22.5 18PR ND870 Premium Drive & 1x Strip & Fit
XO13WD	Parts	03.02.2026	A & D Partners	4 x Batteries
XO13WD	B Service	05.02.2026	MSC Mechanical	<p>Carried out "B" service. Supplied and fitted new engine oil and filter. Supplied and fitted new primary and secondary fuel filters. Supplied and fitted new air filter. Cleaned cabin pollen filter.</p>
XO13WD	Tyres	06.03.2026	Sydney Tyre Service	1xRoad Service, 2x New Power 11R22.5 18PR ND818 Drive & 2 x Disposal
				<p>Cleaned and inspected air filter. Carried out full chassis grease. Checked diff and gearbox oils. Checked all lights. Checked body bolts. Checked and adjusted brakes. 1st axle brakes have 8 mm remaining. 2nd axle brakes have 8 mm remaining. Checked belts. Supplied and fitted new A/C and fan belts. Supplied and fitted new fan belt tensioner. Found 2nd steer wheel studs damaged. Jacked up vehicle. Removed wheel and drum. Removed 3 wheel studs. Supplied and fitted new studs and nuts. Refitted brake drum and wheel. Tensioned wheel and road tested.</p>

XO13WD	Service - A	12.03.2026	MSC Mecahnical	NOTE - N/S front steer tyre damaged
XO13WD	Tyres	22.03.2026	Sydney Tyre Service	Kankook 29580R22.5 154149M AH31+ Tyre Dispoal