



Tank Services

Box 99 - 500 Airport Industrial Park
Breslau, Ontario N0B 1M0
Tel: 519-648-3344
Fax: 519-648-3224
www.utw.ca
Email: info@utw.ca

General Manager - Jason Veenstra

Client: Clean Harbors Canada (Corunna) 923D	Contact:	P.O.#:
Trailer #: 791118	Tractor #:	Unit #:
Date/Time: 2025-07-08 by 3pm - 11pm shift	Deadline	Oxygen Meter Reading: 20.9% @ 02:22:37 PM
Last Product: oily water	Type:	Explosion Meter Reading: 0.0% @ 02:22:37 PM

Special Instructions:

SERVICE	DONE	COMMENTS	SERVICE	DONE	COMMENTS
Cold Water Wash	✓		Hose Tubes Cleaned		
Hot Water Wash			Deodorize		
Hot Detergent Wash			Interior Sanitized		
Interior Rinse	✓				
Hoses Cleaned & Dried			Water Treatment	✓	
Product Pipe Cleaned	✓		Heels Removed Solid	Lts	✓
Caps Cleaned & Dried	✓		Heels Removed Liquid	Lts	✓
			Disposal		
Valves Removed & Cleaned	Qty	✓	Labour	Hrs	✓
Pump Wash			Confined Space Entry		✓
Hoses	Qty				
Neutralize & Pump Off			3' - 4' Gaskets	Qty	
Interior Dry - Hot			Cotter Pins	Qty	
Interior Dry - Cold			Hose Clamps	Qty	
Steam Tank Interior			Valve Packing	Qty	
Regular Exterior Wash			Tear Down Trailer Piping		
Brighten Exterior Wash			Reassemble Trailer Piping		
Polish Acid Wash			Storage	Days	

Comments: interior rusted may contain residue. rear gate valve will not open contains residue	Order Entered By: Jordan Jorgensen	Seal Tab Removal Time:
	Laborers: Jordan Jorgensen David Stoddart	Seal Tabs: