

KG9-16



TANK WASH AND PURGE TEST

Date: Dec 9/24 Time: 12pm

Location: Fort St John, BC

Tank Unit# 193189

Meter Used: NA

Reading:
% LEL Level: NA %O2: NA CO: NA H2S: NA

Tested Clean? Y/N

Comments: gamma jet + confined space
clean

Printed Name: Shawn Dore

Signature*: [Signature]
*this signature verifies that this tanker has been washed out and purged

Title: Branch Manager

Contact Phone Number: 250-224-4717