

K69-17



TANK WASH AND PURGE TEST

Date: Dec 9/24 Time: 12pm

Location: Fort St John, BC

Tank Unit# 193303

Meter Used: NA

Reading: — %O₂: — CO: — H₂S: —

Tested Clean? ☒ Y / ☐ N

Comments: gamma jet + confined space
cleaned

Printed Name: Shawn Doré

Signature*: [Signature]

*this signature verifies that this tanker has been washed out and purged

Title: Branch Manager

Contact Phone Number: 250-224-4717