BRITISH COLUMBIA

Commercial Vehicle Inspection Report

KF1-3

Decal Number: PA07704
Decal Expiry Date: 2027-Jul-31
Inspection Number: 21838364 2026828
Inspection Result: PASS

FACILITY:	COCA-COLA CANADA BOTTLING / P0263	**INSP. TYPE:**	Complete	**INSP. START:**	2026-Jul-07 05:00 AM PDT
INSPECTOR:	BUTTAR, KULJINDER SINGH / 201037	**INSP. CLASS:**	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	**INSP. COMPLETE:**	2026-Jul-07 07:00 AM PDT
WORK ORDER #:		**INSP. REASON:**	Annual		

VEHICLE JUR:	British Columbia	**REGI:**	06777483	**VIN:**	2XKHAM7AXAM263580
PLATE #:	RE4831	**UNIT/FLEET#:**	09B998010	**OWNER/LESSEE NAME:**	COCA-COLA CANADA BOTTLING, COCA-COLA CANADA BOTTLING
LICENCED GVW(kg):	31600	**BODY STYLE:**	Truck Tractor	**ADDRESS:**	Unit 110, 8040 Zylmans Way
VEHICLE YEAR:	2010	**ODOMETER:**	313335 KM		Richmond, British Columbia
MAKE:	KENWORTH	**HUB ODOMETER:**			V6W 0C3, Canada
MODEL:		**BRAKE TYPE:**	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	20	Automatic	28	28
2	Clamp	30	Automatic	32	32

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
11.1			11.9	✔
11.1	11.9	11.1	11.1	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	35	32
2	38	44

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	19	19
Lining (Shoe)	19	18

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured. Did not remove any drum.

Inspection Comments:

Has this Vehicle been road tested? No **Road Test Date:** **Road Tester:**

Inspector: BUTTAR, KULJINDER SINGH **Signature:**

This Inspection Report was submitted to CVSE on 2026-Jul-07 10:07 AM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014
7/7/2026 10:07:55 AM PDT