

SEE Fleet - Work Order Summary

Asset:
60-1290 - Caterpillar D400E Series II Articulated
Dump Truck

Location:
114 CONTOUR ROAD, TAMBORINE MOUNTAIN
QLD 4272

Current Tracker Hours:
23507

Current Tracker Kms:
23342

Work Order	Description	Created	Created Hours	Created Km	Completed	Priority	Item Status	Assigned To/Completed By
320218	Prepare for demob	24/07/2026	23507	23342		CAT 3 - Next Service	Open	SPA Maintenance
317556	Replace Leaking & Damaged Rear Tyres	23/06/2026	23505	23342		CAT 2 - Machine Down	Open	SPA Maintenance
315939	Risk Assessment Inspection	04/06/2026	23499	23316		Service	Open	XX - Serviceman
315784	Inspect & Repair Air Leaks & Transmission Fault	02/06/2026	23499	23316	29/06/2026	CAT 2 - Machine Down	Closed	SPA Maintenance
312324	Electrical fire smell from under cab and machine wont start	14/04/2026	23499	23316	25/06/2026	CAT 1 - Safety	Closed	Chris Collingwood
310930	Split in tyre side wall	23/03/2026	23483	23276	04/06/2026	CAT 1 - Safety	Closed	SPA Maintenance
309997	A/C Evaporator Fault	10/03/2026	23483	23276	09/02/2026	CAT 3 - Next Service	Closed	XX - Auto Electrician
308068	Replace failed batteries	13/02/2026	23471	23204	07/04/2026	CAT 2 - Machine Down	Closed	SPA Maintenance
307342	Inspect & Repair start fault	05/02/2026	23457	23160	07/04/2026	CAT 3 - Next Service	Closed	XX - Subcontractor Fitter
307366	Inspect & Repair Aircon Leak	05/02/2026	23459	23172	17/02/2026	CAT 3 - Next Service	Closed	SPA Maintenance
307072	Repair oil leaks	02/02/2026	23436	23130	04/06/2026	CAT 3 - Next Service	Closed	SPA Maintenance
305640	Carry Out Jump Start	08/01/2026	23420	23080	08/01/2026	CAT 3 - Next Service	Closed	SPA Maintenance
304214	Repair Steering Leaks	04/12/2025	23417	23038	22/01/2026	CAT 1 - Safety	Closed	SPA Maintenance
301988	Mechanical inspection	27/10/2025	23390	22807	04/06/2026	CAT 3 - Next Service	Closed	SPA Maintenance
299672	23500 hours service	18/09/2025	23388	22789	04/06/2026	Service	Closed	SPA Maintenance
297199	steering fault suspect HMU	04/08/2025	23117	22681	10/09/2025	Service	Closed	SPA Maintenance
297183	park brake u/s	04/08/2025	23117	22681	10/09/2025	CAT 1 - Safety	Closed	SPA Maintenance
297058	Inspect TFO Tracker	31/07/2025	23116	22679	04/06/2026	Service	Closed	SPA Maintenance
296981	Hydraulic suction hose leaking at Hyd tank.	30/07/2025	23116	22679	10/09/2025	CAT 3 - Next Service	Closed	SPA Maintenance
295966	run out of fuel	11/07/2025	23116	22679	18/07/2025	CAT 2 - Machine Down	Closed	SPA Maintenance
295673	Fault code on dash - Steering wheel symbol, red colour	04/07/2025	23116	22679	18/07/2025	CAT 3 - Next Service	Closed	SPA Maintenance
295566	Oil leak at torque converter	02/07/2025	23116	22679	18/07/2025	CAT 2 - Machine Down	Closed	XX - Subcontractor Fitter
295080	seal tailgate	23/06/2025	23116	22679	18/07/2025	CAT 3 - Next Service	Closed	XX - Subcontractor Boilermaker
290638	Middle tyre	22/03/2025	23116	22679	29/07/2025	CAT 3 - Next Service	Closed	SPA Maintenance
290169	fuel cap damaged	13/03/2025	23116	22679	13/03/2024	Service	Closed	SPA Maintenance
289953	500 hr service	11/03/2025	23116	22679	11/03/2025	Service	Closed	SPA Maintenance
280174	Cab lift cylinder leaking at main seal (bye passing)	27/02/2025	23116	22679	12/03/2025	CAT 3 - Next Service	Closed	SPA Maintenance
280010	foot brake control valve leaking into cab	25/02/2025	23116	22679	10/03/2025	CAT 2 - Machine Down	Closed	SPA Maintenance
279415	Multiple Prestart Defects	12/02/2025	23116	22679	10/03/2025	CAT 4 - Next Rebuild	Closed	SPA Maintenance
278115	Inspect operator seat	16/01/2025	23116	22679	20/01/2025	CAT 3 - Next Service	Closed	SPA Maintenance

277476 Work Order	flat batteries Description	16/12/2024 Created	23116 Created Hours	22679 Created Km	18/12/2024 Completed	Service Priority	Closed Item Status	Michael Benstead Assigned To/Completed By
272271	hydraulic oil leak	02/09/2024	23116	22679	16/01/2025	CAT 2 - Machine Down	Closed	Mchael Benstead
270330	snapped starter isolator	17/07/2024	23103	22592	16/01/2025	CAT 1 - Safety	Closed	Michael Benstead
270061	Replace 3G Tracker with 4G Tracker & Install VS Tracker	13/07/2024	23103	22592	13/07/2024	CAT 3 - Next Service	Closed	
268930	Multiple Prestart Defects	18/06/2024	23101	22578	16/01/2025	CAT 3 - Next Service	Closed	Michael Benstead
268399	front hub seals leaking oil badly (duo cones)	03/06/2024			17/07/2024	CAT 3 - Next Service	Closed	XX - Subcontractor Fitter Michael Benstead Mark Sinnott
266397	service AND REPAIRS	03/04/2024			08/04/2024	CAT 3 - Next Service	Closed	
265920	install tailgate pivots	21/03/2024			25/03/2024	CAT 1 - Safety	Closed	
264219	A/C FAULT	07/02/2024	22917	21592	12/02/2024	CAT 3 - Next Service	Closed	XX - Subcontractor Fitter
264211	PRE-START FAULTS	07/02/2024			03/06/2024	CAT 3 - Next Service	Closed	Michael Benstead
262035	Hydraulic leak	06/10/2023	22868	21446	08/04/2024	CAT 2 - Machine Down	Closed	Johnathon Cooper
261863	Aircon not working right	26/09/2023			09/11/2023	CAT 3 - Next Service	Closed	
261246	Repair emergency stop switch	29/08/2023	22785	21194	29/08/2023	CAT 3 - Next Service	Closed	XX - Subcontractor Fitter
260917	Park brake pad fell out	14/08/2023			18/08/2023	CAT 2 - Machine Down	Closed	
260594	Reversing camera doesn't work	31/07/2023	0	0	13/07/2023	CAT 3 - Next Service	Closed	SPA Maintenance
260593	Horn doesn't work	31/07/2023			10/08/2023	CAT 3 - Next Service	Closed	
260557	23000 hours service	29/07/2023	22745	21046	28/03/2024	Service	Closed	
260545	Hydronic hose weeping	28/07/2023			28/09/2023	CAT 3 - Next Service	Closed	
260243	Replace worn Pos 5 & 6 tyres	17/07/2023	22678	20744	17/07/2023	CAT 3 - Next Service	Closed	XX - Subcontractor Fitter
260137	Replace main engine earth strap	10/07/2023	22668	20715	10/07/2023	CAT 3 - Next Service	Closed	Owen Macpherson
260054	No start ,starter motor throwing out but not spinning	05/07/2023			10/07/2023	CAT 2 - Machine Down	Closed	
259699	Steering cylinder snapped	13/06/2023			29/06/2023	CAT 2 - Machine Down	Closed	
259403	Two front wheel seals leaking	23/05/2023			03/06/2024	CAT 3 - Next Service	Closed	
259402	Left hand tyre leaking	23/05/2023			07/07/2023	CAT 3 - Next Service	Closed	
259307	Roller on accelerator needs replaced	18/05/2023			25/05/2023	CAT 3 - Next Service	Closed	
259002	Number 3 tyre slow leak	28/04/2023			22/05/2023	CAT 3 - Next Service	Closed	
258940	Front wheel seal still leaking	21/04/2023			27/07/2023	CAT 3 - Next Service	Closed	
258805	Exhaust broken	12/04/2023			15/05/2023	CAT 3 - Next Service	Closed	
258718	Loose bolt on side mirror	04/04/2023			07/07/2023	CAT 3 - Next Service	Closed	
258717	Left hand head board bolt loose	04/04/2023			29/08/2023	CAT 3 - Next Service	Closed	XX - Subcontractor Fitter
257794	wash down machine	10/02/2023	22429	19780	13/03/2023	CAT 3 - Next Service	Closed	Michael Benstead
257742	bottom push on articulation failed.	08/02/2023	22428	19779	15/05/2023	CAT 2 - Machine Down	Closed	Michael Benstead
257311	22500 hours service	12/01/2023	22301	19156	15/05/2023	Service	Closed	
257204	Replace Park brake pads	21/12/2022	22266	19014	01/02/2023	CAT 3 - Next Service	Closed	Michael Benstead
256859	Roller on accelerator pedal broken	01/12/2022			07/07/2023	CAT 3 - Next Service	Closed	
256858	Air conditioning condenser needs replaced	01/12/2022			07/07/2023	CAT 3 - Next Service	Closed	

Work Order	Description	Created	Created Hours	Created Km	Completed	CAT 3 - Next Service Priority	Closed Item Status	Assigned To/Completed By
256814	Reverse camera not working	20/11/2022			07/07/2023	CAT 3 - Next Service	Closed	
256024	oil leak under cab	21/10/2022	21928	17627	31/10/2022	CAT 3 - Next Service	Closed	Michael Benstead
255498	Pos 1&2 very work and mismatched require replacement	19/09/2022			01/02/2023	CAT 3 - Next Service	Closed	
255424	22000 hours service	14/09/2022	21798	16901	02/05/2023	Service	Closed	
255201	Need reverse camera fixing	30/08/2022			21/10/2022	CAT 3 - Next Service	Closed	
254943	Exhaust manifold leaking	16/08/2022			05/10/2022	CAT 3 - Next Service	Closed	
254865	Hose to lifting ram leaking. Front wheel seal leaking	12/08/2022			08/09/2022	CAT 3 - Next Service	Closed	
254781	exhaust leak	08/08/2022	21597	15776	17/04/2023	CAT 3 - Next Service	Closed	Michael Benstead
254559	blown hose for hoist	27/07/2022	21531	15423	05/08/2022	CAT 2 - Machine Down	Closed	Michael Benstead
254537	Transmission leak worsening	26/07/2022			30/01/2023	CAT 3 - Next Service	Closed	
254536	Pos 1 and 2 wheel seals leaking	26/07/2022			15/05/2023	CAT 3 - Next Service	Closed	
254510	Service	24/07/2022	21521	15373	24/07/2022	Service	Closed	Joshua Beeston
254464	replace bolts on lose head board	20/07/2022	21500	15294	20/07/2022	CAT 3 - Next Service	Closed	Michael Benstead
254312	oil leaking out of a pressure relief valve	13/07/2022	21490	15246	13/07/2022	CAT 3 - Next Service	Closed	Michael Benstead
254188	Reverse camera not working	05/07/2022			08/09/2022	CAT 3 - Next Service	Closed	
254133	Pos 2 outside tyre ring U/S	01/07/2022			20/07/2022	CAT 3 - Next Service	Closed	
254111	moxy is getting stuck in gears still	30/06/2022	21440	15093	13/07/2022	CAT 3 - Next Service	Closed	Michael Benstead
254029	Oil leak from transmission	27/06/2022			05/08/2022	CAT 3 - Next Service	Closed	
253958	install new trans output sensor	23/06/2022	21405	14945	23/06/2022	CAT 3 - Next Service	Closed	Michael Benstead
253867	Supply ECM replacement	20/06/2022	21405	14945	23/06/2022	CAT 3 - Next Service	Closed	XX - Subcontractor Fitter
253756	moxy wont change out of first	15/06/2022	21404	14945	23/06/2022	CAT 2 - Machine Down	Closed	Michael Benstead
253617	Replace blower fan	08/06/2022			23/06/2022	CAT 3 - Next Service	Closed	XX - Subcontractor Fitter
253616	Multiple Prestart Defects	08/06/2022			23/06/2022	CAT 3 - Next Service	Closed	
253457	Tub Repairs	31/05/2022	21399	14926	31/05/2022	CAT 3 - Next Service	Closed	XX - Subcontractor Fitter
253409	Fit See Group Decals	30/05/2022	21399	14926	30/05/2022	CAT 3 - Next Service	Closed	
253405	Fit run out tyres on steer & move pos1 to 3	30/05/2022	21399	14926	30/05/2022	CAT 3 - Next Service	Closed	XX - Subcontractor Fitter
252887	Wash Machine	28/04/2022	21396	14925	28/04/2022	CAT 3 - Next Service	Closed	XX - Subcontractor Fitter
252845	Diagnose transmission fault	26/04/2022	21396	14925	02/06/2022	CAT 3 - Next Service	Closed	XX - Subcontractor Fitter
252809	replace hydraulic hoses	25/04/2022	21396	14925	25/04/2022	CAT 3 - Next Service	Closed	Michael Benstead
252716	Steer cyl rods bent, pick up and drop to marrow s for repairs	17/04/2022	21393	14917	22/04/2022	CAT 2 - Machine Down	Closed	
252691	Articulation pin fallen out	13/04/2022			22/04/2022	CAT 3 - Next Service	Closed	
252563	broken grease fitting	05/04/2022	21332	14675	22/04/2022	CAT 3 - Next Service	Closed	Michael Benstead
252511	Steering lost.	31/03/2022			04/04/2022	CAT 2 - Machine Down	Closed	Michael Benstead
252416	21500 hours service	25/03/2022	21295	14579	25/04/2022	Service	Closed	
252352	Prestart Defect - Air Conditioner functional (where fitted) F	22/03/2022			10/06/2022	CAT 2 - Machine Down	Closed	
252284	Diagnose & repair air-conditioning	17/03/2022			10/06/2022	CAT 3 - Next Service	Closed	XX - Subcontractor Fitter
252268	Gear selection issues intermittently	16/03/2022			29/03/2022	CAT 3 - Next Service	Closed	

Work Order	Description	Created	Created Hours	Created Km	Completed	CAT 2 - Machine Down Priority Service	Closed Status	Assigned To/Completed By
251603 251018	Bad oil leak 21000 hours service	02/02/2022 16/12/2021	20858	12950	01/02/2022 21/02/2022		Closed Closed	XX - Subcontractor Fitter
250944	pos 3 & 5 tyres leaking air	10/12/2021	207909	12814	02/02/2022	CAT 3 - Next Service	Closed	
250832	208000 hours service	03/12/2021	207806	12649	02/02/2022	Service	Closed	
250417	hoist wont lower	07/11/2021	20670	12197	16/11/2021	CAT 3 - Next Service	Closed	Rhys Ward
250092	Prestart Defect - Tyres inflated and free from damage Failed	19/10/2021			03/11/2021	CAT 3 - Next Service	Closed	Jonathon Little
249240	Multiple Prestart Defects	23/08/2021			23/06/2022	CAT 3 - Next Service	Closed	
249217	Transmission issues	20/08/2021			26/08/2021	CAT 3 - Next Service	Closed	XX - Subcontractor Fitter
248808	20500 hours service	22/07/2021	20349	11268	16/08/2021	Service	Closed	
248714	hand brake pads worn excessively	13/07/2021	20317	11174	16/08/2021	CAT 3 - Next Service	Closed	Geoff Vanderwolf
248700	Prestart Defect - Tyres inflated and free from damage Failed	12/07/2021			16/08/2021	CAT 3 - Next Service	Closed	Jonathon Little
248583	Prestart Defect - Odometer/Hours Correct	30/06/2021			16/08/2021	CAT 3 - Next Service	Closed	
248373	Prestart Defect - Oil leaks evident or abnormally low level F	15/06/2021			16/08/2021	CAT 3 - Next Service	Closed	Don Battese
247939	Prestart Defect - UHF radio functioning	14/05/2021			09/08/2021	CAT 3 - Next Service	Closed	Geoff Vanderwolf
247799	Prestart Defect - Test washers / wipers Failed	30/04/2021			30/06/2021	CAT 3 - Next Service	Closed	Geoff Vanderwolf
247705	leak in 2 tyres	22/04/2021	20237	10878	24/05/2021	CAT 3 - Next Service	Closed	Geoff Vanderwolf
247641	Prestart Defect - Oil leaks evident or abnormally low level F	17/04/2021			30/06/2021	CAT 3 - Next Service	Closed	Geoff Vanderwolf
247607	Prestart Defect - UHF radio functioning Failed	15/04/2021			24/05/2021	CAT 3 - Next Service	Closed	Geoff Vanderwolf
247367	Grease nipple missing	22/03/2021	20123	10246	22/03/2021	CAT 3 - Next Service	Closed	
246473	Prestart Defect - UHF radio functioning Failed	02/03/2021			30/06/2021	CAT 3 - Next Service	Closed	Geoff Vanderwolf
245070	20000 hours service	09/02/2021	19966	9172	27/02/2021	Service	Closed	XX - Subcontractor Fitter
242757	Tyre o-ring leak	30/11/2020			14/12/2020	CAT 2 - Machine Down	Closed	
242235	batterys failed	19/11/2020			14/12/2020	CAT 3 - Next Service	Closed	
242212	starter motor gasket leaking	18/11/2020			14/12/2020	CAT 3 - Next Service	Closed	
228973	Prestart Defect - Air Conditioner functional (where fitted) F	07/10/2020			14/12/2020	CAT 3 - Next Service	Closed	Matt Rennie
228604	Prestart Defect - Oil leaks evident or abnormally low level F	28/09/2020			14/12/2020		Closed	Matt Rennie
228507	Prestart Defect - Check Transmision Oil Failed	25/09/2020			14/12/2020	CAT 3 - Next Service	Closed	Matt Rennie
241811	replace hose from tranny to filter	22/09/2020			27/10/2020		Closed	
241598	replace orings and hoses	25/08/2020			22/09/2020		Closed	
241463	blown hose from trasnission to out put 40mm hose	04/08/2020			25/08/2020		Closed	
241402	throttle pedal roller failed	24/07/2020			14/12/2020		Closed	Jackson Atkin
225716	Prestart Defect - Air Conditioner functional (where fitted) F	22/07/2020			14/12/2020		Closed	
241327	wash down	13/07/2020			11/08/2020		Closed	
241239	heater in cab not working	02/07/2020			11/08/2020		Closed	
241172	500 HR SERVICE	26/06/2020			14/07/2020	Service	Closed	
241100	inspect over dumpy with matt	22/06/2020			02/07/2020		Closed	
241105	electrical fault in hitch harness	22/06/2020			11/08/2020		Closed	Matthew McCormack
241071	blown hose on eng	15/06/2020			02/07/2020		Closed	

Work Order	Description	Created	Created Hours	Created Km	Completed	Priority	Item Status	Assigned To/Completed By
240819	replace transmisson hose and o'rings	19/05/2020			02/07/2020		Closed	
240753	blow n main hose to tipper	12/05/2020			02/07/2020		Closed	
240720	replaced grease line on tailgate	07/05/2020			02/07/2020		Closed	
240542	tranny not engaging	21/04/2020			24/04/2020		Closed	
240522	Transmission stuck in 5th	17/04/2020			07/05/2020		Closed	
240207	tyre repairs and fittment of sedcond hand tyres	17/03/2020			17/03/2020		Closed	
240182	Auto-Init WO - March 16, 2020	16/03/2020			08/04/2020		Closed	
239899	aircon u-s	19/02/2020			11/03/2020		Closed	
239554	broken chains on tailgate	28/01/2020			11/03/2020		Closed	
213621	19000 hours service	19/12/2019			23/02/2021	Service	Closed	
238910	replace oils in finals	10/12/2019			21/12/2019		Closed	
238894	Weld up cracks in tailgate and fit	09/12/2019			21/12/2019		Closed	
238746	Auto-Init WO - November 26, 2019	26/11/2019			09/12/2019		Closed	
238664	inspect complaint with transmission gear selection	20/11/2019			20/11/2019		Closed	Jackson Atkin
238663	seat has no air	20/11/2019			20/11/2019		Closed	Jackson Atkin
238662	transmisson front housing leaking	20/11/2019			11/03/2020		Closed	
238460	AC not working	08/11/2019			19/12/2019		Closed	Matthew McCormack
238356	POS 5 tyre flat	04/11/2019			19/12/2019		Closed	Matthew McCormack
238153	brake fault	23/10/2019			19/12/2019		Closed	Matthew McCormack
238003	hyd hoist cylinder mount bolts loose	11/10/2019			11/10/2019		Closed	Jackson Atkin
237912	HYD leaks	08/10/2019			11/03/2020		Closed	
237520	install tailgate	14/09/2019			03/10/2019		Closed	Jackson Atkin
237449	tighten head boards	11/09/2019			11/09/2019		Closed	Jackson Atkin
237450	bleed brakes	11/09/2019			11/09/2019		Closed	Jackson Atkin
237392	remove components from watercart	09/09/2019			11/09/2019		Closed	Jackson Atkin
237379	electrical repairs	06/09/2019			11/09/2019		Closed	Jesse Baildon
237373	repair and paint water tank	05/09/2019			11/09/2019		Closed	Keith Bower
237341	install hoist cylinders	03/09/2019			11/09/2019		Closed	Jackson Atkin
237286	Sand blast inside of water tank	29/08/2019			11/09/2019		Closed	Keith Bower
237264	Line bore body rear pivot ears	27/08/2019			27/08/2019		Closed	Keith Bower
237190	Modifications to water tank for chassis swap	21/08/2019			11/09/2019		Closed	
237136	Remove Water tank	17/08/2019			27/08/2019		Closed	
237086	Paint red stripe on rims (Mbris)	13/08/2019			11/09/2019		Closed	
237055	Water spray bar upgrade	12/08/2019			27/08/2019		Closed	
236942	Replace fan hub bearings	05/08/2019			27/08/2019		Closed	
236896	Repair leaking hoses	01/08/2019			11/09/2019		Closed	
236893	New unit numbers x 3	01/08/2019			11/09/2019		Closed	Raymond Jackson

206158 Work Order	transfer output housing leaking Description	06/06/2019 Created	Created Hours	Created Km	27/08/2019 Completed	Priority	Closed Item Status	Assigned To/Completed By
235382	tracker not working	29/03/2019			29/03/2019		Closed	Jolon Maingay
235381	air leak for spray system	29/03/2019			29/03/2019		Closed	Jolon Maingay
235316	engine overheating	25/03/2019			11/09/2019		Closed	Matthew McCormack
235220	18,750 hours service	18/03/2019			08/04/2019	Service	Closed	Jolon Maingay
235204	fit cannon	18/03/2019			25/03/2019		Closed	Matthew McCormack
234811	BLOWN HOSE	20/02/2019			25/02/2019		Closed	Matthew McCormack
234700	REPLACE AIR DRYER	13/02/2019			20/02/2019		Closed	Matthew McCormack
234481	AC blower motor U/S	30/01/2019			12/02/2019		Closed	Matthew McCormack
234468	no gears	29/01/2019			12/02/2019		Closed	Matthew McCormack
234425	4250 Kilometres Service	25/01/2019			08/04/2019	Service	Closed	
194674	4250 kmservice	25/01/2019		4180	25/01/2019	Service	Closed	
234407	horn US	24/01/2019			12/02/2019		Closed	Matthew McCormack
234394	starter motor leaking	24/01/2019			11/09/2019		Closed	
234393	output shaft solenoid leaking	24/01/2019			12/02/2019		Closed	Matthew McCormack
234392	rear main seal leaking	24/01/2019			11/09/2019		Closed	Matthew McCormack
234391	pos 1 & 2 duo cones leaking	24/01/2019			03/10/2019		Closed	Matthew McCormack
234389	replace ECM mounts	24/01/2019			12/02/2019		Closed	Matthew McCormack
234388	replace diff plugs	24/01/2019			12/02/2019		Closed	Matthew McCormack
234370	replace leaking hoses and fittings	23/01/2019			12/02/2019		Closed	Matthew McCormack
234247	FIT 6 TYRES	17/01/2019			25/03/2019		Closed	
234210	Park brake u/s	15/01/2019			12/02/2019		Closed	
234000	Fit runout to POS6	18/12/2018			29/01/2019		Closed	Ashley Shuttleworth
233966	500 hour service	17/12/2018			03/01/2019	Service	Closed	Jolon Maingay
233962	Alternator u/s	15/12/2018			29/01/2019		Closed	Jesse Baildon
233870	4000 Kilometres Service	11/12/2018			07/01/2019	Service	Closed	
194111	4000 kmservice	11/12/2018		3513	11/12/2018	Service	Closed	
233787	3750 Kilometres Service	04/12/2018			11/12/2018	Service	Closed	
194057	3750 kmservice	04/12/2018		3403	04/12/2018	Service	Closed	
233714	blocked screen in tank	28/11/2018			28/11/2018		Closed	
233693	Water pump on tank issue	27/11/2018			28/11/2018		Closed	
194000	3500 kmservice	24/11/2018		3215	24/11/2018	Service	Closed	
233636	3500 Kilometres Service	24/11/2018			28/11/2018	Service	Closed	
193947	3250 kmservice	16/11/2018		3042	16/11/2018	Service	Closed	
233492	3250 Kilometres Service	16/11/2018			28/11/2018	Service	Closed	
233444	Check horn	13/11/2018			28/11/2018		Closed	Jesse Baildon
233329	3000 Kilometres Service	08/11/2018			28/11/2018	Service	Closed	
193901	3000 kmservice	08/11/2018		2859	08/11/2018	Service	Closed	

Work Order	Description	Created	Created Hours	Created Km	Completed	Priority	Item Status	Assigned To/Completed By
233234	2750 Kilometres Service	01/11/2018			28/11/2018	Service	Closed	
193859	2750 kmservice	01/11/2018		2740	01/11/2018	Service	Closed	
233055	2500 Kilometres Service	20/10/2018			28/11/2018	Service	Closed	
193802	2500 kmservice	20/10/2018		2533	21/10/2018	Service	Closed	
232945	rimlock missing	12/10/2018			11/12/2018		Closed	
232820	replace worn or leaking hyd lines	08/10/2018			28/11/2018		Closed	
193686	2250 kmservice	28/09/2018		2088	30/09/2018	Service	Closed	
232675	2250 Kilometres Service	28/09/2018			28/11/2018	Service	Closed	
232581	Bad engine oil sample	24/09/2018			28/11/2018		Closed	
191623	2000 kmservice	13/09/2018		1749	13/09/2018	Service	Closed	
232382	2000 Kilometres Service	13/09/2018			28/11/2018	Service	Closed	
232274	Various hose leaks	07/09/2018			28/11/2018		Closed	
232227	install new Air dryer kit	06/09/2018			28/11/2018		Closed	
232221	reseal HMU	05/09/2018			28/11/2018		Closed	
232081	250 hour service	27/08/2018			05/09/2018	Service	Closed	Jolon Maingay
191485	1750 kmservice	24/08/2018		1361	24/08/2018	Service	Closed	
191434	1500 kmservice	16/08/2018		1192	16/08/2018	Service	Closed	
191344	1250 kmservice	07/08/2018		959	07/08/2018	Service	Closed	
191213	1000 kmservice	25/07/2018		544	25/07/2018	Service	Closed	
191179	750 kmservice	19/07/2018		373	19/07/2018	Service	Closed	
231406	Replace Compressor (passing Oil)	19/07/2018			05/09/2018		Closed	
231292	Coupling faulting on water pump	12/07/2018			13/07/2018		Closed	
231258	Reseal tank water pump	06/07/2018			05/09/2018		Closed	
231262	Discharge and recharge a/c	06/07/2018			06/07/2018		Closed	Jesse Baildon
231254	turbocharger u/s	05/07/2018			05/07/2018		Closed	
231223	Dummy	04/07/2018			05/09/2018		Closed	
191054	500 kmservice	30/06/2018		70081	30/06/2018	Service	Closed	