

04067482

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

Vehicle Safety Box 45064 Regent Postal Outlet Winnipeg, MB, R2C 5C7 1-204-985-0920

Manitoba

C019762

Date Inspection Started 26 03 25
Date Inspection Completed 02 04 25
Inspection Expiry Date 30 04 27

Station Number A16262 Mullen Contracting Sifton MB
Mechanic Number M10360
Vehicle Owner Baker
Address Dauphin MB

Pass/Safe Vehicle
Licence Number H5J97A
Prov. MB
NSC # MB9569258
Odometer Reading 35
Vehicle Identification Number 1HS4HWATNX4J1023510
Make I/H
Model 8600
Year 2004

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck 14515 KGS
Truck Tractor
Trailer
Semi-Trailer
Bus
School Bus
Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

Section 1 - Power Train: Defects (if any) 2E: Pipe component turbo 12C: RH rear fuel tank strap.
Section 2 Suspension: Defects (if any)
Section 3 - Brake Systems: 3H 3A
Defects (if any) Circle Brake Type
14A: RH+LH 1st Brake pads rust holes
4B: LH front air tank leaking
Section 4 - Steering: Defects (if any)
Section 5 - Instruments & Auxiliary Equipment: Defects (if any) 7B: Wiper blades torn 7D: washer not working
Section 6 - Lamps: Defects (if any) 1S: LH mirror light 1F: RH signal under door
Section 7 - Electrical System: Defects (if any) 2K: Battery hold down.
Section 8 - Body: Defects (if any) 8-4A: Rust holes back of cab 21A: LH front fender falling off
Section 9 - Tire & Wheel: Defects (if any)

Brake Inspection Type: A B C D E
Table with columns: Axle, Lining (L, R), Drum/Rotor (L, R), Stroke (L, R)
Row 1: 1, 11/16, 11/16, 16.573, 16.588, 1, 1
Row 2: 2, 3/8, 3/8, 16.538, 16.522, 1 1/4, 1 1/4

Tread Depth 132
Air Pressure
Table with columns: Axle, Initial, Corrected (L, R) for Tread Depth and Air Pressure
Row 1: 1, 14, 14, 110, 110
Row 2: 2, 7, 7, 12, 110, 110, 110, 110

Section 10 - Coupling Devices: Defects (if any)

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: Signature Date:

PRESENT THIS COPY WHEN REGISTERING VEHICLE