



# Commercial Vehicle Inspection Report

Decal Number: GK54459  
Decal Expiry Date: 2026-Aug-31  
Inspection Number: 21471575

L03-12

Inspection Result:

**PASS**

**CITY:** TWISTED METAL MECHANICS LTD. / S20269  
**SPECTOR:** BOLIVAR, MICHAEL BRANDON / 202902  
**DRK ORDER #:** 17  
**INSPECTION TYPE:** Complete  
**INSPECTION CLASS:** Class 3 - Trailer and Semi-Trailer  
**INSPECTION REASON:** Annual  
**INSPECTION START:** 2025-Aug-24 01:54 PM PDT  
**INSPECTION COMPLETE:** 2025-Aug-24 03:54 PM PDT

**VEHICLE JURISDICTION:** British Columbia  
**VEHICLE REGISTRATION #:** 37750U  
**VEHICLE WEIGHT (kg):** 999999  
**VEHICLE YEAR:** 2014  
**MAKE:** LAZERINOX  
**MODEL:**  
**REGISTRATION:** 11012310  
**UNIT/FLEET #:** 244  
**BODY STYLE:** Tank Trailer  
**VIN:** 2L9TS5330ED079264  
**OWNER/LESSEE NAME:** SWAMP DONKEY, SWAMP  
**ADDRESS:** PO BOX 2394 STN MAIN, PO BOX 2394 STN MAIN  
Dawson Creek, British Columbia  
V1G4T9, Canada  
**ODOMETER:**  
**HUB ODOMETER:**  
**BRAKE TYPE:** Air  
**FUEL TYPE:**

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	28	25	12	14	12	12	
2	Clamp	30	Automatic	34	34	11	10	10	10	
3	Clamp	30	Automatic	32	32	12	12	12	12	

Comment:

Comment:


Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	40	35	Lining (Shoe)	19	19	Drum		
2	45	45	Lining (Shoe)	19	19	Drum		
3	45	48	Lining (Shoe)	18	19	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

## Inspection Comments:

Is this Vehicle been road tested? No  
Inspector: BOLIVAR, MICHAEL BRANDON  
Road Test Date:   
Signature:   
Road Tester:

This Inspection Report was submitted to CVSE on 2025-Aug-24 04:54 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement.

SED014

4/2025 4:54:50 PM PDT