



Commercial Vehicle
Inspection Report

Decal Number: GK54450
Decal Expiry Date: 2026-Feb-28
Inspection Number: 21471540

Inspection Result:
PASS

CILITY: TWISTED METAL MECHANICS LTD. / S20269

SPECTOR: BOLIVAR, MICHAEL BRANDON / 202902

DRK ORDER #: 8

INSP. TYPE: Complete

INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more

INSP. REASON: Semi-annual

INSP. START: 2025-Aug-24 12:36 PM PDT

INSP. COMPLETE: 2025-Aug-24 02:36 PM PDT

148

VEHICLE JUR: British Columbia

ATE #: SX6185

PERMITTED GVW(kg): 54500

REGI: 11217217

UNIT/FLEET#: 148

BODY STYLE: Truck Tractor

VIN: 1NKDX4EX2FR974916

OWNER/LESSEE NAME: SWAMP DONKEY, SWAMP

ADDRESS: PO BOX 2394 STN MAIN, PO BOX 2394 STN MAIN Dawson Creek, British Columbia V1G4T9, Canada

VEHICLE YEAR: 2015

MAKE: KENWORTH

MODEL:

ODOMETER: 470522 KM

HUB ODOMETER:

BRAKE TYPE: Air

FUEL TYPE:

- Vehicle Identification (VIN) Passed
- Section 1 - Power Train Passed
- Section 2 - Suspension Passed
- Section 3 - Brake System Passed
- Section 3A - Air Brakes Passed
- Section 3H - Hydraulic Brakes Not Applicable
- Section 4 - Steering Passed
- Section 5 - Instruments and Auxiliary Equipment Passed
- Section 6 - Lamps Passed
- Section 7 - Electrical System Passed
- Section 8 - Frame and Body Passed
- Section 9A - Tires Passed
- Section 9B - Wheels Passed
- Section 10 - Coupling Devices Passed
- Section 11 - Other Vehicle Components Not Applicable

Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	25	25	10			10	✓
2	Clamp	30	Automatic	35	35	8	8	8	8	
3	Clamp	30	Automatic	32	32	8	8	8	8	
4	Clamp	30	Automatic	33	35	10	10	10	10	
Comment:						Comment:				




Commercial Vehicle
Inspection Report

Decal Number: GK54450
Decal Expiry Date: 2026-Feb-28
Inspection Number: 21471540

Inspection Result:
PASS

Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	60	60	Lining (Shoe)	18	18	Drum		
2	65	65	Lining (Shoe)	17	17	Drum		
3	60	65	Lining (Shoe)	17	16	Drum		
4	68	72	Lining (Shoe)	15	15	Drum		
omment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:

Is this Vehicle been road tested? No
Inspector: BOLIVAR, MICHAEL BRANDON
Road Test Date: 
Signature: _____ Road Tester:

This Inspection Report was submitted to CVSE on 2025-Aug-24 03:36 PM PDT
Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.