Commercial Vehicle Inspection Report

Decal Number: Decal Expiry Date:

Inspection Number:

GK54445 2026-Feb-28 21471507

L63-22 Inspection Result:

PASS

Steering

TWISTED METAL MECHANICS LTD. INSP. TYPE:

INSP. CLASS:

REGI:

Complete

INSP. START:

2025-Aug-24 09:32 AM PDT 2025-Aug-24 12:32 PM PDT

/ S20269

BOLIVAR, MICHAEL BRANDON / 202902

BIA

INSP. REASON:

Class 3 - Trailer and Semi-Trailer

Semi-annual

INSP. COMPLETE:

DRK ORDER #:

HICLE JUR:

ATE #:

ODEL:

Alberta

CENCED GVW(kg): 99999

UNIT/FLEET#: BODY STYLE:

259 Trailer VIN: OWNER/LESSEE NAME:

ADDRESS:

2L9TC4410CD079916 SWAMP DONKEY, SWAMP

PO BOX 2394 STN MAIN, PO BOX 2394

STN MAIN

Dawson Creek, British Columbia

V1G4T9, Canada

HICLE YEAR: 2012 AKE:

LAZER TANK

ODOMETER: **HUB ODOMETER:**

BRAKE TYPE:

FUEL TYPE:

Not Applicable

ehicle Identification (VIN)

ection 1 - Power Train ection 2 - Suspension

ection 3 - Brake System ection 3A - Air Brakes

ection 3H - Hydraulic Brakes ection 4 - Steering

ection 5 - Instruments and Auxiliary

quipment

ection 6 - Lamps ection 7 - Electrical System ection 8 - Frame and Body

ection 9A - Tires ection 9B - Wheels ection 10 - Coupling Devices

ection 11 - Other Vehicle Components

Passed Passed

Passed Not Applicable

Passed

Passed

Passed

Not Applicable

Passed Passed Passed

Passed Passed Passed

Not Applicable

· Brake Chamber Type, Size and Push Rod Stroke (mm)

Tire Tread Depth (mm) Size Outer R Axles Type Slack Adj. Left Right Outer L Inner L Inner R Clamp 30 Automatic 25 25 10 10 10 1 10 12 2 Clamp 30 **Automatic** 32 32 12 12 12 3 Clamp 30 Automatic 34 34 12 12 12 12 30 Automatic 32 35 10 10 10 10 Clamp

Comment:

omment:



Commercial Vehicle Inspection Report

Decal Number: Decal Expiry Date:

Inspection Number:

GK54445 2026-Feb-28 21471507 Inspection Result:

PASS

Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	60	55	Lining (Shoe)	15	15	Drum		
2	45	50	Lining (Shoe)	16	16	Drum		
3	60	70	Lining (Shoe)	14	14	Drum		
4	65	55	Lining (Shoe)	14	14	Drum		
mment:	Commont.					Comment: Air Brake Camshaft Rotation performed. Rot Thickness or Drum Diameter not measured.		

spection Comments:

Is this Vehicle been road tested? No Road Test Date: Road Tester:

Spector: BOLIVAR, MICHAEL BRANDON Signature: ______

s Inspection Report was submitted to CVSE on 2025-Aug-24 02:34 PM PDT

s inspection's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.