

Commercial Vehicle Inspection Report

Decal Number: Decal Expiry Date: Inspection Number:

VIN:

ADDRESS:

GK54468 2026-Feb-28 21471604

Inspection Result:

PASS

CILITY:

TWISTED METAL MECHANICS LTD. INSP. TYPE:

REGI:

INSP. CLASS:

Complete Class 3 - Trailer and Semi-Trailer

INSP. START:

OWNER/LESSEE NAME:

INSP. COMPLETE:

2025-Aug-24 10:12 AM PDT 2025-Aug-24 02:12 PM PDT

Steering

SPECTOR:

ORK ORDER #

HICLE JUR:

ATE #:

BOLIVAR MICHAEL BRANDON /

202902

British Columbia

26

INSP REASON:

Semi-annual

11865261

Dump Trailer

411

2MFB2S3D1GR008471

SWAMP DONKEY, SWAMP

PO BOX 2394 STN MAIN, PO BOX 2394

STN MAIN

Dawson Creek, British Columbia

HICLE YEAR:

2016

MIDLAND

20561U

ODOMETER:

UNIT/FLEET#:

BODY STYLE:

HUB ODOMETER: BRAKE TYPE:

FUEL TYPE:

Air

V1G4T9, Canada

AKE: DDEL:

shicle Identification (VIN)

CENCED GVW(kg): 999999

ection 1 - Power Train ection 2 - Suspension

ection 3 - Brake System

ection 3A - Air Brakes ection 3H - Hydraulic Brakes

ection 4 - Steering

ection 5 - Instruments and Auxiliary quipment

ection 6 - Lamps

ection 7 - Electrical System ection 8 - Frame and Body ection 9A - Tires

ection 9B - Wheels

ection 10 - Coupling Devices ection 11 - Other Vehicle Components Passed

Not Applicable

Passed

Passed Passed

Not Applicable

Passed

Passed

Passed

Passed Passed

Passed Passed

Passed Passed

•	Brake	Chamber	Type, S	ize and Pu	sh Rod Stroke	(mm)
	Ayles	T	ivne	Sizo	Slack Ar	li .

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R
1	Clamp	30	Automatic	34	34	7	7	7	7
2	Clamp	30	Automatic	30	34	7	7	7	7
3	Clamp	30	Automatic	32	32	9	10	8	10
omment:						Comment:			

· Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right	
1	90	75	Lining (Shoe)	12	14	Drum			
2	85	90	Lining (Shoe)	12	10	Drum			
3	85	70	Lining (Shoe)	12	12	Drum			
omment:	nent: Comment:					Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.			

spection Comments:

spector:

s this Vehicle been road tested?

No BOLIVAR, MICHAEL BRANDON Signature:

Road Tester:

Tire Tread Depth (mm)

s Inspection Report was submitted to CVSE on 2025-Aug-24 06:12 PM PDT

3 Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

TICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection Tor generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this rmation, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

4/2025 6:12:27 PM PDT