



Commercial Vehicle
Inspection Report

Decal Number: GK54448
Decal Expiry Date: 2026-Feb-28
Inspection Number: 21471534

L03-28

Inspection Result:
PASS

CILITY:	TWISTED METAL MECHANICS LTD. / S20269	INSP. TYPE:	Complete	INSP. START:	2025-Aug-24 12:18 PM PDT
SPECTOR:	BOLIVAR, MICHAEL BRANDON / 202902	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2025-Aug-24 02:18 PM PDT
ORK ORDER #:	5	INSP. REASON:	Semi-annual		
EHICLE JUR:	British Columbia	REGI:	14322005	VIN:	1XPTP4EX5RD898069
ATE #:	VC6515	UNIT/FLEET#:	146	OWNER/LESSEE NAME:	SWAMP DONKEY, SWAMP
ENCED GVW(kg):	54500	BODY STYLE:	Truck Tractor	ADDRESS:	PO BOX 2394 STN MAIN, PO BOX 2394 STN MAIN
EHICLE YEAR:	2024	ODOMETER:	188000 KM		Dawson Creek, British Columbia
AKE:	PETERBILT	HUB ODOMETER:			V1G4T9, Canada
ODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

ehicle Identification (VIN)	Passed
ection 1 - Power Train	Passed
ection 2 - Suspension	Passed
ection 3 - Brake System	Passed
ection 3A - Air Brakes	Passed
ection 3H - Hydraulic Brakes	Not Applicable
ection 4 - Steering	Passed
ection 5 - Instruments and Auxiliary quipment	Passed
ection 6 - Lamps	Passed
ection 7 - Electrical System	Passed
ection 8 - Frame and Body	Passed
ection 9A - Tires	Passed
ection 9B - Wheels	Passed
ection 10 - Coupling Devices	Passed
ection 11 - Other Vehicle Components	Passed

Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	25	25	12			12	✓
2	Clamp	30	Automatic	34	35	10	10	10	10	
3	Clamp	30	Automatic	35	35	10	10	10	10	
4	Clamp	30	Automatic	32	32	10	10	10	10	
omment:	Comment:									



Commercial Vehicle
Inspection Report

Decal Number: GK54448
Decal Expiry Date: 2026-Feb-28
Inspection Number: 21471534

Inspection Result:
PASS

Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	30	30	Lining (Shoe)	19	19	Drum		
2	45	45	Lining (Shoe)	19	19	Drum		
3	45	45	Lining (Shoe)	19	19	Drum		
4	55	50	Lining (Shoe)	19	19	Drum		
omment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:
Is this Vehicle been road tested? No
Inspector: BOLIVAR, MICHAEL BRANDON
Road Test Date: 
Signature:  Road Tester:

This Inspection Report was submitted to CVSE on 2025-Aug-24 03:18 PMPDT
Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.