



Commercial Vehicle
Inspection Report

Decal Number: GK54467
Decal Expiry Date: 2026-Feb-28
Inspection Number: 21471602

LO3-29
Inspection Result:
PASS

CILITY: TWISTED METAL MECHANICS LTD. / S20269
SPECTOR: BOLIVAR, MICHAEL BRANDON / 202902
ORK ORDER #: 25
INSPECTION TYPE: Complete
INSPECTION CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSPECTION REASON: Semi-annual
INSPECTION START: 2025-Aug-24 02:02 PM PDT
INSPECTION COMPLETE: 2025-Aug-24 05:02 PM PDT

VEHICLE JUR: British Columbia
ATE #: SE7718
PERMITTED GVW(kg): 54500
VEHICLE YEAR: 2023
MAKE: PETERBILT
MODEL:
REGI: 13985360
UNIT/FLEET#: 143
BODY STYLE: Truck Tractor
VIN: 1XPTP4EX4PD808360
OWNER/LESSEE NAME: SWAMP DONKEY, SWAMP
ADDRESS: PO BOX 2394 STN MAIN, PO BOX 2394 STN MAIN
Dawson Creek, British Columbia
V1G4T9, Canada
ODOMETER: 262000 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	25	25	12			12	✓
2	Clamp	30	Automatic	32	32	10	10	10	10	
3	Clamp	30	Automatic	34	32	10	10	10	10	
4	Clamp	30	Automatic	32	31	8	8	8	8	
Comment:						Comment:				



Commercial Vehicle Inspection Report

Decal Number: GK54467
Decal Expiry Date: 2026-Feb-28
Inspection Number: 21471602

Inspection Result:
PASS

Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	35	35	Lining (Shoe)	19	19	Drum		
2	45	45	Lining (Shoe)	18	18	Drum		
3	50	52	Lining (Shoe)	18	18	Drum		
4	55	55	Lining (Shoe)	18	18	Drum		
omment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:
Is this Vehicle been road tested? No
Inspector: BOLIVAR, MICHAEL BRANDON
Road Test Date:  Road Tester:
Signature:

This Inspection Report was submitted to CVSE on 2025-Aug-24 06:03 PM PDT
Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.