

## Commercial Vehicle **Inspection Report**

Decal Number: **Decal Expiry Date:** Inspection Number: GK54458 2026-Feb-28 21471573

Inspection Result: PASS

TWISTED METAL MECHANICS LTD. INSP. TYPE: CILITY:

/ S20269

BOLIVAR, MICHAEL BRANDON /

202902

INSP. REASON:

INSP. CLASS:

Complete

Class 2 - Heavy Vehicle with LGVW

5501 kg or more

INSP. START: INSP. COMPLETE: 2025-Aug-24 12:45 PM PDT 2025-Aug-24 02:45 PM PDT

**DRK ORDER #:** 

British Columbia

SE7719

CENCED GVW(kg): 54500

REGI:

13985401 144

Air

Truck Tractor

Semi-annual

VIN:

OWNER/LESSEE NAME:

ADDRESS:

1XPTP4EX6PD808361

SWAMP DONKEY, SWAMP PO BOX 2394 STN MAIN, PO BOX 2394

STN MAIN

Dawson Creek, British Columbia

V1G4T9, Canada

:HICLE YEAR:

:HICLE JUR:

ATE #:

AKE:

ODEL:

SPECTOR:

2023 PETERBILT

ODOMETER: HUB ODOMETER: 302000 KM

BRAKE TYPE:

**FUEL TYPE:** 

UNIT/FLEET#:

BODY STYLE:

ehicle Identification (VIN) ection 1 - Power Train ection 2 - Suspension ection 3 - Brake System

ection 3A - Air Brakes ection 3H - Hydraulic Brakes

ection 4 - Steering

ection 5 - Instruments and Auxiliary auipment

ection 6 - Lamps ection 7 - Electrical System ection 8 - Frame and Body

ection 9A - Tires ection 9B - Wheels

Axles

2

3

4

omment:

ection 10 - Coupling Devices ection 11 - Other Vehicle Components

Type

Clamp

Clamp

Clamp

Clamp

Passed

Passed Passed Passed

Passed Not Applicable

Passed

Passed

Passed Passed Passed

Passed Passed Passed

Passed

Automatic

Automatic

Automatic

· Brake Chamber Type, Size and Push Rod Stroke (mm) Size

24

30

30

30

Slack Adj. Left Right Automatic

25 25 34 34 35 35 32

32

14 14 14 14

14

14

14

Tire Tread Depth (mm) Outer L Inner L

Outer R Inner R 14 14 14 14 14 14 14

Steering

Comment:



## **Commercial Vehicle** Inspection Report

Decal Number: **Decal Expiry Date:** Inspection Number:

GK54458 2026-Feb-28 21471573

Inspection Result:

· Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	25	25	Lining (Shoe)	19	19	Drum		
2	45	45	Lining (Shoe)	19	19	Drum		
3	50	55	Lining (Shoe)	19	19	Drum		
4	55	50	Lining (Shoe)	19	19	Drum		
omment: Comment:					Comment: Air Brake Camshaft Rotation performed. Rot Thickness or Drum Diameter not measured.			

spection Comments:

s this Vehicle been road tested? spector:

No BOLIVAR, MICHAEL BRANDON Road Test Date: Signature:

s Inspection Report was submitted to CVSE on 2025-Aug-24 04:45 PM PDT

<sup>3</sup> Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.