

## Commercial Vehicle Inspection Report

Decal Number: **Decal Expiry Date:** Inspection Number:

GK54462 2026-Feb-28 21471586

Inspection Result:

Steering

CILITY: SPECTOR:

ATE #:

TWISTED METAL MECHANICS LTD. INSP. TYPE:

/ S20269

BOLIVAR, MICHAEL BRANDON /

202902

INSP. CLASS: INSP. REASON: Complete

Semi-annual

13470220

139

5501 kg or more

INSP. START: INSP. COMPLETE: 2025-Aug-24 12:19 PM PDT

2025-Aug-24 02:19 PM PDT

**DRK ORDER #:** HICLE JUR:

HICLE YEAR:

20

British Columbia

PS6011

CENCED GVW(kg): 63500

2020 **PETERBILT**  UNIT/FLEET#: BODY STYLE:

REGI:

ODOMETER: 423000 KM

HUB ODOMETER: **BRAKE TYPE:** Air

Truck Tractor

Class 2 - Heavy Vehicle with LGVW

VIN:

1XPTP4EX2LD659506 OWNER/LESSEE NAME:

ADDRESS:

SWAMP DONKEY, SWAMP PO BOX 2394 STN MAIN, PO BOX 2394

STN MAIN

Dawson Creek, British Columbia

V1G4T9, Canada

DDEL:

omment:

AKE:

shicle Identification (VIN)

ection 1 - Power Train ection 2 - Suspension ection 3 - Brake System ection 3A - Air Brakes

ection 3H - Hydraulic Brakes ection 4 - Steering

ection 5 - Instruments and Auxiliary

quipment ection 6 - Lamps

ection 7 - Electrical System ection 8 - Frame and Body ection 9A - Tires

ection 9B - Wheels ection 10 - Coupling Devices ection 11 - Other Vehicle Components

**FUEL TYPE:** Passed

Passed Passed Passed Passed Not Applicable Passed

Passed

Passed Passed Passed Passed Passed Passed Passed

Left

25

31

32

32

Right

25

31

32

32

Brake Chamber Type, Size and Push Rod Stroke (mm) Axles Size Slack Adj. Type

Clamp 24 Automatic 2 Clamp 30 Automatic 3 Clamp 30 Automatic 4 Clamp 30 Automatic

Tire Tread Depth (mm)

Comment:

Outer L Inner L Outer R Inner R 10 10 12 12 12 12 10 10 10 10 8 8 8 8

TICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.



## **Commercial Vehicle** Inspection Report

Decal Number: **Decal Expiry Date:** Inspection Number:

GK54462 2026-Feb-28 21471586

Inspection Result:

Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	45	45	Lining (Shoe)	18	18	Drum		
2	65	65	Lining (Shoe)	15	15	Drum		
3	70	65	Lining (Shoe)	15	15	Drum		
4	72	65	Lining (Shoe)	15	15	Drum		
nment: Comment:						Comment: Air Brake Camshaft Rotation performed. Ro Thickness or Drum Diameter not measured.		

spection Comments:

spector:

s this Vehicle been road tested?

No BOLIVAR, MICHAEL BRANDON Road Test Date:

Signature:

s Inspection Report was submitted to CVSE on 2025-Aug-24 05:20 PM PDT

<sup>3</sup> Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.