

Commercial Vehicle Inspection Report

Decal Number: Decal Expiry Date: Inspection Number:

GK54452 2026-Feb-28 21471549

CILITY:

TWISTED METAL MECHANICS LTD. INSP. TYPE:

/ S20269

BOLIVAR, MICHAEL BRANDON /

202902

INSP CLASS INSP. REASON: Complete

5501 kg or more

Semi-annual

INSP. START: Class 2 - Heavy Vehicle with LGVW

INSP. COMPLETE:

2025-Aug-24 11:52 AM PDT 2025-Aug-24 02:52 PM PDT

SPECTOR: ORK ORDER #:

HICLE JUR:

ATE #:

AKE:

ODEL:

10

British Columbia

RF2143

CENCED GVW(kg): 54500

REGI: UNIT/FLEET#: BODY STYLE: 13708298 141

Truck Tractor

291000 KM

VIN: OWNER/LESSEE NAME:

1XPTP4TX4MD762124 SWAMP DONKEY, SWAMP

ADDRESS:

PO BOX 2394 STN MAIN, PO BOX 2394

Steering

STN MAIN

Dawson Creek, British Columbia

V1G4T9, Canada

HICLE YEAR:

2021 PETERBILT

ODOMETER: **HUB ODOMETER:**

BRAKE TYPE:

Air

FUEL TYPE:

shicle Identification (VIN) ection 1 - Power Train

ection 2 - Suspension ection 3 - Brake System

ection 3A - Air Brakes ection 3H - Hydraulic Brakes

ection 4 - Steering ection 5 - Instruments and Auxiliary

quipment

ection 6 - Lamps ection 7 - Electrical System

ection 8 - Frame and Body ection 9A - Tires ection 9B - Wheels ection 10 - Coupling Devices

ection 11 - Other Vehicle Components

Passed

Passed

Passed Passed Passed Not Applicable

Passed

Passed

Passed Passed

Passed Passed

Passed

Not Applicable

· Brake Chamber Type, Size and Push Rod Stroke (mm)

Tire Tread Depth (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R
1	Clamp	24	Automatic	25	25	12			12
2	Clamp	30	Automatic	35	32	14	14	14	14
3	Clamp	30	Automatic	32	32	14	14	14	14
4	Clamp	30	Automatic	32	32	14	14	14	14
omment:						Comment:			

TICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.



Commercial Vehicle COLUMBIA Inspection Report

Decal Number: **Decal Expiry Date:** Inspection Number:

GK54452 2026-Feb-28 21471549

Inspection Result:

· Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right	
1	40	40	Lining (Shoe)	19	19	Drum			
2	55	55	Lining (Shoe)	17	17	Drum			
3	62	65	Lining (Shoe)	16	18	Drum			
4	60	60	Lining (Shoe)	17	17	Drum			
omment:	Comment:					Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.			

spection Comments:

spector:

s this Vehicle been road tested?

No BOLIVAR, MICHAEL BRANDON Road Test Date:

Signature:

Road Tester:

s Inspection Report was submitted to CVSE on 2025-Aug-24 03:53 PM PDT

³ Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.